

ASS. REC. BY:

REF: CS/FCI18018715/

Uqdz/n²

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Lurene juw

of

FCI

Date/Time:

17/10/18 @ 3:52pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

GBF 1396 X

Insured:

SHC0987S

at Workshop m/s

Tan Jim Motor

Tel:

GESS 5151

of

51 Defu Lane 10

Policy No.:

Claim No.:

218007545MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/10/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

4:10pm @ 17/10/18

Person Contacted:

Jim

Vehicle IN / OUT

☒

Date/Time	Action/Instruction (✓) Estimate
	GBF 1396 X - X
	SHC0987S - X
16/10/18 @ 1:21pm	revised to Lurene by email

SIN 1100

REF: FCI

ASSIGNMENT

From: Date: 25/10/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspection Vehicle No: GBF 1396X
at Workshop m/s Tan Lim Motor
of 51 Defu Lane 10

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

2pm - 4pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up) 5828E
Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBF 1396X Yr Regn: 7, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota Aygo c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 114936 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDY 23 / 8024314

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/10/18

Survey held at

Rear

R/Bal. 6/6 mm

L/Bal. 6/6 mm

D.O.I. 25/10/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/10/18 confirmed final for 500 with w.l.h.e.s. (Red \$ 1410.78, 74%)

RECEIVED 26 OCT 2018

Date/Time, File Pass to?

1) 26/10/18

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 500

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS. St

) Photos

) Others

TOTAL

100

50

20

170



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007545MFSH

Date: 26 October 2018

Our Ref: CS/FCI18018715/Uqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBF 1396X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/10/2018 at the premises of M/s TAN LIM MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 1,910.78 .
Revised Estimate Amount	: S\$ 500.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s body.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	17-10-2018	Our Ref No. D18007545MFSH
Accident Date	16-10-2018	Claim Type. Third Party
Insured Vehicle	SHC0987S	Third Party Vehicle. GBF1396X
Survey Location	51 DEFU LANE 10	
Contact Person.	LAM WEI SHONG WILLIAM	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 26 October 2018 1:21 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007545MFSH/1
Attachments: CSFCI18018715Uqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of GBF 1396X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Wednesday, 17 October 2018 4:12 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007545MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 17 October 2018 3:52 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18007545MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5828E
Vehicle Details	
Vehicle No.:	GBF1396X
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 M
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2604612
Chassis No.:	KDY2318024314
Maximum Power Output:	-
Open Market Value:	\$33,905.00
Original Registration Date:	12 Jul 2016
First Registration Date:	12 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$1,696.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$33,143.00
Total Rebate Amount:	\$33,143.00

The information contained herein is correct as at 26 Oct 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SHC987S
Date of Accident : 16 October 2018

Messrs Joyway Pte Ltd

Date : 17 October 2018

Estimate To Repair GBF1396X - Toyota DYNA 3.0 M
Chassis No : KDY2318024314

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	side gate lid step panel	\$ 121.75
02	1 pc	side gate lid step panel stopper left	\$ 25.95
			\$ 147.70
		Less 25 %	\$ 36.92
			\$ 110.78
		<u>SPECIAL NETT ITEMS</u>	
03	1 pc	side sliding door aluminium sheet left	\$ 550.00
04	1 pc	side sliding door aluminium sheet corporate name and telephone number	\$ 350.00
			\$ 900.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same and repair comply hook and railing side.	\$ 500.00
02		Putty and spray painting of the affected portion.	\$ 400.00
			\$ 900.00
		Total	\$ 1,910.78

Not Authorized
date

Take photo After Repair

2 days

25/10/18

plz \$ 500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118018715/Uqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 987S	Veh. Inspected	GBF 1396X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007545MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	17/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDY2318024314	Colour	SILVER	
Odometer	114936	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	145 R13	BRIDGESTONE	6 mm	
L/H Front Tyre	145 R13	BRIDGESTONE	6 mm	
R/H Rear Tyre	145 R13 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	145 R13 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/10/2018	Inspection Date	25/10/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 1396X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE GATE LID STEP PANEL	TO REPAIR SEE LABOUR	121.75	-
1	SIDE GATE LID STEP PANEL STOPPER LEFT	NOT NECESSARY	25.95	-
	LESS 25% DISCOUNT		-36.92	-
			110.78	-
	SPECIAL NETT ITEMS			
1	SIDE SLIDING DOOR ALUMINIUM SHEET LEFT (SN)	NOT NECESSARY	550.00	-
1	SIDE SLIDING DOOR ALUMINIUM SHEET CORPORATE NAME AND TELEPHONE NUMBER (SN)	NOT NECESSARY	350.00	-
			900.00	-
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME AND REPAIR COMPLY HOOK AND RAILING SIDE INCLUSIVE OF THE REPAIR OF SIDE GATE LID STEP PANEL.		500.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		400.00	300.00
			900.00	500.00
	GRAND TOTAL		1,910.78	500.00
	RECOMMENDED COST OF REPAIRS			500.00

Report Ref No. CS/FCI18018715/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.