

22/03/2002

ASS. REC. BY:

REF: CS/SPF18018719/Tirb22 Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person): Frankie May of SPF Date/Time: 16/02/08

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 8254E Insured: QX 782Z

at Workshop m/s MDVU Tel: 62723892

of Bk 1008 Bukit Merak, Lane 3 #01-04

Policy No: Claim No: REMD / 105 / 009 / 2018 / 117

Sum Insured: Excess:

Make of Veh: D.O.A. 20092008
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time: 16/02/08 1029am Person Contacted: Nabilah Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 8254E - X
	QX 782Z - CS/SPF18018719/GN3 DCA 20092008
	Submit \$ 3200.00 @ 5 days
	Red: \$ 2269.25, 41%.

14/11/18 Case re-open to inpt repair range Celye refulie.

\$3800 - \$4000.

56 days.

1st B02 11/11/18, re-open not only 20/11/18

Surveyor

Tanph

REF:

SPF

ASSIGNMENT

CoE 2023 Sep

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%


3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT



Veh No

SLP8254E

Yr Regn:

2008 Sep

Type: ☒ M/Cap / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Isis

C.C.

1747

Colour

white

A/C: Insured / Std / NI / NA

Sp Reading

169041

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ENM10056834

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Apollo

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/15 P1715

Survey held at

Mo...

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 23 OCT 2018

Date/Time: File Pass to?



: Preli. Report

1) *typist*



: Final Report

Date/Time: File Return to?

2)

Report Format :

TP - SPF

Lump Sum / I.E.T. (\$

3200

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

280

280

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/10/2018

SPF ACCIDENT CLAIM SECTION

No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Attention :- XA066

Page # :- 1

Veh # :- SLP8254E

Veh Model :- TOYOTA ISIS 1.8LX A

Estimate# :- CK418102

Claim # :-

ACC. Date :- 20/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR WINDSCREEN MOULDING	1 PC	78.00	78.00
2.	REAR BOOT	1 PC	1,635.00	1,635.00
3.	REAR BOOT EMBLEM	1 PC	98.00	98.00
4.	REAR BUMPER	1 PC	1,200.00	1,200.00
5.	REAR TAIL LAMP LOWER BRACKET L & R	2 PCS	90.00	180.00
6.	REAR BUMPER TOW COVER	1 PC	60.00	60.00
7.	REAR BUMPER CLIPS	10 PCS	4.80	48.00
8.	REAR END PANEL OUTER	1 PC	720.00	720.00
	LIST TOTAL S\$			4,019.00
	25% DISCOUNT S\$			-1,004.75
				3,014.25
SPECIAL NET ITEMS :				
1.	REAR PARKING SENSOR L & R	1 SET	250.00	250.00
2.	WINDSCREEN SEALANT	1 PC	45.00	45.00
	SPECIAL NET TOTAL S\$			295.00
LABOUR :				
	TO REPAIR REAR FLOOR PANEL, REAR END PANEL INNER. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS		600	800.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS		600	800.00
	TO REMOVE & REFIX REAR WINDSCREEN		✓	100.00
	TO REMOVE & REFIX REAR BOOT MECHANISM AND OTHERS ATTACHMENT PARTS		150	100.00
	TO REMOVE REAR SIDE TRIM BOARD L & R, SPARE TYRE HOUSE AND OTHER ATTACHMENT PARTS		160	120.00
	TO INSPECT REAR TAIL LAMP WATER LEAKAGE		nn + x	40.00
	TO REMOVE & REFIX REAR PARKING SENSORS & CHECK WIRING		30	80.00
	TO RUST PROOF ACCIDENT AFFECTED AREAS		30	60.00
	TO APPLY SEAL ON WELDING JOINT & NEW PARTS		nn + x	60.00
	LABOUR TOTAL S\$			2,160.00

Main Office:
 Mova Building
 No. 22, Jaiian Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

09/10/2018

SPF ACCIDENT CLAIM SECTION
No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Attention :- XA066

Page # :- 1 132867

Veh # :- SLP8254E

Veh Model :- TOYOTA ISIS 1.8LX A

Estimate# :- CK418102

Claim # :-

ACC. Date :- 20/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,469.25

GST @ 7 % 382.85


AMOUNT DUE S\$ 5,852.10

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 974 95749
 'wp'
 16/10/18 @ 17:15
 Resurvey after repair
 5 days
 sur @ lkkauto.com

 22/10/18

Main Office:
 Move Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6478 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

09/10/2018

SPF ACCIDENT CLAIM SECTION
 No. 1 Mount Pleasant Rd
 Bk 8 Old Police Academy
 Singapore 298333.

Attention :- XA066

Page # :- 1

Veh # :- SLP8254E

Veh Model :- TOYOTA ISIS 1.8LX A

Estimate# :- CK418102

Claim # :-

ACC. Date :- 20/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR WINDSCREEN MOULDING	1 PC	78.00	78.00
2.	REAR BOOT	1 PC	1,635.00	1,635.00
3.	REAR BOOT EMBLEM	1 PC	98.00	98.00
4.	REAR BUMPER	1 PC	1,200.00	1,200.00
5.	REAR TAIL LAMP LOWER BRACKET L & R	2 PCS	90.00	180.00
6.	REAR BUMPER TOW COVER	1 PC	60.00	60.00
7.	REAR BUMPER CLIPS	10 PCS	4.80	48.00
8.	REAR END PANEL OUTER - Repair	1 PC	720.00	720.00
LIST TOTAL S\$				4,019.00
25% DISCOUNT S\$				-1,004.75
				3,014.25
SPECIAL NET ITEMS :				
1.	REAR PARKING SENSOR L & R	1 SET	250.00	250.00
2.	WINDSCREEN SEALANT	1 PC	45.00	45.00
SPECIAL NET TOTAL S\$				295.00
LABOUR :				
TO REPAIR REAR FLOOR PANEL, REAR END PANEL INNER, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS				600 800.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				600 800.00
TO REMOVE & REFIX REAR WINDSCREEN				100.00
TO REMOVE & REFIX REAR BOOT MECHANISM AND OTHERS ATTACHMENT PARTS				50 100.00
TO REMOVE REAR SIDE TRIM BOARD L & R, SPARE TYRE HOUSE AND OTHER ATTACHMENT PARTS				60 120.00
TO INSPECT REAR TAIL LAMP WATER LEAKAGE				40.00
TO REMOVE & REFIX REAR PARKING SENSORS & CHECK WIRING				30 80.00
TO RUST PROOF ACCIDENT AFFECTED AREAS				30 60.00
TO APPLY SEAL ON WELDING JOINT & NEW PARTS				60.00
LABOUR TOTAL S\$				2,160.00

Part \$ 3119 - 25%

\$ 2339.25

SN item \$ 245

Labour \$ 1470

total \$ 3200 1/5 5.0445

11

Estimate

09/10/2018

SPF ACCIDENT CLAIM SECTION
 No. 1 Mount Pleasant Rd
 Blk 8 Old Police Academy
 Singapore 298333.

Attention :- XA066

Page # :- 1 132867

Veh # :- SLP8254E

Veh Model :- TOYOTA ISIS 1.8LX A

Estimate# :- CK418102

Claim # :-

ACC. Date :- 20/09/18

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0068864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,469.25

GST @ 7 % 382.85

AMOUNT DUE S\$ 5,852.10

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Tanpin 97495749
 WP
 16/10/18 @ 17:15
 Resung after repair
 5 days
 suv@lucendo.com

Janice Lee (LKKAUTO)

From: Tan Yoong Wei <tanyw@moval.com.sg>
Sent: Monday, October 22, 2018 5:15 PM
To: Taufikh (LKKAUTO)
Cc: SUR; Veron Chen (LKKAUTO)
Subject: FINALISE SLP8254E
Attachments: 20181020_114430.jpg; 20181020_114435.jpg; 20181020_114441.jpg;
22102018165150.pdf

Hi taufikh,
Please advice whether we can finalise cost of repair lumpsum \$3200 with 5 working days ?
Thank you.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTOMOTIVE ENGINEERING & MGT DIVISION
ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY
SINGAPORE 298333
ATTN : FRANKIE THAY

INV No. AC1811133
INV Date 29/10/2018
Reference CS/SPF18018719/T1rbe2
Code SPF



PROFESSIONAL SERVICE FEE

Vehicle No. SLP 8254E
Insured Veh. QX 782Z
Claim No. AEMD/105/009/2018/117
Policy No.
Accident Date 20/09/2018
Inspection Date 16/10/2018

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (7%)	19.60
Grand Total	299.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

hard copy on hold (2/11)
-pending olivia clarify with Bryan
for repair cost range



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 8254E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NECESSARY	78.00	78.00
1	REAR BOOT	BENT	1,635.00	1,635.00
1	REAR BOOT EMBLEM	NECESSARY	98.00	98.00
1	REAR BUMPER	DEFORMED	1,200.00	1,200.00
2	REAR TAIL LAMP LOWER BRACKET L & R @\$90.00	NOT NECESSARY	180.00	-
1	REAR BUMPER TOW COVER	DEFORMED	60.00	60.00
10	REAR BUMPER CLIPS @\$4.80	NECESSARY	48.00	48.00
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	720.00	-
	LESS 25% DISCOUNT		-1,004.75	-779.75
			3,014.25	2,339.25
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR PARKING SENSOR L & R (SN)	NOT WORKING	250.00	200.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	45.00	45.00
			295.00	245.00
<u>LABOUR</u>				
	TO REPAIR REAR FLOOR PANEL, REAR END PANEL INNER. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER.		800.00	600.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.		800.00	600.00
	TO REMOVE & REFIX REAR WINDSCREEN.		100.00	100.00
	TO REMOVE & REFIX REAR BOOT MECHANISM AND OTHERS ATTACHMENT PARTS.		100.00	50.00
	TO REMOVE REAR SIDE TRIM BOARD L & R, SPARE TYRE HOUSE AND OTHER ATTACHMENT PARTS.		120.00	60.00
	TO INSPECT REAR TAIL LAMP WATER LEAKAGE.	NOT NECESSARY	40.00	-
	TO REMOVE & REFIX REAR PARKING SENSORS & CHECK WIRING.		80.00	30.00
	TO RUST PROOF ACCIDENT AFFECTED AREAS.		60.00	30.00
	TO APPLY SEAL ON WELDING JOINT & NEW PARTS.	NOT NECESSARY	60.00	-
			2,160.00	1,470.00

Report Ref No. CS/SPF18018719/T1rbe2



GRAND TOTAL		5,469.25	4,054.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/SPF18018719/T1rbe2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,200.00-4,000.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.