

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBA5090C180221

Estimate**Customer**Name: AIG Asia Pacific Insurance Pte LtdAddress Motor Claims Department78 Shenton Way #07-16AIG BuildingSingapore 079120

Date:

Vehicle No: GBA5090CModel/Make: Toyota HiaceManual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front bumper <i>696.40</i>	\$ 796.80	
2	Bumper Bracket <i>nls</i>	\$ 137.26	
3	Bumper Clips 1 set	\$ 50.00	
4	Bumper Grille	\$ 155.80	
5	Bumper Wire Bracket	\$ 104.50	
6	Grille <i>545.10</i>	\$ 688.20	
7	Grille Clips 1 set	\$ 30.00	SN X
8	HeadLamp <i>766.01</i>	\$ 930.70	+
9	HeadLamp Clip 1 set	\$ 65.00	SN X
10	Step Garnish	\$ 225.70	+
11	Step Garnish Clips 1 set	\$ 30.00	SN X
12	Radiator <i>1618.30</i> <i>(25%)</i>	\$ 2,372.30	+
13	Radiator Tank Cowling	\$ 352.50	X
14	Radiator Coolant	\$ 45.00	SN X
15	Door "LTA" Corporate Detail Sticker	\$ 48.00	SN <i>405.2</i>
	To check all wiring & electrical component for proper function	\$ 80.00	- <i>20</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	- <i>300</i>
	To putty & spray painting & including touch up paint on accident affected	\$ 600.00	- <i>380</i>
	To remove & replace radiator & conduct pressure test and bleed system	\$ 100.00	- <i>40</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 7,611.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
2/5 @ 3000
3 day.

4038.71
3029.03