



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms GOH SUE LYNN, FIONA  Blk 607 Senja Road #10-06 Singapore 670607  Contact No Mobile: 97827763	Cust No/Name	/Ms Goh Sue Lynn, Fiona
	Reg No/Reg Date	SKP7758L / 09/10/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MF5332094
	Engine No	G4FGEH741550
	Make/Model	KIA/15MY F K3 1.6 A EX
	Colour/Trim	MST / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	15/10/2018/ 09:48	QUE	261 / Edwin Caina	37226		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550 2200.00
RENEW & RE-ALIGN RR DAMAGED PORTION AREAS:							
RENEW RR BUMPER							
REPAIR RR FENDER LH & RR END PNL							420 1400.00
E PNT98000							
RESPRAY RR BUMPER , RR END PNL & RR FENDER LH							120 275.00
E PNT88000							
REMOVE & REFIT RR FLR BOARD,TRIM & CARPET							30 50.00
A 54900099							
CHECK WIRING & ELECTRICAL SYSTEM							200.00
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							X 80.00
M SUNDRY							
APPLY ANTI CORROSION ON AFFECTED AREAS							80 100.00
E PNT88000							
TO RENEW REVERSE SENSOR							? 220.00
M SUNDRY							
TO SUPPLY REVERSE SENSOR							20 50.00
M SUNDRY							
Sundries							
M COVER-RR BUMPER				1.00	768.00	00.00	can 768.00
M COVER-RR BUMPER,UPR				1.00	234.00	00.00	de 234.00
M COVER-RR BPR UNDER				1.00	42.00	00.00	? 42.00
M BEAM-RR BUMPER				1.00	365.00	00.00	? 365.00
M STAY-RR BUMPER LH				1.00	75.00	00.00	? 75.00
M STAY-RR BUMPER RH				1.00	75.00	00.00	X 75.00
M BRACKET-RR BUMPER SIDE MTG,LH				1.00	33.00	00.00	new 33.00
M LAMP ASSY-REAR COMBINATION,LH				1.00	302.00	00.00	? 302.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tayfun 97455464SURVEYOR SIGNATURE: Tayfun

Confirm &amp; accepted by

DATE: 24/10/18 @ 4:33pm.REMARKS: Resurvey before paint02 days service maintenance
 Nett  
6469.00

 6,469.00  
452.83

Total Payable

6,921.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.