COMFORTDELGRO ENGINEERING PTE LTD

· REPAIR ESTIMATE*

VEHICLE NO: SHC 8568R

DATE 12/10/2018 16:48

Qty Qty	Front Bumper Cover Front Bumper Bracket Top (LH)	Туре	Unit Price	S 1052.2	
Qty	Front Bumper Cover			8 1052.2	0
	IF TOIL DUMPEL DIACKET TOP			\$ 22.	
	Front Bumper Bracket (LH)			\$ 24.	- 1
	Headlamp (LH)			\$ 1,388.	00
				\$ 1,979.	50
	SUB TOTAL LESS 20%			\$ 395.	- 1
	DISCOUNTED TOTAL			\$ 1,583	.60
	DISCOUNTED TOTAL				
		4			
	Labour Charge			2	00
	Panel Beating			\$ 226	0.00
	Spray Painting Charge			_	9.00
	Wiring			\$ 30	200
				\$ 47	0.00
	TOTAL LABOUR	2		3 47	0.00
	ESTIMATE TOTAL	L		\$ 2,05	3.60
	1(a/uz ((16/4)				
	15/10/18 1110k	* _KK Auto C the Repaire • To resurvey • To display d • Parts prices	nsultants hence notify rof the following: efore/after spray painting maged part(s) during resurve are subject to confirmation	y	
	He Ryst phlo	 Third party No illegal m Supplement is subject to 	odification(s) is allowed tary item(s) must be resurveyed inal approval from Insurance	bnshe	
		Signature: Date:	d by Repairer		
			(R13)		
	This is an initial estimate based on a visual inspection of be prepared after the vehicle is surveyed by a motor Sur	f the above v	ehicle. The final repair	ir quantum v	vill