

Premium Carz

Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date: 12/10/2018

TO: EQ Insurance Company Ltd
5 Maxwell Road
#17-00 MND Complex
Singapore 069110

Our Customer: Tee Yaw Kiat

Vehicle No: SMA4130Y

Model: Honda Shuttle 1.5G CVT

Manufacture Year: 2018

Date of Accident: 11/10/2018

Total Estimate Repair Days: 25

Total Pages: 3

Attn: Motor Claims Department

Fax: 6224 3903

Re: Repair Estimate For Third Party Claim against SKZ389L

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Tail gate <i>Distorted</i>	1	\$1,195.20	\$1,195.20	✓
2	Tail gate absorber RH <i>3mm</i>	1	\$165.40	\$165.40	+
3	Tail gate absorber LH	1	\$165.40	\$165.40	+
4	Tail gate lock <i>3mm</i>	1	\$96.60	\$96.60	✓
5	Tail gate lower catch <i>But</i>	1	\$24.70	\$24.70	✓
6	Tail gate opening bezel <i>new</i>	1			+
7	Tail gate weatherstrip <i>lt</i>	1	\$168.50	\$168.50	✓
8	Tail gate trimboard <i>Grubed</i>	1	\$320.80	\$320.80	✓
9	Tail gate garnish <i>new</i>	1			+
10	Tail gate chrome ?	1	\$383.30	\$383.30	?
11	Tail gate "H" logo <i>new</i>	1	\$38.20	\$38.20	+
12	Tail gate "Shuttle" emblem <i>new</i>	1	\$55.20	\$55.20	✓
13	Rear number plate lamp <i>new</i>	2	\$38.50	\$77.00	+
14	Tail gate reflector RH ?	1	\$305.20	\$305.20	
15	Tail gate reflector LH ?	1	\$305.20	\$305.20	
16	Tail lamp RH ?	1	\$520.60	\$520.60	
17	Tail lamp LH ?	1	\$520.60	\$520.60	
18	Tail lamp panel RH ?	1			
19	Tail lamp panel LH ?	1			
20	Rear bumper <i>Distorted</i>	1	\$1,180.40	\$1,180.40	✓
21	Rear bumper side retainer RH <i>3mm</i>	1	\$26.50	\$26.50	✓
22	Rear bumper side retainer LH	1	\$26.50	\$26.50	✓
23	Rear bumper tow hook cover <i>Del'd.</i>	1	\$26.50	\$26.50	✓
24	Rear bumper reflector garnish RH <i>Del'd.</i>	1	\$45.20	\$45.20	✓
25	Rear bumper reflector garnish LH <i>Del'd.</i>	1	\$45.20	\$45.20	✓
26	Rear bumper reflector RH <i>3mm</i>	1	\$45.60	\$45.60	+
27	Rear bumper reflector LH	1	\$45.60	\$45.60	+
28	Rear bumper lower cover RH ?	1			?
29	Rear bumper lower cover LH ?	1			?
30	Rear fender RH ?	1	\$1,010.90	\$1,010.90	?
31	Rear fender LH ?	1	\$1,010.90	\$1,010.90	?
32	Rear fender trimboard RH ?	1	\$489.60	\$489.60	?
33	Rear fender trimboard LH ?	1	\$489.60	\$489.60	?
34	Rear door RH <i>3mm</i>	1	repair	repair	+
35	Rear door LH	1	repair	repair	+
36	Rear end panel <i>Distorted</i>	1	\$601.90	\$601.90	✓
37	Rear end panel garnish <i>Distorted</i>	1	\$155.50	\$155.50	✓

Premium Carz

Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
38	Spare tyre panel ?	1	\$956.20	\$956.20	?
39	Spare tyre board <i>could</i>	1	\$585.40	\$585.40	✓
40	Spare tyre tools box <i>could</i>	1	\$350.80	\$350.80	✓
41	Exhaust silencer ?	1	\$745.90	\$745.90	?
42	Exhaust heat shield ?	1	\$78.60	\$78.60	?
43	Exhaust mounting <i>New</i>	2	\$26.50	\$53.00	✓
44	Rear windscreen glass moulding <i>new</i>	1	\$120.40	\$120.40	✓
45	Rear fender quarter glass moulding RH ?	1	\$48.60	\$48.60	?
46	Rear fender quarter glass moulding LH ?	1	\$48.60	\$48.60	?
47	Rear chassis RH <i>Repair</i>	1	repair	repair	✓
48	Wiper motor <i>new</i>	1	\$490.80	\$490.80	✓
Sub-Total				\$13,020.10	
Less 20%				\$2,604.02	
Total				\$10,416.08	
A.	Spare Parts (S/Nett)				
1	Rear number plate <i>Beut cut</i>	1	\$35.00	\$35.00	✓
2	Rear number plate casing <i>Rehnd</i>	1	\$35.00	\$35.00	✓
3	Reverse camera <i>Rehd</i>	1	\$388.00	\$388.00	✓
4	Insulator tape <i>new</i>	1	\$150.00	\$150.00	60
5	Sealant <i>new</i>	1	\$80.00	\$80.00	60
6	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	30
7	Rear bumper lower cover clip RH/LH ?	10	\$5.00	\$50.00	?
8	Rear end panel garnish clip <i>new</i>	8	\$5.00	\$40.00	10
9	Tail gate trimboard clip <i>new</i>	16	\$5.00	\$80.00	30
10	Reverse sensor (Set) <i>Rehd</i>	1	\$250.00	\$250.00	200
11	Spare tyre <i>new</i>	1	\$350.00	\$350.00	✓
12	Tools box ?	1	\$280.00	\$280.00	?
Sub Total 2				\$1,788.00	
Total for Parts				\$12,204.08	
B.	Labour				
1	To check wiring.			TBA	
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$3,000.00	
3	Spray painting all affected parts & areas.			\$2,000.00	1400
4	To spray anti-rust undercoat.			\$150.00	60
5	To remove and refit rear windscreen glass.			\$120.00	✓
6	To remove and refit rear fender quarter glass RH.			\$100.00	?
7	To remove and refit rear fender quarter glass LH.			\$100.00	?
8	To remove and replace exhaust silencer.			\$250.00	80
Total Labour				\$5,720.00	
Total Repair Cost				\$17,924.08	

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	<i>Adrian Lj</i>
Contact	<i>96893735</i>
Survey Date	<i>15/10/18</i>
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Date : 15/10/2018

TO: EQ Insurance Company Ltd
5 Maxwell Road
#17-00 MND Complex
Singapore 069110

Our Customer : Tee Yaw Kiat

Vehicle No : SMA4130Y

Model : Honda Shuttle 1.5G CVT

Manufacture Year : 2018

Date of Accident : 11/10/2018

Total Estimate Repair Days : 25

Total Pages : 1

Attn : Motor Claims Department

Fax : 6224 3903

Re: Supplementary Repair Estimate For Third Party Claim against SKZ389L

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Spare tyre foam	1		\$0.00	
2	Spare tyre tools foam	1		\$0.00	
3	Rear bumper reflector garnish inner foam RH	1		\$0.00	
4	Rear bumper reflector garnish inner foam LH	1		\$0.00	
5	Rear air vent LH	1		\$0.00	
6	Rear bumper inner panel LH	1		\$0.00	
	Rear bumper air vent LH top bracket		Sub-Total	\$0.00	
			Less 20%	\$0.00	
	Total Supplementary Repair Cost				

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No