

22/03/2002

ASS. REC. BY:

REF:

CS/ASM18018728/4rd3

Special Instruction:

Surveyor:

Matus

ASSIGNMENT (Office)

From (Person):

Lynn Khong

of

ASM(AxA)

Date/Time:

15/10/2018

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGK 7249M

Insured:

at Workshop m/s

Ethoz (fempines)

Tel:

GG54 7617

of

22 fempines street 92

Policy No:

Claim No:

S8M00Z9P

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

14/10/2018

☒ CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:02pm 16/10/18

Person Contacted:

Zuon Kai

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SGK 7249M-x

16/10/18

Send preli revised via SMART claim

Submarine No/cus

REF:

ASSIGNMENT

From: Date: Estimated Cost: 00 / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SGK 7249M
at Workshop n/s Stur
of
Insured:
Policy No:
Claims No:
Sum Insured: Excess: 100
(Client's Record)
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 18500/-
IDAC Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 1.34 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1A1316
Date: Person Contacted: Nett 5384
Vehicle: IN / OUT

Veh No: SGK 7249M Yr Regn: 8.06
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Herb Civic C/C 1799
Colour: red A/C: Insured / Std / NI / NA
Sp. Reading: 205/33 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: JHMF0163065211730
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or
Brake: Order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/55 R18
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 14/10/18 D.O.I. 16/10/18
Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
21
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Nett Repair agree not more than \$5300
30-6-2021

26/10/2018

26/10/18 \$5201.25 - confirmed by fax (Red 2225.10, 30th) (No LS)

RECEIVED 26 OCT 2018

Date/Time: File Pass to? ☐ : Preli. Report
☐ : Final Report

Date/Time: File Return to?

26/10- typet

Report Format: SMART claim
Lump Sum / I.B.I: (\$) 5201.25

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Weekend (\$)

Survey Fee
Transportation
\$ + RS \$
Photos
Others

TOTAL

200
200

New Message

Type *

☒ Message

Subject *

IA SUBMITTED FOR-SGK 7249M

Message *

Dear Sir/Madam,
Please be informed that IA submitted. We have Authorize repair. Thanks Veron Chen

Cancel

Send



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date:16/10/2018

Survey details

Date of loss	14/10/2018
Date of appointment	15/10/2018
Date of survey	16/10/2018
Location of survey	ETHOZ AUTOMOTIVE

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGK 7249M
Make and Model	HONDA CIVIC 1.8L (A)
Date of registration	23/8/2006
Excess	\$500
Market Value	\$18,500.00
Parf Rebate	\$13,116.00
Nett Loss	\$5,384.00

Repair details

Initial Estimate	\$7,426.35
------------------	------------

Proposed/Revised repair cost:

Parts	\$3,465.50
"Check items (Estimated)	\$605.00
Labour	\$1,191.25
Total	\$5,261.75
Lump Sum (Estimated)	

Number of days of repair	5 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the front portion

Damages Consistent
Repair Cost Economical

We have authorise repair.

Repairer agree repair cost not exceeding \$5300/-

Service Request Details

Claim

S8M00Z9P

Reference

None 

Loss Date

October 14, 2018

Request Date

October 15, 2018

Due Date

October 22, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SGK7249M

Make

HONDA

Model

CIVIC 1.8 VTI

Service Address

Primary Contact/Insured

LIM KON LENG

BLK 162 TAMPINES STREET 12, #08-235, 521162, Singapore

65416938

limkl@pweh.com

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Additional Instructions

ETHOZ (TAMP) OD EXCESS \$500 (unnamed)

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 9769G

Vehicle Details

Vehicle No.: SGK7249M
 Vehicle to be Exported: No
 Intended Deregistration Date: 16 Oct 2018
 Vehicle Make: HONDA
 Vehicle Model: CIVIC 1.8L A
 Primary Colour: Red
 Manufacturing Year: 2006
 Engine No.: R18A11039165
 Chassis No.: JHMFJ16306S211730
 Maximum Power Output: 103.0 kW (138 bhp)
 Open Market Value: \$20,861.00
 Original Registration Date: 23 Aug 2006
 First Registration Date: 23 Aug 2006
 Transfer Count: 0
 Actual ARF Paid: \$22,948.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2021
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 5
 PQP Paid: \$24,240.00
 COE Rebate Amount: \$13,116.00
 Total Rebate Amount: \$13,116.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Oct 2018

OK



HONDA CIVIC Price Range Depreciation > 10 year(s) Vehicle Type

[Advanced Search](#)

Home » Used Cars » Car Search » Honda Civic 1.8M VTI-S (COE till 05/2021)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle



Sugar King Gives Away Fortune

movymag.com

"My Greatest Gift To Malaysia"
"Robert Kuok -
"Do this to give yourself an amazing future"

OPEN

Honda Civic 1.8M VTI-S (COE till 05/2021)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

CONSIGNMENT



[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price	\$19,800
Depreciation	\$7,550 /yr
Reg Date	17-Jul-2006 (2yrs 7mths 14days COE left)
Manufactured	2006
Mileage	229,000 km (18.7k /yr)
Transmission	Manual
Engine Cap	1,799 cc
Road Tax	\$1,174 /yr
Power	103.0 kW (138 bhp) View specs of the Honda Civic (2006-2012)
Curb Weight	1,190 kg
Features	Powerful DOHC 16 Valves I-Vtec Powering 138HP On A Front Wheel Drive Setup Mated To A 5 Speed Automatic/Pedal Shift Gearbox With SRS Safety Airbag!
Accessories	-
Description	Powerful, Comfortable, Reliable And Low Maintenance Cost. Flexible Bank/ In-house Loan Package Available. Viewing Is Highly Encouraged, Consignment Unit. Call Our Friendly And Professional Sales Team Now To Arrange Viewing For This Beautiful Unit!
COE	\$23,024
OMV	\$20,709
ARF	\$22,780
Dereg Value	\$12,073 as of today (change)
No. of Owners	4
Type of Veh	Mid-Sized Sedan
Category	COE Car, Consignment Car
Availability	Available

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#)

Posted on: 15-Oct-2018 | Last Updated on: 15-Oct-2018

Tags: Honda Civic, honda civic, 2006 Honda Civic, 2006 honda civic, Honda, Civic, civic, Used Honda

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » [List of owner consignment cars](#)
- » [List of consignment agents](#)



Seller Information

Company	Car Search
	» dealer's pricelist
	» 49 vehs sold 145 vehs available
Address	18 Sin Ming Lane #04-02 Search cars nearby this location.
Location	Midview City
Office No	62620728
Contact Person(s)	Charles 94527972 Justin 91827511 Rachel 91126538 Kelvin 97593539

Upfront Payment

» [more Financial info](#)

Compare

Transfer Fee \$25



redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 📠 (65) 6880 4740
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

Certificate of Insurance

account number
08274

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	LIM KON LENG	Certificate number	GA383665 / 1
Cover	Comprehensive	Chassis number	JHMF16306S211730
Plan name	Essential	Engine number	R18A11039165
NCD applicable	50%		
Vehicle registration number	SGK7249M		
Period of Insurance	from 23/08/2018 to 22/08/2019 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS Windscreen Excess Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1849769G



Name

LIM KON LENG

林 崑 龍

Race

CHINESE

Date of birth

27-04-1951

Sex

M

Country/Place of birth

MALAYSIA

5976410



NRIC No. S1849769G



Date of issue

10-07-2018

Address

APT BLK 162 TAMPINES STREET 12
#08-235
SINGAPORE 521162

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Portrait of a man

Licence Number: **S8920509C**
Name: **LIM SHENG LIANG, DESMOND**

Birth Date: **17 Jun 1989**
Issue Date: **27 Sep 2011**

002003585D

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals =< 2500kg **28 Sep 2009**

NP 428A



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 10:24
Date Of Accident	14/10/2018 20:30
Exact Location Of Accident	SLIP RD OF TAMP AVE 12 TO TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK7249M
Insured/Policyholder	
Name Of Registered Owner	LIM KON LENG
NRIC No	S1849769G
Email Address	DESMONDLIM89@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90882285
Alternative Phone No	OFFICE-90882285

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA383665/1
Cover Note Number	23/08/2018-22/08/2019

Driver

Name of Driver	LIM SHENG LIANG DESMOND
NRIC No	S8920509C
Date Of Birth	17/06/1989
Occupation	INDOOR
Date Of Driving Pass	02/09/2009
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96163686
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	162 TAMPINES ST 12 08-235
Postcode	521162
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6160R
Vehicle Make/Model/Colour	TOYOTA PRIUS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NADIMOH BIN DARIMOSUVITO
NRIC/Passport Number	S1429703J
Contact Number	96992506
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/10/18 1040HR

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/10/18, around 8.30pm, I was exiting Tampines Ave 12, entering TPE (towards SLE), via the slip road. As I was checking for on-coming cars along TPE, I did not notice that the car in front had stopped and hit his rear bumper. The car was SHD 6160R, a SMRT TAXI TOYOTA PRIUS (car A)

We stopped to exchange particulars and no one was injured.


You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.


Reporting Only
<input checked="" type="checkbox"/> Claim OD
Claim TP
Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/10/18 1040HR


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ETHOZ AUTOMOTIVE
SOLUTIONS LTD
22 TAMPINES STREET 92
SINGAPORE
528876

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/1
Date Calculated: 15/10/18 07:12

Full Report - V1
Registration: SGK7249M
Printed: 15/10/18 14:13

Summary Information

Excess \$500

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jimmy Goh	Date of Incident:	14/10/18
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:		Estimated Repair Time:	6 day(s)
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

*Authorised
here
to be pho before
part.
16/10/18 @ 2pm
5-ly.*

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	BASE MODEL
Model Sheet Number:	H48 01
Registration:	SGK7249M
Registration Month:	August
Registration Year:	2006
VIN Number:	JHMF16306S211730
Manufacture Year:	2006
Odometer:	Not Known
Colour:	
Engine Number:	R18A11039165
Fuel Level:	%

Model Specs

FROM MODEL 2006	AIR CONDITIONING
FOG LAMPS	PAINTED DOOR HANDLES
PAINTED DOOR MIRRORS	MIRROR W/NDICATOR
1.6 LTR 92KW VTEC	CVT AUTO GEARBOX
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/10/18
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/1
Date Calculated: 15/10/18 07:12

Full Report - V1
Registration: SGK7249M
Printed: 15/10/18 14:13



Addresses

Cost Summary

Total Labour	\$1,107.00
Total Paint/Material	\$174.25
Total Parts	\$6,040.10
Total of Additional Costs	\$105.00
Excess:	TBA
Grand Total Exc GST:	\$7,426.35
7 % GST:	\$519.84
Grand Total Inc GST:	\$7,946.19

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	R + R BOTH FOG LAMPS	2.0	9.00
71125-SNB)	R + R RADIATOR GRILLE BRACKET	1.0	4.50
17SNA-601	RENEW BONNET	6.0	27.00
	INCLUDES: R + R AND ADJUST BONNET		
76841-SNB)	R + R FRONT WIPER RESERVOIR	2.0	9.00
	(BUMPER REMOVED)		
38100-SJD	R + R LOW TONE HORN	5.0	22.50
38150-SLA	R + R HIGH TON HORN	5.0	22.50
60261-SNB	R + R L/F WING	10.0	45.00
	INCLUDES: R + R FRONT BUMPER, HEADLAMP		
	AND WHEELHOUSE COVER		
60260-SMG	R + R R/F WING	7.0	31.50
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: R + R WHEELHOUSE		
	COVER		
	AND HEADLAMP		
60400-SNB	RENEW FRONT PANEL CPL	26.0	117.00
19010-RNA)	R + R RADIATOR CPL WITH ATTACHED PARTS	14.0	63.00
80110-SNA)	R + R AIR CONDITIONING CONDENSER	2.0	9.00
NO NUMBER	REFILL + VENT AIR CONDITIONING	8.0	36.00
0741	REPAIR L/F WING	20.0*	90.00
0742	REPAIR R/F WING	20.0*	90.00

LABOUR COST

Total Work Units	128.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	12.8HRS	\$576.00
Paint Labour	11.8HRS	\$531.00

Audatex System Using Manufacturer Times

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/1
Date Calculated: 15/10/18 07:12

Full Report - V1
Registration: SGK7249M
Printed: 15/10/18 14:13

Total Labour **24.6HRS** **\$1,107.00**

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	FRONT BUMPER SUPPORTSURFACE PAINT	4.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	15.0	
471	BONNET REPAIR PAINTING >50%	26.0	
741	L/F WING REPAIR PAINTING >50%	17.0	
742	R/F WING REPAIR PAINTING >50%	17.0	
LABOUR COST - PAINT			
TIME(PAINT)		85.0	
Preparation Main Work Plastic		8.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		118.0	
Total Paintwork Labour		11.8HRS	\$531.00
MATERIAL COST - PAINT			Cost Price
Surface-/Blend Paint			\$15.69
Repair Painting			\$71.90
Repair Painting Plastic			\$45.36
Material-Const Main Work Plastic			\$12.70
Total Excluding Pearlescent Uplift			\$174.25
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$174.25

PARTS

				Price Valid: 01/06/15	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
471	1	BONNET	60100SNB000ZZ		0% <i>Buc</i> 490.00* ✓
481	1	BONNET INSULATION	74141SNB000		0% <i>11</i> 105.00* X
492	1	BONNET LOCK	74120SNBE11		0% <i>12</i> 138.00* ✓
4465	1	CONDENSER	80110SNBA43	<i>set / part</i>	0% 520.00* ✓
283	1	FRONT BUMPER	04711SNB010ZZ		0% <i>22</i> 380.00* ✓
340	1	FRONT BUMPER SUPPORT	71130SNAU90ZZ		0% <i>321</i> 300.00* ✓
1009	1	FRONT PANEL CPL	60400SNBN01ZZ		0% <i>31</i> 530.00* ✓
350	1	FRT BUMPER CLAMP KIT			0% <i>121</i> 50.00* ✓
260	1	FRT NO PLATE REINF	71145SNBG90		0% <i>22</i> 58.00* ✓
411	1	GRILL BRACKET	71125SNB000		0% <i>7011</i> 98.00* ✓
412	1	GRILLE	71121SNB003		0% <i>711</i> 115.00* ✓
431	1	GRILLE BADGE	75700S9AG00		0% <i>226</i> 65.00* ✓
9646	1	HIGH TONE HORN	38150SLA013		0% <i>118</i> 158.00* X
561	1	L/F HEADLAMP CPL	33151SNBD01		0% <i>11</i> 495.00* X
317	1	L/F OUT BUMPER BRKT	71198SNB003		0% <i>311</i> 58.00* ✓
865	6	L/F SCREW	934050601608		0% <i>25</i> 0.00F X
867	1	L/F SCREW	90108S0A003		0% <i>25</i> 0.00F X
319	1	L/F UPP BUMPER BRKT	71190SNB000		0% <i>11</i> 55.00* X
789	1	L/F WING CLAMP KIT			0% <i>11</i> 50.00* X
7769	1	L/UPP RADIATOR BRKT	74171SNAA00		0% <i>11</i> 65.00* X
841	1	L/WHEELHOUSE SHELL	74151SNAA10		0% <i>11</i> 95.00* X

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/1
Date Calculated: 15/10/18 07:12

Full Report - V1
Registration: SGK7249M
Printed: 15/10/18 14:13

9645	1	LOW TONE HORN	38100SFJW02	0%	11	158.00*	X
367	4	MOUNTING CLAMP	934050601604	0%	11	0.00F	X
869	2	MOUNTING CLAMP	91545SE0003	0%	11	0.00F	X
870	2	MOUNTING CLAMP	91545SE0003	0%	11	0.00F	X
366	3	MOUNTING CLAMP	91506S9A003	0%	11	0.00F	X
365	8	MOUNTING CLAMP	91505S9A003	0%	11	0.00F	X
562	1	R/F HEADLAMP CPL	33101SNBD01	0%	11	495.00*	X
318	1	R/F OUT BUMPER BRKT	71193SNB003	0%	Ref	58.00*	X
866	6	R/F SCREW	934050601608	0%	11	0.00F	X
868	1	R/F SCREW	90108S0A003	0%	11	0.00F	X
320	1	R/F UPP BUMPER BRKT	71140SNB000	0%	Ref	55.00*	X
790	1	R/F WING CLAMP KIT		0%	11	50.00*	X
7770	1	R/UPP RADIATOR BRKT	74171SNAA00	0%	11	65.00*	X
842	1	R/WHEELHOUSE SHELL	74101SNAA10	0%	11	95.00*	X
7761	1	RADIATOR	19010RNAA01	0%	Ref/pun	550.00*	X
410	1	RADIATOR GRILLE TRIM	71122SNB003	0%	Ref	140.00*	X
f: OEM Parts				Saving		\$56.11	
g: Original				Sub Total		\$5,491.00	
h: Secondhand				Mark Up From Cost (10 %)		\$549.10	
p: Parallel				Sundry Parts (Fixed)		\$0.00	
x: Exchange				Total Parts		\$6,040.10	390

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRONT NUMBER SPECIALIST	0%	\$35.00
PLATE		
RADIATOR COOLANT SPECIALIST		\$20.00
AIRCON COOLANT SPECIALIST	0%	\$50.00
Total Extras		\$105.00

Final Calculation

Total Parts	\$6,040.10
Labour	
Total Panel/Mechanical	\$576.00
Total Paintwork	\$531.00
Total Labour	\$1,107.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$105.00
Total of Additional Costs	\$105.00
Total Paint/Material Costs	\$174.25
Grand Total Excludes GST	\$7,426.35
GST @ 7 %	\$519.84
Grand Total Includes GST	\$7,946.19

Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Audatex System Using Manufacturer Times Acknowledged by Repairer

Signature:
Date:

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:

Full Report - V1

Assessment Number: JIM00254

Registration: SGK7249M

Version: ETHOZASL/1

Printed: 15/10/18 14:13

Date Calculated: 15/10/18 07:12

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Prel. Revised

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/2
Date Calculated: 16/10/2018 08:30

Full Report - V1
Registration: SGK7249M
Printed: 16/10/2018 15:31

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	14/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	6 day(s)
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	BASE MODEL
Model Sheet Number:	H48 01
Registration:	SGK7249M
Registration Month:	August
Registration Year:	2006
VIN Number:	JHMFD16306S211730
Manufacture Year:	2006
Odometer:	Not Known
Colour:	
Engine Number:	R18A11039165
Fuel Level:	%

Model Specs

FROM MODEL 2006	AIR CONDITIONING
FOG LAMPS	PAINTED DOOR HANDLES
PAINTED DOOR MIRRORS	MIRROR W/NDICATOR
1.6 LTR 92KW VTEC	CVT AUTO GEARBOX
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Full Report - V1



Assessment Number: JIM00254

Registration: SGK7249M

Version: ETHOZASL/2

Printed: 16/10/2018 15:31

Date Calculated: 16/10/2018 08:30



Addresses

Cost Summary

Total Labour	\$1,017.00
Total Paint/Material	\$174.25
Total Parts	\$3,965.50
Total of Additional Costs	\$105.00
Excess:	TBA
Grand Total Exc GST:	\$5,261.75
7 % GST:	\$368.32
Grand Total Inc GST:	\$5,630.07

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$45.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	R + R BOTH FOG LAMPS	2.0	9.00
71125-SNB)	R + R RADIATOR GRILLE BRACKET	1.0	4.50
17SNA-601	RENEW BONNET	6.0	27.00
	INCLUDES: R + R AND ADJUST BONNET		
76841-SNB)	R + R FRONT WIPER RESERVOIR	2.0	9.00
	(BUMPER REMOVED)		
38100-SJD	R + R LOW TONE HORN	5.0	22.50
38150-SLA	R + R HIGH TON HORN	5.0	22.50
60261-SNB	R + R L/F WING	10.0	45.00
	INCLUDES: R + R FRONT BUMPER, HEADLAMP		
	AND WHEELHOUSE COVER		
60260-SMG	R + R R/F WING	7.0	31.50
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: R + R WHEELHOUSE		
	COVER		
	AND HEADLAMP		
60400-SNB	RENEW FRONT PANEL CPL	26.0	117.00
19010-RNA)	R + R RADIATOR CPL WITH ATTACHED PARTS	14.0	63.00
80110-SNA)	R + R AIR CONDITIONING CONDENSER	2.0	9.00
NO NUMBER	REFILL + VENT AIR CONDITIONING	8.0	36.00
0741	REPAIR L/F WING	10.0*	45.00
0742	REPAIR R/F WING	10.0*	45.00

LABOUR COST

Total Work Units

108.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

10.8HRS

\$486.00

Paint Labour

11.8HRS

\$531.00

Claim Reference:

Full Report - V1

Assessment Number: JIM00254

Registration: SGK7249M

Version: ETHOZASL/2

Printed: 16/10/2018 15:31

Date Calculated: 16/10/2018 08:30

Total Labour**22.6HRS****\$1,017.00**

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	FRONT BUMPER SUPPORT SURFACE PAINT	4.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	15.0	
471	BONNET REPAIR PAINTING >50%	26.0	
741	L/F WING REPAIR PAINTING >50%	17.0	
742	R/F WING REPAIR PAINTING >50%	17.0	
LABOUR COST - PAINT			
	TIME(PAINT)	85.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	118.0	
	Total Paintwork Labour	11.8HRS	\$531.00
MATERIAL COST - PAINT			Cost Price
	Surface-/Blend Paint		\$15.69
	Repair Painting		\$71.90
	Repair Painting Plastic		\$45.36
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$174.25
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$174.25

PARTS

Guide No.		Qty	Description	Part Number	Supplier	Bet.	Price (\$)
471	1		BONNET	60100SNB000ZZ		0%	490.00*
492	1		BONNET LOCK	74120SNBE11		0%	138.00*
4465	1		CONDENSER	80110SNBA43		0%	520.00*
283	1		FRONT BUMPER	04711SNB010ZZ		0%	380.00*
340	1		FRONT BUMPER SUPPORT	71130SNAU90ZZ		0%	300.00*
1009	1		FRONT PANEL CPL	60400SNBN01ZZ		0%	530.00*
350	1		FRT BUMPER CLAMP KIT			0%	50.00*
260	1		FRT NO PLATE REINF	71145SNBG90		0%	58.00*
411	1		GRILL BRACKET	71125SNB000		0%	98.00*
412	1		GRILLE	71121SNB003		0%	115.00*
431	1		GRILLE BADGE	75700S9AG00		0%	65.00*
317	1		L/F OUT BUMPER BRKT	71198SNB003		0%	58.00*
319	1		L/F UPP BUMPER BRKT	71190SNB000		0%	55.00*
365	8		MOUNTING CLAMP	91505S9A003		0%	0.00F
367	4		MOUNTING CLAMP	934050601604		0%	0.00F
366	3		MOUNTING CLAMP	91506S9A003		0%	0.00F
318	1		R/F OUT BUMPER BRKT	71193SNB003		0%	58.00*
7761	1		RADIATOR	19010RNAA01		0%	550.00*
410	1		RADIATOR GRILLE TRIM	71122SNB003		0%	140.00*
f: OEM Parts				Saving			\$28.73
g: Original				Sub Total			\$3,605.00

Price Valid: 01/06/2015

Claim Reference:

Full Report - V1

Assessment Number: JIM00254

Registration: SGK7249M

Version: ETHOZASL/2

Printed: 16/10/2018 15:31

Date Calculated: 16/10/2018 08:30

h: Secondhand

p: Parallel

x: Exchange

Mark Up From Cost

(10 %)

\$360.50

Sundry Parts

(Fixed)

\$0.00

Total Parts**\$3,965.50**

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras**Description****Betterment****Price**FRONT NUMBER SPECIALIST
PLATE

0%

\$35.00

RADIATOR COOLANT SPECIALIST
AIRCON COOLANT SPECIALIST

0%

\$20.00

\$50.00

Total Extras**\$105.00****Final Calculation****Total Parts****\$3,965.50****Labour**

Total Panel/Mechanical

\$486.00

Total Paintwork

\$531.00

Total Labour**\$1,017.00****Additional Costs**

Corr Prot Materials External

\$0.00

Corr Prot Materials Internal

\$0.00

Cost of Specialist

\$105.00

Total of Additional Costs**\$105.00****Total Paint/Material Costs****\$174.25****Grand Total Excludes GST****\$5,261.75**

GST @ 7 %

\$368.32**Grand Total Includes GST****\$5,630.07****Assessment Notes**

ETHOZ AUTOMOTIVE
SOLUTIONS LTD
22 TAMPINES STREET 92
SINGAPORE
528876

Workshop Finalised

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/3
Date Calculated: 20/10/18 05:00

Full Report - V1
Registration: SGK7249M
Printed: 23/10/18 12:13

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jimmy Goh	Date of Incident:	14/10/18
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	6 day(s)
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	BASE MODEL
Model Sheet Number:	H48 01
Registration:	SGK7249M
Registration Month:	August
Registration Year:	2006
VIN Number:	JHMFD16306S211730
Manufacture Year:	2006
Odometer:	Not Known
Colour:	
Engine Number:	R18A11039165
Fuel Level:	%

Model Specs

FROM MODEL 2006	AIR CONDITIONING
FOG LAMPS	PAINTED DOOR HANDLES
PAINTED DOOR MIRRORS	MIRROR W/NDICATOR
1.6 LTR 92KW VTEC	CVT AUTO GEARBOX
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	15/10/18
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/3
Date Calculated: 20/10/18 05:00

Full Report - V1
Registration: SGK7249M
Printed: 23/10/18 12:13



Addresses

Cost Summary

Total Labour	\$1,017.00
Total Paint/Material	\$174.25
Total Parts	\$3,905.00
Total of Additional Costs	\$105.00
Excess:	TBA
Grand Total Exc GST:	\$5,201.25
7 % GST:	\$364.09
Grand Total Inc GST:	\$5,565.34

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	R + R BOTH FOG LAMPS	2.0	9.00
71125-SNB)	R + R RADIATOR GRILLE BRACKET	1.0	4.50
17SNA-601	RENEW BONNET	6.0	27.00
	INCLUDES: R + R AND ADJUST BONNET		
76841-SNB)	R + R FRONT WIPER RESERVOIR (BUMPER REMOVED)	2.0	9.00
38100-SJD	R + R LOW TONE HORN	5.0	22.50
38150-SLA	R + R HIGH TON HORN	5.0	22.50
60261-SNB	R + R L/F WING	10.0	45.00
	INCLUDES: R + R FRONT BUMPER, HEADLAMP AND WHEELHOUSE COVER		
60260-SMG	R + R R/F WING (BUMPER REMOVED) DOES NOT INCLUDE: R + R WHEELHOUSE COVER AND HEADLAMP	7.0	31.50
60400-SNB	RENEW FRONT PANEL CPL	26.0	117.00
19010-RNA)	R + R RADIATOR CPL WITH ATTACHED PARTS	14.0	63.00
80110-SNA)	R + R AIR CONDITIONING CONDENSER	2.0	9.00
NO NUMBER	REFILL + VENT AIR CONDITIONING	8.0	36.00
0741	REPAIR L/F WING	10.0*	45.00
0742	REPAIR R/F WING	10.0*	45.00

LABOUR COST

Total Work Units

Corrosion Protection External Labour

Corrosion Protection Internal Labour

Sub Total

Paint Labour

108.0	
0.0HRS	0.00
0.0HRS	0.00
10.8HRS	\$486.00
11.8HRS	\$531.00

Audatex System Using Manufacturer Times

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/3
Date Calculated: 20/10/18 05:00

Full Report - V1
Registration: SGK7249M
Printed: 23/10/18 12:13

Total Labour 22.6HRS \$1,017.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	FRONT BUMPER SUPPORTSURFACE PAINT	4.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	15.0	
471	BONNET REPAIR PAINTING >50%	26.0	
741	L/F WING REPAIR PAINTING >50%	17.0	
742	R/F WING REPAIR PAINTING >50%	17.0	
LABOUR COST - PAINT			
	TIME(PAINT)	85.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	118.0	
	Total Paintwork Labour	11.8HRS	\$531.00
MATERIAL COST - PAINT			Cost Price
	Surface-/Blend Paint		\$15.69
	Repair Painting		\$71.90
	Repair Painting Plastic		\$45.36
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$174.25
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$174.25

PARTS

				Price Valid: 01/06/15	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
471	1	BONNET	60100SNB000ZZ		0% 490.00*
492	1	BONNET LOCK	74120SNBE11		0% 138.00*
4465	1	CONDENSER	80110SNBA43		0% 520.00*
283	1	FRONT BUMPER	04711SNB010ZZ		0% 380.00*
340	1	FRONT BUMPER SUPPORT	71130SNAU90ZZ		0% 300.00*
1009	1	FRONT PANEL CPL	60400SNBN01ZZ		0% 530.00*
350	1	FRT BUMPER CLAMP KIT			0% 50.00*
260	1	FRT NO PLATE REINF	71145SNBG90		0% 58.00*
411	1	GRILL BRACKET	71125SNB000		0% 98.00*
412	1	GRILLE	71121SNB003		0% 115.00*
431	1	GRILLE BADGE	75700S9AG00		0% 65.00*
485	7	INSULATION MNTG KIT	91501STK003		0% 0.00F
317	1	L/F OUT BUMPER BRKT	71198SNB003		0% 58.00*
865	6	L/F SCREW	934050601608		0% 0.00F
365	8	MOUNTING CLAMP	91505S9A003		0% 0.00F
367	4	MOUNTING CLAMP	934050601604		0% 0.00F
366	3	MOUNTING CLAMP	91506S9A003		0% 0.00F
318	1	R/F OUT BUMPER BRKT	71193SNB003		0% 58.00*
866	6	R/F SCREW	934050601608		0% 0.00F
7761	1	RADIATOR	19010RNAA01		0% 550.00*
410	1	RADIATOR GRILLE TRIM	71122SNB003		0% 140.00*

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/3
Date Calculated: 20/10/18 05:00

Full Report - V1
Registration: SGK7249M
Printed: 23/10/18 12:13

f: OEM Parts	Saving	\$52.00
g: Original	Sub Total	\$3,550.00
h: Secondhand	Mark Up From Cost (10 %)	\$355.00
p: Parallel	Sundry Parts (Fixed)	\$0.00
x: Exchange	Total Parts	\$3,905.00

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRONT NUMBER SPECIALIST	0%	\$35.00
PLATE		
RADIATOR COOLANT SPECIALIST		\$20.00
AIRCON COOLANT SPECIALIST	0%	\$50.00
Total Extras		\$105.00

Final Calculation

Total Parts	\$3,905.00
Labour	
Total Panel/Mechanical	\$486.00
Total Paintwork	\$531.00
Total Labour	\$1,017.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$105.00
Total of Additional Costs	\$105.00
Total Paint/Material Costs	\$174.25
Grand Total Excludes GST	\$5,201.25
GST @ 7 %	\$364.09
Grand Total Includes GST	\$5,565.34

Assessment Notes

cdh confirm
26/10/18
\$5,565.34

EURO AUTOPART TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201810-10363

ATTENTION TO SALES PERSON: JIMMY
P/O 165904

DATE: 16-Oct-18

VEHICLE NO: SGK7249M HD CIVIC FD1

30 DAYS

SEND TO : 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		BONNET	1	\$ 490.00	\$ 490.00
2		BONNET LOCK	1	\$ 138.00	\$ 138.00
3		AIRCON CONDENSER	1	\$ 520.00	\$ 520.00
4		FRT BUMPER	1	\$ 380.00	\$ 380.00
5		FRT BUMPER REINFOCEMENT	1	\$ 300.00	\$ 300.00
6		FRT SUPPORT PANEL	1	\$ 530.00	\$ 530.00
7		FRT BUMPER CLIPS	10	\$ 5.00	\$ 50.00
8		FRT BUMPER NUMBER PLATE	1	\$ 58.00	\$ 58.00
9		FRT SUPPORT TOP GARNISH	1	\$ 98.00	\$ 98.00
10		FRT GRILLE BASE	1	\$ 115.00	\$ 115.00
11		FRT GRILLE LOGO	1	\$ 65.00	\$ 65.00
12		FRT GRILLE CHROME MOULDING	1	\$ 140.00	\$ 140.00
13		FRT BUMPER RETAINER RH/LH	2	\$ 58.00	\$ 116.00
14		RADIATOR	1	\$ 550.00	\$ 550.00
15					\$ -
16					\$ -
17		Dept Head			\$ -
18		Agreement No			\$ -
19		Job Card No			\$ -
20					\$ -
21		Finance			\$ -
22		Control No			\$ -
23		Invoice No			\$ -
24					\$ -
25		Remarks			\$ -
SUB-TOTAL					\$ 3,550.00
GST @ 7%					\$ 248.50
GRAND TOTAL					\$ 3,798.50

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

Jimmy Goh



Jimmy Goh

AUTHORISED BY:



NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore

408933

Finalised

Claim Reference:
Assessment Number: JIM00254
Version: ETHOZASL/3
Date Calculated: 26/10/2018 02:38

Full Report - V1
Registration: SGK7249M
Printed: 26/10/2018 09:39

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	14/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	6 day(s)
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	BASE MODEL
Model Sheet Number:	H48 01
Registration:	SGK7249M
Registration Month:	August
Registration Year:	2006
VIN Number:	JHMF16306S211730
Manufacture Year:	2006
Odometer:	Not Known
Colour:	
Engine Number:	R18A11039165
Fuel Level:	%



Model Specs

FROM MODEL 2006	AIR CONDITIONING
FOG LAMPS	PAINTED DOOR HANDLES
PAINTED DOOR MIRRORS	MIRROR W/INDICATOR
1.6 LTR 92KW VTEC	CVT AUTO GEARBOX
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

**Addresses****Cost Summary**

Total Labour	\$1,017.00
Total Paint/Material	\$174.25
Total Parts	\$3,905.00
Total of Additional Costs	\$105.00
Excess:	TBA
Grand Total Exc GST:	\$5,201.25
7 % GST:	\$364.09
Grand Total Inc GST:	\$5,565.34

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	R + R BOTH FOG LAMPS	2.0	9.00
71125-SNB)	R + R RADIATOR GRILLE BRACKET	1.0	4.50
17SNA-601	RENEW BONNET	6.0	27.00
	INCLUDES: R + R AND ADJUST BONNET		
76841-SNB)	R + R FRONT WIPER RESERVOIR (BUMPER REMOVED)	2.0	9.00
38100-SJD	R + R LOW TONE HORN	5.0	22.50
38150-SLA	R + R HIGH TON HORN	5.0	22.50
60261-SNB	R + R L/F WING	10.0	45.00
	INCLUDES: R + R FRONT BUMPER, HEADLAMP AND WHEELHOUSE COVER		
60260-SMG	R + R R/F WING (BUMPER REMOVED)	7.0	31.50
	DOES NOT INCLUDE: R + R WHEELHOUSE COVER AND HEADLAMP		
60400-SNB	RENEW FRONT PANEL CPL	26.0	117.00
19010-RNA)	R + R RADIATOR CPL WITH ATTACHED PARTS	14.0	63.00
80110-SNA)	R + R AIR CONDITIONING CONDENSER	2.0	9.00
NO NUMBER	REFILL + VENT AIR CONDITIONING	8.0	36.00
0741	REPAIR L/F WING	10.0*	45.00
0742	REPAIR R/F WING	10.0*	45.00

LABOUR COST

Total Work Units	108.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	10.8HRS	\$486.00
Paint Labour	11.8HRS	\$531.00

Total Labour**22.6HRS****\$1,017.00****PAINT WORK****Time Basis 10 WU = 1 HR. Price = \$45.00/HR****Guide Number Description****WU****Cost Price (\$)**

- TWO COAT METALLIC
- PREPARE OFF VEHICLE

340	FRONT BUMPER SUPPORTSURFACE PAINT	4.0
1009	FRONT PANEL CPL SURFACE PAINT	6.0
283	FRONT BUMPER REPAIR PAINT PLASTIC	15.0
471	BONNET REPAIR PAINTING >50%	26.0
741	L/F WING REPAIR PAINTING >50%	17.0
742	R/F WING REPAIR PAINTING >50%	17.0

LABOUR COST - PAINT**TIME(PAINT)****85.0****Preparation Main Work Plastic****8.0****Preparation Main Work Metal****25.0****Preparation Work Multi Layer Paint****0.0****Total Work Units (10WU/HR)****118.0****Total Paintwork Labour****11.8HRS****\$531.00****MATERIAL COST - PAINT****Cost Price****Surface-/Blend Paint****\$15.69****Repair Painting****\$71.90****Repair Painting Plastic****\$45.36****Material-Const Main Work Plastic****\$12.70****Total Excluding Pearlescent Uplift****\$174.25****Pearlescent Uplift @ 0.0%****\$0.00****Total Paint Material Cost****\$174.25****PARTS**

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
471	1	BONNET	60100SNB000ZZ		0%	490.00*
492	1	BONNET LOCK	74120SNBE11		0%	138.00*
4465	1	CONDENSER	80110SNBA43		0%	520.00*
283	1	FRONT BUMPER	04711SNB010ZZ		0%	380.00*
340	1	FRONT BUMPER SUPPORT	71130SNAU90ZZ		0%	300.00*
1009	1	FRONT PANEL CPL	60400SNBN01ZZ		0%	530.00*
350	1	FRT BUMPER CLAMP KIT			0%	50.00*
260	1	FRT NO PLATE REINF	71145SNBG90		0%	58.00*
411	1	GRILL BRACKET	71125SNB000		0%	98.00*
412	1	GRILLE	71121SNB003		0%	115.00*
431	1	GRILLE BADGE	75700S9AG00		0%	65.00*
485	7	INSULATION MNTG KIT	91501STK003		0%	0.00F
317	1	L/F OUT BUMPER BRKT	71198SNB003		0%	58.00*
865	6	L/F SCREW	934050601608		0%	0.00F
365	8	MOUNTING CLAMP	91505S9A003		0%	0.00F
367	4	MOUNTING CLAMP	934050601604		0%	0.00F
366	3	MOUNTING CLAMP	91506S9A003		0%	0.00F
318	1	R/F OUT BUMPER BRKT	71193SNB003		0%	58.00*
866	6	R/F SCREW	934050601608		0%	0.00F
7761	1	RADIATOR	19010RNAA01		0%	550.00*
410	1	RADIATOR GRILLE TRIM	71122SNB003		0%	140.00*

Claim Reference:

Full Report - V1

Assessment Number: JIM00254

Registration: SGK7249M

Version: ETHOZASL/3

Printed: 26/10/2018 09:39

Date Calculated: 26/10/2018 02:38

f: OEM Parts	Saving	\$52.00
g: Original	Sub Total	\$3,550.00
h: Secondhand	Mark Up From Cost (10 %)	\$355.00
p: Parallel	Sundry Parts (Fixed)	\$0.00
x: Exchange	Total Parts	\$3,905.00

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras		Betterment	Price
FRONT NUMBER	SPECIALIST	0%	\$35.00
PLATE			
RADIATOR COOLANT	SPECIALIST		\$20.00
AIRCON COOLANT	SPECIALIST	0%	\$50.00
Total Extras			\$105.00

Final Calculation

Total Parts		\$3,905.00
Labour		
Total Panel/Mechanical	\$486.00	
Total Paintwork	\$531.00	
Total Labour		\$1,017.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$105.00	
Total of Additional Costs		\$105.00
Total Paint/Material Costs		\$174.25
Grand Total Excludes GST		\$5,201.25
GST @ 7 %		\$364.09
Grand Total Includes GST		\$5,565.34

Assessment Notes




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CS/ASM18018728/Uvd3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : LYNN KHONG			Date : 01-11-2018	
			Code : ASM	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SGK 7249M
Policy No.	GA383665/1	Coverage (\$)	0.00	
Claim No.	S8M00Z9P	Excess (\$)	500.00	
Assign From	LYNN KHONG	Assign Date	15/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JHMF16306S211730	Colour	RED	
Odometer	205133	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/10/2018	Inspection Date	16/10/2018	
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876			
5a. Remarks				
A)THE MARKET VALUE IS S\$18,500.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 7249M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	490.00	490.00
1	BONNET INSULATION	NOT NECESSARY	105.00	-
1	BONNET LOCK	TWISTED	138.00	138.00
1	CONDENSER	BENT / PUNCTURE	520.00	520.00
1	FRONT BUMPER	DENTED	380.00	380.00
1	FRONT BUMPER SUPPORT	BENT	300.00	300.00
1	FRONT PANEL CPL	BENT	530.00	530.00
1	FRT BUMPER CLAMP KIT	NECESSARY	50.00	50.00
1	FRT NO PLATE REINF	DEFORMED	58.00	58.00
1	GRILL BRACKET	TORN	98.00	98.00
1	GRILLE	TWISTED	115.00	115.00
1	GRILLE BADGE	NECESSARY	65.00	65.00
1	HIGH TONE HORN	NOT NECESSARY	158.00	-
1	L/F HEADLAMP CPL	NOT NECESSARY	495.00	-
1	L/F OUT BUMPER BRKT	BENT	58.00	58.00
6	L/F SCREW (NPA)	NO SUCH PARTS	-	-
1	L/F SCREW (NPA)	NO SUCH PARTS	-	-
1	L/F UPP BUMPER BRKT	NOT NECESSARY	55.00	-
1	L/F WING CLAMP KIT	NOT NECESSARY	50.00	-
1	L/UPP RADIATOR BRKT	NOT NECESSARY	65.00	-
1	L/WHEELHOUSE SHELL	NOT NECESSARY	95.00	-
1	LOW TONE HORN	NOT NECESSARY	158.00	-
4	MOUNTING CLAMP (NPA)	NOT NECESSARY	-	-
2	MOUNTING CLAMP (NPA)	NOT NECESSARY	-	-
2	MOUNTING CLAMP (NPA)	NOT NECESSARY	-	-
3	MOUNTING CLAMP (NPA)	NOT NECESSARY	-	-
8	MOUNTING CLAMP (NPA)	NOT NECESSARY	-	-
1	R/F HEADLAMP CPL	NOT NECESSARY	495.00	-
1	R/F OUT BUMPER BRKT	BENT	58.00	58.00
6	R/F SCREW (NPA)	NOT NECESSARY	-	-
1	R/F SCREW (NPA)	NOT NECESSARY	-	-

Report Ref No. CS/ASM18018728/Uvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R/F UPP BUMPER BRKT	TO REPAIR SEE LABOUR	55.00	-
1	R/F WING CLAMP KIT	NOT NECESSARY	50.00	-
1	R/UPP RADIATOR BRKT	NOT NECESSARY	65.00	-
1	R/WHEELHOUSE SHELL	NOT NECESSARY	95.00	-
1	RADIATOR	BENT / PUNCTURE	550.00	550.00
1	RADIATOR GRILLE TRIM	CRACKED	140.00	140.00
	COST PLUS 10%		549.10	355.00
			6,040.10	3,905.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	RADIATOR COOLANT (SN)	NECESSARY	20.00	20.00
1	AIRCON COOLANT (SN)	NECESSARY	50.00	50.00
			105.00	105.00
	<u>LABOUR</u>			
	TOTAL PANEL / MECHANICAL. INCLUSIVE OF THE REPAIR OF R/F UPP BUMPER BRKT.		576.00	486.00
	TOTAL PAINTWORK.		531.00	531.00
	TOTAL PAINT / MATERIAL COSTS.		174.25	174.25
			1,281.25	1,191.25
	GRAND TOTAL		7,426.35	5,201.25
	RECOMMENDED COST OF REPAIRS			5,201.25
	LESS EXCESS			-500.00
	NETT LIABILITY			4,701.25

Report Ref No. CS/ASM18018728/Uvd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.