

ASS. REC. BY:

REF: CS/LPC18018731/R1+d3³²

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Gerold poh

of

Lpc

Date/Time: 16/10/18 @ 10:57am

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 9911R

Insured:

at Workshop m/s

Trans Eurokars

Tel:

6395 7877 / 63310684

of

27A fengong pengun

Policy No:

Claim No:

18/18/18/VPOS/021025

19/11/18

Sum Insured:

Excess:

NO EXCESS

Make of Veh:

D.O.A.

12/10/18

(Client's Record)

CA / ☒ KEV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:23am @ 16/10/18

Person Contacted:

Vion

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 9911R - X
18/10	Revert via email preli advised.
	Pending repair cost.
	Submit uneconomical total loss report.

108/1/17

REF:

2547E

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MVTo Inspect Vehicle No: SKV 9911Rat Workshop m/s: TRANS EURO KARSof 27A, Myzrm PmzrmInsured: kompa

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: NIL

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 60K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKV 9911R Yr Regn: 2015 / AnhType: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: MAZDA 3 4000 1.5 c.c. 1496Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 64137 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 66M 42A 800 31324Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or LION SPORT

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/10/18 D.O.I. 12/10/18Survey held at TRANS EURO KARSDes. of Damages ☒ Fr / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 60.000/-
 LTA: 46.939/-
 NV: 13.061/-

RECEIVED 25 OCT 2018

Date/Time, File Pass to?

25/10/18 Typist
 Date/Time, File Return to?

2)

2)

Report Format : CTL

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)Survey Fee: 210Transportation: 50

S + RS SI

Photos 580Others 101TOTAL 861

26/10/18

36 x 15 = 540
 540 + 170 = 710

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 16 October 2018 10:57 AM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG; vion.lim@eurokars.com.sg
Subject: FW: OUR REF: SKV9911R OWN DAMAGED CLAIM
Attachments: SKV9911R OD LONPAC (TP).pdf

Our Ref : 18/18/18/VP05/021025

Dear Catherine/Nivitha,

Please proceed to survey and revert.

There is no excess applicable under Section I of the Motor policy.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: samuel.ng@eurokars.com.sg [mailto:samuel.ng@eurokars.com.sg]

Sent: Tuesday, 16 October, 2018 9:55 AM

To: GERALD POH WEE BIN; vion.lim@eurokars.com.sg

Cc: catherinechua@eurokars.com.sg

Subject: OUR REF: SKV9911R OWN DAMAGED CLAIM

OUR REF: SKV9911R OWN DAMAGED CLAIM

Dear Sir/Mdm,

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

The car currently inside our workshop at 27A Tanjong Penjuru.

Best Regards,

Samuel Ng

Insurance Claims Officer

Trans Eurokars Pte Ltd

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 18 October 2018 5:43 PM
To: Admin-D (LKKAUTO); 'GERALD POH WEE BIN'; assignments
Cc: 'MT_Claim_SG'; SUR
Subject: RE: OUR REF: SKV9911R OWN DAMAGED CLAIM
Attachments: PRELI ADVISED SKV 9911R.PDF; estimate_0001.pdf; photo.pdf

Dear Gerald,

Enclosed preliminary revised of vehicle **SKV 9911R**

We have not authorise repair

We are pending repair cost from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 16 October 2018 11:30 AM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: OUR REF: SKV9911R OWN DAMAGED CLAIM

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Tuesday, 16 October 2018 10:57 AM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; vion.lim@eurokars.com.sg
Subject: FW: OUR REF: SKV9911R OWN DAMAGED CLAIM

Our Ref : 18/18/18/VP05/021025

Denise Tay (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 22 October 2018 8:45 AM
To: Denise Tay (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: OUR REF: SKV9911R OWN DAMAGED CLAIM

Our Ref : 18/18/18/VP05/021025

Dear Denise,

Our surveyors had assessed the market value of the vehicle to be in the region of \$59,000.00 to \$62,000.00

Based on the Preliminary Advice, your surveyor had adjusted the repair cost from \$46,105.19 to \$33,246.00 with items of \$4,228.29 to be checked.

As the economical repair limit is \$13,061.00, kindly advise if the vehicle can be repaired to its pre-accident condition.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 18 October, 2018 5:43 PM
To: Admin-D (LKKAuto); GERALD POH WEE BIN; assignments
Cc: MT_Claim_SG; SUR
Subject: RE: OUR REF: SKV9911R OWN DAMAGED CLAIM

Dear Gerald,

Enclosed preliminary revised of vehicle **SKV 9911R**

We have not authorise repair

We are pending repair cost from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : 18/18/18/VP05/021025

Date: 18/10/2018

Our Ref: CS/LPC18018731/R1td3

The Motor Claims Department
LONPAC INSURANCE BHD

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKV 9911R


We thank you for the instruction on 16/10/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/10/2018 at the premises of M/s Trans Eurokars and have the following to report: -

Workshop Estimate Amount	: S\$ 46,105.19
Revised Estimate Amount	: S\$ 33,246.00
"Check" Items Amount	: S\$ 4,228.29
Market Value	: S\$ 60,000.00
LTA Reimbursement Value	: S\$ 46,939.00
Nett Value	: S\$ 13,061.00

Description of Damage:

The vehicle sustained at the front and rear portion.



Comments/ Present Status:

Damage consistent

We recommend uneconomical total loss

We have not authorized repairs.

Yours Faithfully,

Rasul
Automotive Assessor



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 18/18/18/VP05/021025

Date: 18/10/2018

Our Ref: CS/LPC18018731/R1td3

The Motor Claims Department
LONPAC INSURANCE BHD

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKV 9911R.


We thank you for the instruction on 16/10/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/10/2018 at the premises of M/s Trans Eurokars and have the following to report: -

Workshop Estimate Amount	: S\$ 46,105.19
Revised Estimate Amount	: S\$ 33,246.00
"Check" Items Amount	: S\$ 4,228.29
Market Value	: S\$ 60,000.00
LTA Reimbursement Value	: S\$ 46,939.00
Nett Value	: S\$ 13,061.00

Description of Damage:

The vehicle sustained at the front and rear portion.



Comments/ Present Status:

Damage consistent

Pending repair cost from repairer

We have not authorized repairs.

Yours Faithfully,
Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/10/2018 12:25
Date Of Accident	12/10/2018 19:20
Exact Location Of Accident	PIE TOWARDS CHANGI (ENG NEO AVE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV9911R
Insured/Policyholder	
Name Of Registered Owner	ROLAND LEE CHYE TECK
NRIC No	S1382547E
Email Address	ROLANDLEE@NCHOIL.COM.SG
Mobile Phone No	(LOCAL) +65-98394909
Alternative Phone No	OFFICE-98394909

Vehicle Particulars

Manufacturer	MAZDA
Model	3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05019576
Cover Note Number	

Driver

Name of Driver	CHONG JENNY ISABEL
NRIC No	S1356145A
Date Of Birth	02/08/1959
Occupation	INDOOR
Date Of Driving Pass	30/01/1985
Driving Experience	33 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97331338
Fax Number	
Contact Number	
Email Address	ISAJENNCH@GMAIL.COM

Address	307 KEW CRESCENT
Postcode	S465942
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CALEB JORDAN LEE YUNG
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEHICLE C SUDDENLY BRAKE, I ALSO BRAKE. SUDDENLY I FELT A VERY HARD IMPACT FROM MY REAR WHICH CAUSE MY VEHICLE TO MOVE FORWARD AND HIT VEHICLE C. AFTER THE ACCIDENT THEN I REALIZED THAT IT'S A 6 VEHICLE CHAIN COLLISION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP9334B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	REBECCA
NRIC/Passport Number	S8540027D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKB3972R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLJ4807T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLG3171R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SHC8239R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHONG JENNY ISABEL

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



Vehicle B - SLP 9334B.
 Vehicle C - SKB3972R
 Vehicle D - SLJ480TT
 Vehicle E - SL63171R.
 Vehicle F - SHC8239R

fact

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle C suddenly brake. ~~Felt a very hard~~
 I also brake suddenly felt a very hard impact
 from my rear which cause my vehicle to move
 forward and hit vehicle C.
 After the accident then i realized that it's a
 6 vehicle chain collision.

fact

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2547E

Vehicle Particulars

Vehicle No.: SKV9911R
Vehicle to be Exported: No
Intended Deregistration Date: 18 Oct 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: P520286532
Chassis No.: JM6BM42A8G0311324
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$16,686.00
Original Registration Date: 18 Aug 2015
First Registration Date: 18 Aug 2015
Transfer Count: 0
Actual ARF Paid: \$11,686.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Aug 2025
PARF Rebate Amount: \$8,764.00

Intended COE Rebate Details

COE Expiry Date: 17 Aug 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,889.00
COE Rebate Amount: \$38,175.00
Total Rebate Amount: \$46,939.00

The information contained herein is correct as at 18 Oct 2018

OK

60,000
46,939

13,061



LONPAC INSURANCE BHD (S98FC5635C)

Incorporated in Malaysia

Singapore Office: 700, Beach Road at The Concourse, Singapore 189558

Tel: +65 6251 7310 Fax: +65 6249 3787 Website: www.lonpac.com.sg

GST Reg No: P04005625-C

MX1

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP. 189) REPUBLIC OF SINGAPORE.
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1980 (REPUBLIC OF SINGAPORE).
ROAD TRANSPORT ACT 1987 (MALAYSIA).
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1969 (MALAYSIA).

Certificate No. : Z18VP05019576

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

MAZDA 3 1.5
- SKV9911R

2. Name of Policy Holder

ROLAND LEE CHYE TECK

3. Effective Date of the Commencement of Insurance
for the purpose of the Act

18/08/2018

4. Date of Expiry of the Insurance

17/08/2019

5. Persons or Classes of Persons entitled to drive

(A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so
permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT
COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS
(OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE
MOTOR TRADE.

Excess : S\$ 0.00 (SECTION 1) INSURED / NAMED DRIVERS

S\$ 1,000.00 (SECTION 1) UNNAMED DRIVERS

S\$ 3,000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS

S\$ 100.00 WINDSCREEN EXCESS

LONPAC'S AUTHORISED WORKSHOPS

Condition : ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS OR DISTRIBUTOR-OWNED MOTOR WORKSHOP


* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and
Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor
Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner : UNITED OVERSEAS BANK LIMITED

CHIEF EXECUTIVE
(Singapore Branch)User ID: MR9ALP0014
Date Issued: 25/07/2018

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1356145A



Name
CHONG JENNY ISABEL

Race
CHINESE

Date of Birth
02-08-1959

Country of Birth
SINGAPORE

Sex
F

REPUBLIC OF SINGAPORE DRIVING LICENCE

S1356145A



CHONG JENNY ISABEL

Exp. Date: 02 Aug 1999

Valid Date: 09 Apr 2000

1000363823K

3604191



NRIC No. S1356145A



Blood Group: O+

Date of issue: 19-01-1994

307 KEN CRESCENT
SINGAPORE 465942

NRIC No: S1356145A

Date: 14-01-1997 No: 2208016


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 30 Jan 1995

NP 429A

Licence No: S1356145A





TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



(TP)

LONPAC INSURANCE BHD		NAME : Mr Lee Chye Teck Roland		WIP : 25482	
100 BEACH ROAD		ADDRESS : 307 Kew Crescent		EXCESS :	
#19-00, SHAW TOWER		Singapore 465942		DATE: 15-Oct-18	
SINGAPORE 189702		TEL : 98394909			
ATTN : MOTOR CLAIMS					
FAX :					
VEH NO :	SKV9911R	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BM42A8G0311324	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3	DATE REG.:	18-Aug-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	FRONT BUMPER DE ✓	1	MBHR3-50-031BBB		\$ 1,031.70
2	RETAINER LHS na ✓	1	MBHN1-50-0U1E		\$ 18.70
3	RETAINER RHS na ✓	1	MBHN1-50-0T1F		\$ 18.70
4	BRACKET LHS na ✓	1	MBHN1-50-162		\$ 15.10
5	BRACKET RHS na ✓	1	MBHN1-50-152		\$ 15.10
6	COVER LHS, FRONT BUMPER X	1	MBHN1-50-102		\$ 28.00
7	COVER RHS, FRONT BUMPER na ✓	1	MBHN1-50-101		\$ 28.00
8	CHROME LHS, FOGLAMP X	1	MBJE1-50-C22		\$ 106.10
9	CHROME RHS, FOGLAMP na ✓	1	MBJE1-50-C12		\$ 106.70
10	COVER LHS, FOGLAMP X	1	MBJE1-50-C21A		\$ 46.40
11	COVER RHS, FOGLAMP na ✓	1	MBJE1-50-C11A		\$ 46.40
12	LAMP RHS, SIDE TURN ?	1	MB45A-51-350A		\$ 157.30
13	FOGLAMP RHS ?	1	MTK21-51-680A		\$ 351.40
14	BRACKET RHS, FOGLAMP ?	1	MBHR1-51-684A		\$ 17.30
15	TOWING COVER X	1	MBHN1-50-A11 BB		\$ 28.60
16	FRONT REINFORCEMENT na ✓	1	MB45A-50-070A		\$ 444.50
17	STIFF'A', FRONT BUMPER DE ✓	1	MBHN1-50-0S0B		\$ 83.70
18	CLIP, FRONT BUMPER na ✓	12	MC274-50-133		\$ 42.00
19	FASTENER, FRONT BUMPER na ✓	2	MB45A-56-146A		\$ 5.60
20	GROMMET, FRONT BUMPER na ✓	2	MGHP9-50-0Z5		\$ 5.40
21	GRILLE TOP DE ✓	1	MBHN1-50-033 S1		\$ 335.00
22	RIVET, GRILLE TOP na ✓	6	MS51S-51-833		\$ 22.80
23	RIVET, GRILLE TOP na ✓	4	MTK21-50-355		\$ 34.80
24	BRACKET TOP, GRILLE ?	1	MBHN1-50-717D		\$ 102.40
25	FASTENER, GRILLE ?	8	MGD7A-50-EA1		\$ 24.00
26	MASCOT, FRONT na ✓	1	MC235-51-731A		\$ 44.20
27	CHROME LHS CRA ✓	1	MBHN1-50-7K1A		\$ 176.70
28	CHROME RHS CRA ✓	1	MBHN1-50-7J1A		\$ 176.70
29	FRONT GRILLE CRS ✓	1	MBJE1-50-712B		\$ 581.60
30	BRACKET LHS, FRONT GRILLE DE ✓	1	MBHN1-50-163		\$ 15.10

31	BRACKET RHS, FRONT GRILLE	DE ✓	1	MBHN1-50-153	\$	15.10
32	PIN LOCATOR, FRONT GRILLE	NE ✓	2	MKD45-50-1K5A	\$	5.40
33	GROMMET, FRONT GRILLE	NE ✓	2	MKD45-50-ES1	\$	5.40
34	RIVET, FRONT GRILLE	NE ✓	2	MEA01-50-037	\$	15.20
35	COVER RHS, HEADLAMP WASHER	MIS ✓	1	MBHT4-51-8G1 51	\$	85.10
36	ACTUATOR RHS, HEADLAMP WASHER	CRA ✓	1	MBHT4-51-82X	\$	242.40
37	CLAMP, ACTUATOR	NE ✓	1	MTK33-51-829	\$	16.40
38	FRONT PANEL UPPER	PH ✓	1	MB45A-53-150	\$	110.60
39	STAY LOCK	PH ✓	1	MB45A-52-15Y	\$	38.80
40	FRONT SUPPORT PANEL	PH ✓	1	MGHR5-53-110B	\$	469.70
41	PLATE SEAL LHS	X	1	MBHN1-50-1V1A	\$	35.60
42	PLATE SEAL RHS	CRA ✓	1	MBHN1-50-1U1A	\$	35.60
43	FASTENER, PLATE SEAL	NE ✓	4	MKD45-50-EA1	\$	10.00
44	PLATE SET, FRONT REINFORCEMENT	CRA ✓	1	MBHN3-50-1C0	\$	92.70
45	FASTENER, PLATE SET	NE ✓	4	MGD7A-50-EA1	\$	12.00
46	BONNET	PH ✓	1	MBHY0-52-31XA	\$	1,067.30
47	HINGE LHS, BONNET	PH X	1	MB45A-52-420A	\$	41.00
48	HINGE RHS, BONNET	PH X	1	MB45A-52-410A	\$	41.00
49	WEATHERSTRIP BONNET	NE ✓	1	MBHN9-56-770A	\$	63.60
50	PROTECTOR, BONNET LOCK	X	1	MKD53-56-627	\$	10.80
51	LOCK BONNET	PH ✓	1	MB45C-56-620A	\$	197.10
52	CONDENSER	PH ✓	1	MGHR1-61-480B	\$	1,063.00
53	RING, 'O'	NE ✓	1	MGJ6A-61-J19	\$	10.50
54	RING, 'O'	NE ✓	1	MGJ6E-61-J19	\$	6.70
55	RADIATOR	?	1	MPE20-15-200	\$	1,064.90
56	RUBBER TOP MOUNT, RADIATOR	?	2	MPE01-15-242	\$	73.40
57	BRACKET TOP, RADIATOR	?	2	MPE01-15-241	\$	20.60
58	FAN COWLING ASSY	?	1	MPE20-15-025	\$	1,356.80
59	WASHER TANK	DE ✓	1	MGHP9-67-481A	\$	104.00
60	AIR DUCT	DE ✓	1	MP501-13-200	\$	92.70
61	COVER, AIRCLEANER	?	1	MP501-13-3AX	\$	75.40
62	CASE, AIRCLEANER	?	1	MP501-13-3AY	\$	79.70
63	RUBBER MOUNTING, LOWER CASE	?	2	MPE01-13-363	\$	28.00
64	RESONANCE, AIRCLEANER	?	1	MP56F-13-195	\$	70.80
65	CLIP, RESONANCE	?	2	MBGV4-56-145	\$	5.40
66	SPARE TANK, RADIATOR	?	1	MPE01-15-351A	\$	65.80
67	HEADLAMP LHS	CRA ✓	1	MBHT6-51-041A	\$	2,245.00
68	HEADLAMP RHS	CRA ✓	1	MBHT6-51-031A	\$	2,245.00
69	HID CONTROL UNIT	?	1	MBHN3-51-0H3	\$	895.50
70	GASKET, CONTROL UNIT	?	1	MC236-51-0B2	\$	13.60
71	CLIP, HEADLAMP	NE ✓	4	MFB01-50-133C	\$	15.20
72	REAR BUMPER	DE ✓	1	MBPD8-50-221ABB	\$	1,074.80
73	BRACKET CENTER, REAR BUMPER	NE ✓	1	MKD53-50-251	\$	5.10
74	BRACKET LWR LHS, REAR BUMPER	NE ✓	1	MBHR2-50-251A	\$	23.70
75	TOWING COVER LHS	CRA ✓	1	MBHN1-50-EL1 BB	\$	15.70
76	TOWING COVER RHS	MIS ✓	1	MBHN1-50-EK1 BB	\$	16.20
77	REFLECTOR RHS	X	1	MD350-51-5M0E	\$	50.40

78	REAR REINFORCEMENT	BA /	1	MB45A-50-260		\$ 537.30
79	RETAINER, SENSOR	na /	4	MKD47-67-UCSA51		\$ 69.20
80	SENSOR, ULTRASONIC	na /	2 prc /	MKD47-67-UC1 51	38780	\$ 775.60
81	TAPE PROTECTOR, SENSOR	na /	3	MGS1D-50-EM1A		\$ 24.30
82	CLIP, REAR BUMPER	na /	2	MGJ21-50-049		\$ 6.40
83	FASTENER, REAR BUMPER	na /	4	MB45A-56-146A		\$ 11.20
84	RIVET, REAR BUMPER	na /	4	MBBM4-50-355		\$ 16.80
85	GROMMET, REAR BUMPER	na /	2	M9991-00-501		\$ 5.60
86	GROMMET, REAR BUMPER	na /	4	MBHN1-50-0Z1A		\$ 10.00
87	REAR END PANEL	repair	1	MB4YA-70-75Z		\$ 505.10
88	TRIM, END PANEL	?	1	MBHN1-68-89XA		\$ 85.10
89	BOOTLID	BA /	1	MBHY2-52-61XA		\$ 957.40
90	WEATHERSTRIP BOOT LID	na /	1	MBHN1-56-951A		\$ 107.70
91	LOCK, BOOTLID	?	1	MBHY1-56-82XA		\$ 177.30
92	STRIKER, BOOTLID	?	1	MGG2A-56-840		\$ 33.40
93	ORNAMENT, MAZDA	na /	1	MBHN1-51-721		\$ 53.40
94	MASCOT, REAR	na /	1	MBHN1-51-730		\$ 74.40
95	ORNAMENT, SKYACTIVE	na /	1	MBHN1-51-771		\$ 63.60
96	GASKET LHS, BOOTLID LAMP	na /	1	MB45A-51-3J8		\$ 20.90
97	GASKET RHS, BOOTLID LAMP	na /	1	MB45A-51-3H8		\$ 20.90
98	GASKET LHS, TAILLAMP	na /	1	MBHN1-51-163		\$ 20.90
99	GASKET RHS, TAILLAMP	na /	1	MBHN1-51-153		\$ 20.90
100	DASHBOARD	TBR /	1	MB45A-60-350 02		\$ 1,429.10
101	PASSENGER AIRBAG	ACT /	1	MBHS2-57-K50A		\$ 1,130.00
102	BRACKET, AIRBAG	na /	2	MBHN1-60-A11		\$ 19.40
103	SPACER SET, DASHBOARD	na /	1	MBHN1-55-180A		\$ 88.40
104	TAPE CUSHION, DASHBOARD	na /	2	MBHN1-55-161		\$ 39.20
105	TAPE SEAL, DASHBOARD	na /	1	MB45C-55-162		\$ 2.30
106	CORD SHORT, AIRBAG	na /	3	MBHS2-67-SH1		\$ 223.20
107	DRIVER AIRBAG	ACT /	1	MKD45-57-K00C02		\$ 1,466.00
108	SPRING CLOCK, AIRBAG	ACT /	1	MKD49-66-CS0A		\$ 484.40
109	CONTROL UNIT, AIRBAG	ACT /	1	MBRE7-57-K30A		\$ 1,190.90
110	SENSOR IMPACT, AIRBAG	ACT /	1	MG46C-57-K1XA		\$ 130.10
111	RIVET, HEADLAMP	na /	2	MB092-51-833		\$ 6.60
112	SEATBELT LHS	ACT /	1	MB716-57-L90A02		\$ 1,023.10
113	SEATBELT RHS	ACT /	1	MBHV6-57-L30B02		\$ 1,023.10
114	BUCKLE LHS	na /	1	MKD45-57-620B		\$ 102.30
115	BUCKLE RHS	na / } photo	1	MKDY5-57-680B		\$ 106.20
116	ADJUSTER, SHOULDER	X	2	MKD45-57-960B75		\$ 170.20
26	RADIATOR COOLANT	na /	5			\$ 68.50
TOTAL PARTS						\$ 29,739.10
LESS 10%						\$ 2,973.91
TOTAL PARTS COST						\$ 26,765.19
Labour Description						

1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET. TO REPAIR FRONT FENDER LH, FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	1980	\$ 3,960.00
2	MZ-SP-SFRT06	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, BONNET, FRONT FENDER LH AND FRONT FENDER RH.	3150	\$ 3,780.00
3	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1980	\$ 3,960.00
4	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	2205	\$ 2,646.00
5	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.		\$ 660.00
6	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	330	\$ 660.00
7	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	330	\$ 660.00
9	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT	\$ 70.00
10	MZ-BR-TRIM52	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	330	\$ 990.00
11	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
13	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
14	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
15	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	\$ 120.00
16	MZ-BR-SUNDRI	SUNDRIES.	NETT 50	\$ 100.00

TOTAL LABOUR	\$ -	\$ 19,340.00
TOTAL PARTS	\$ -	\$ 26,765.19
TOTAL	\$ -	\$ 46,105.19
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED

TRANS EUROKARS PTE LTD

WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

Rasul

Hp 900100 68

16 days

9/P

17/10/18 @ 1510

EXCESS: NIL

REVERT

Resy by print

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date: