

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

AXA

LKK

17/10

After 11am

Not withain

Resurvey Bepain 1-B.1

12/10/2018

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH -1.8A - SMC7922Z

1pc	front RH door
2pcs	front RH door glass frame sticker @\$131.35
1pc	front RH door inner rubber
1pc	front RH door inner lock
1pc	rear RH door
2pcs	rear RH door glass frame sticker @\$141.45
1pc	rear RH door inner rubber
1pc	rear RH door inner lock front

By	\$ 1,712.25	✓
me	\$ 262.70	✓
Sh	\$ 274.45	X
n	\$ 561.60	X
Red/warp	\$ 1,217.85	✓
me	\$ 282.90	✓
Sh	\$ 581.90	X
n	\$ 591.25	X

\$ 5,484.90

\$ 1,371.23

\$ 4,113.68

less 25%

remove & refit front & rear door glass
wiring
tuffkote
spray painting
labour charges
Total

\$ 120.00	✓
\$ 150.00	2ol
\$ 150.00	6ol
\$ 800.00	7ool
\$ 800.00	4ool
\$ 6,133.68	4ool



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: