

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCA 818 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER DEFORMATION ELEMENT BRACKET-RH <i>mp</i>	\$ 43.00	+
22	FRONT FENDER BRACE-RH <i>New Part.</i>	\$ 103.00	+ 82.40
23	FRONT WHEEL HOUSING LINER-RH <i>torn</i>	\$ 209.00	✓ 167.00
24	WHEEL HOUSING LINER ATTACHEMENT PARTS <i>New</i>	\$ 78.00	? 62
24	FRONT WHEEL SPOILER-RH <i>crushed</i>	\$ 63.00	✓ 50.16
25	FRONT WHEEL SPOILER END PLATE-RH <i>New</i>	\$ 31.00	? X
26	STONE CHIP GUARD <i>not New</i>	\$ 44.00	- X
27	FRONT FENDER LEDGE COVER-RH <i>New</i>	\$ 27.00	? X
28	FRONT FENDER LEDGE COVER PROTECTON FILM-RH <i>New</i>	\$ 20.00	? 15.36
29	LED HEADLIGHT-RH <i>crushed.</i>	\$ 6,973.00	✓ 5578.40
30	LED HEADLIGHT POWER MODULE-RH <i>New</i>	\$ 695.00	+
31	LED HEADLIGHT CONTROL UNIT-RH	\$ 657.00	+
32	LED HEADLIGHT LIFT CYLINDER-RH <i>Long.</i>	\$ 184.00	? 147.20
33	FRONT NO. PLATE <i>New</i>	S/N \$ 25.00	+
34	SUNDRIES <i>New</i>	\$ 300.00	? 13.92
TOTAL SPARE PARTS CHARGES		:	\$ 14,986.00
TOTAL LABOUR CHARGES		:	\$ 4,152.00
GRAND TOTAL		:	\$ 19,138.00

19,885.93

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 16/10/18. ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1164/2018/GW 12-Nov-18 James 1 SCA 818 S Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>LABORS</u>			
1	To carry out paint protection. (Supplied by Owner)	\$ 747.93	
TOTAL		\$ 747.93	

For Premium Automobiles Pte Ltd

Adrian Ling
S/S

Authorised Signature

Claims

From: Aaron Goh [aarongjh@hotmail.com]
Sent: Thursday, 18 October 2018 6:35 PM
To: claims@premiumauto.com.sg
Subject: Attn: James Receipt / Tax Invoice for Aaron SCA818S

Hi James,

Please see forwarded email below.

Thank you!

From: EA Detailer <no-reply@vendhq.com>
Sent: Thursday, June 30, 2016 7:39 PM
To: aarongjh@hotmail.com
Subject: Receipt / Tax Invoice

Making the REAL Difference

Aaron Goh

Receipt / Tax Invoice

Invoice #: 1643 Thu, 30 Jun '16 7:39 pm Served by: Victor Tang On register: Siglap

-1 Discount		- \$382.00	- \$382.00
1 DiamondBrite Paint Protection			\$850.00
1 NanoGlass Ultra Windscreen Coating			\$180.00
1 Special Request Rims Coating			\$0.00
4 Prepayment: DiamondBrite Conservation Program		- \$88.00	\$352.00
Subtotal	\$1,000.00		
Tax (No Tax)	\$0.00		
TOTAL	\$1,000.00		
Credit Card	\$1,000.00		
TO PAY	\$0.00		

You are the heart of our operations
Nothing is more important than delighting you.
Feel free to engage us anytime at enquiry@eadetailer.com

Sent to you by vendhq.com

EA DETAILER PTE LTD

EA DETAILER PTE LTD

Attn: Mr Aaron Goh
Blk 431 Ang Mo Kio Ave 10 #08-1463
Singapore 560431

Quotation: AG-EAD20181116

Date: 16-Nov-18

Date	Items	Unit	Unit Price	Total
16-Nov-2018	Reference: Audi A4 SCA818S			
	1 Ceraz Nano membrane - 3 Layering Application - Paintwork Refining - Sedan Category Range - Audi A4 SCA818S	1	\$1,213.02	\$1,214.02
	2 Special Discount	1	-\$794.46	-\$794.46

Total Payable Amount \$747.93

This is a computer generated form, no signature is required

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 20 November 2018 9:33 AM
To: 'Claims'; SUR
Subject: RE: Supplementary for SCA 818 S
Attachments: IMG.pdf

Dear James,

Refer attached marking.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 19 November 2018 6:44 PM
To: SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: Supplementary for SCA 818 S

Dear All,

Kindly refer to the above attached.

Above supplementary, please pass to Adrian for marking and revert back to us.

Thanks.

Best Regards,

James Tan

Claims Advisor

Premium Automobiles Pte Ltd (Reg No. 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1164/2018/GW
Date	:	15-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

5 days - ok - jb - 10 Jan 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Aaron Goh Jin Hao (Wu RenHao)
Address	:	Apt Blk 431 Ang Mo Kio Avenue 10 Singapore 560431
Telephone	:	HP +65 90227055
Type of Claim	:	Own Damage Claims
Policy No.	:	2100472595-02
Vehicle No	:	SCA 818 S
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	Jun-16
Engine No	:	CVN 009457
Chassis No	:	WAUZZZF45GA074222
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	12-Oct-18
Place of Accident	:	Car park Under Blk 432 Ang Mo Kio Ave 10

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SCA 818 S

S/n	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness ofr headlights, horns, outside temperature sensor and healdight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper,rhs front fender and rhs headlight.Re-organise front crash management components.Reinstall all parts removed.	\$ 2,100.00	\$ 1,250.00
3	To respray front bumper,rhs front fender.	\$ 1,500.00	\$ 1,100.00
4	<i>Added labour - by owner</i>	\$ 747.93	\$ 747.93
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,899.93	\$ 3,649.93

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCA 818 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 245.00	
3	SECURING STRIP	\$ 30.00	
4	FRONT BUMPER GRILLE-CENTER	\$ 171.00	
5	FRONT BUMPER CLOSING ELEMENT	\$ 180.00	
6	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	
7	RADIATOR GRILLE	\$ 972.00	
8	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 118.00	\$ 94.00
9	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	\$ 25.36
10	FOAM FILLER PIECE	\$ 107.00	
11	FRONT BUMPER CARRIER	\$ 702.00	
12	FRONT BUMPER COVER	\$ 109.00	
13	SIGN "CAUTION"	\$ 12.00	
14	STICKER FOR AIR CONDITIONER	\$ 7.00	
15	FRONT BUMPER SUPPORT-RH	\$ 24.00	
16	LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
17	FRONT FEDER-RH	\$ 665.00	\$ 532.00
18	FRONT FENDER ATTACHMENT PARTS-RH	\$ 45.00	
19	FRONT FENDER CLOSING ELEMENT-RH	\$ 44.00	\$ 34.56
20	FRONT FENDER BRACKET-RH	\$ 31.00	\$ 24.16
	SUB TOTAL SPARE PARTS CHARGES	\$ 5,534.00	\$ 2,283.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCA 818 S

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	2,283.28
21	FRONT FENDER DEFORMATION ELEMENT BRACKET-RH	\$	43.00	
22	FRONT FENDER BRACE-RH	\$	103.00	\$ 82.40
23	FRONT WHEEL HOUSING LINER-RH	\$	209.00	\$ 167.20
24	WHEEL HOUSING LINER ATTACHEMENT PARTS	\$	78.00	\$ 62.00
24	FRONT WHEEL SPOILER-RH	\$	63.00	\$ 50.16
25	FRONT WHEEL SPOILER END PLATE-RH	\$	31.00	
26	STONE CHIP GUARD	\$	44.00	
27	FRONT FENDER LEDGE COVER-RH	\$	27.00	
28	FRONT FENDER LEDGE COVER PROTECTON FILM-RH	\$	20.00	\$ 15.36
29	LED HEADLIGHT-RH	\$	6,973.00	\$ 5,578.40
30	LED HEADLIGHT POWER MODULE-RH	\$	695.00	
31	LED HEADLIGHT CONTROL UNIT-RH	\$	657.00	
32	LED HEADLIGHT LIFT CYLINDER-RH	\$	184.00	\$ 147.20
33	FRONT NO. PLATE	S/N \$	25.00	
34	SUNDRIES	\$	300.00	\$ 13.92
	TOTAL SPARE PARTS CHARGES	:	\$ 14,986.00	\$ 8,399.92
	TOTAL LABOUR CHARGES	:	\$ 4,899.93	\$ 3,649.93
	GRAND TOTAL	:	\$ 19,885.93	\$ 12,049.85

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1164/2018/GW
12-Nov-18
James
1
SCA 818 S
Audi A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
LABORS			
1	To carry out paint protection. (Supplied by Owner)	\$ 747.93	\$ 747.93
TOTAL		\$ 747.93	\$ 747.93

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 1 February 2019 5:31 PM
To: 'Boo seng yak'; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SCA818S - OD AIG - SURVEYED 16 OCT 18

Dear Mr Boo,

Confirm repair cost of \$12,049.85 before GST @ 5 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, 10 January 2019 4:52 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SCA818S - OD AIG - SURVEYED 16 OCT 18

hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$12,049.85 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SCA 818 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1164/2018/MAS

23 Feb 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SCA 818 S, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SCA 818 S**, claimant, **Mr. Aaron Goh Jin Hao**, please find the related document per attached.

1. A copy of the Original invoice no. 85013460 – S\$12,893.34
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SCA 818 S

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408628
Telephone 6384 1888
Telefax 6384 1888

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

Page 1 17:40

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013460
Date : 15/02/2019
Order : SCA0818S
Term : 30

Account: A0005 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SCA0818S (V 29750)

Regn Date: 29/06/2016

Mileage: 46572

WIP No.: 28530

Model: A4 SEDAN 1.4 TFSI S tronic

Chassis: WAUZZZF45GA074222

Engine: CVN 009457

Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	OTHERS	M: TO CARRY OUT PAINT PROTECTION (BY OWNER)	747.93	1.00	747.93
X	ABW0941774A	HEADLIGHT Less 020%	1.00	5973.00	5,578.40
X	ABW0821172A	WHEEL HOUS Less 020%	1.00	209.00	167.20
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone: 6388 2223
Main Telefax: 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408608
Telephone: 6388 2223

Customer Service

Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2323

9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 17:40

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013450 Date: 15/02/2019 Order: SCA0818S Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SCA0818S (V 29750) Regn Date: 29/06/2016 Mileage: 46572 WIP No.: 28530
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF45GA074222 Engine: CVN 009457 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	ABW0853888A	SPOILER	Less 020%	1.00	62.70
X	ABW0821106A	FENDER	Less 020%	1.00	665.00
X	ABW0807771	BRACKET	Less 020%	1.00	117.50
X	ABW0807065C GRU	COVER	Less 020%	1.00	1849.00
X	ABW0898629	ATT. PARTS	Less 020%	1.00	77.50
X	ABW0821460	BRACKET	Less 020%	1.00	30.20
X	ABW0807284	GUIDE	Less 020%	1.00	31.70
X	ABW0821092	PLATE	Less 020%	1.00	43.20
X	ABW0821136C	SUPPORT	Less 020%	1.00	103.00
X	ABW0823746	COVER	Less 020%	1.00	19.20
X	ABW0807682B 989	GRILLE	Less 020%	1.00	117.50
X	ABW0955102A	CYLINDER	Less 020%	1.00	184.00
X	AN 0161857	POP-RIVET	Less 020%	6.00	2.90

Parts 8,399.92
Labour 747.93
Sublet 2,902.00
Menus 0.00
Lubricant 0.00

Sub-Total 12,049.85

7% GST 843.49

Grand Total 12,893.34

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SCA 0818 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1164/2018/JW
12 Nov 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZF45GA074222
Vehicle Regn No. : SCA 0818 S
Vehicle Mileage : 45758 KM
Vehicle Owner : Mr. Aaron Goh Jin Hao (Wu RenHao)
Certificate No : 2100472595-02
Policy Excess : Waived
Accident Date : 12th October 2018
Place : Carpark Under Blk 432 Ang Mo Kio Ave 10
Repair Cost : \$ 12,893.34
WIP No. : 28530
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 0700pm
Date : 12.11.18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Pending for Survey Report
Main	16 Oct 2018 16:25		16 Oct 2018 14:32 Edit Adj Rpt	S\$12,049.85 Edit Estimates	S\$12,049.85 View Rpt		Cancel Case

Main		Reference	Claim Details	Documents	Show All
------	--	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: **AARON GOH JIN HAO (WU RENHAO)**, ID: S8725486J, Tel: +6590227055, Email: AARONGOH@HOTMAIL.COM

Vehicle Reg. No.: **SCA818S**

Claim Type: **OD / 7730996898SG**

Date of Loss: 12/10/2018 18:00 - :59
[27 Months and 13 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.: (Comprehensive)

Excess: S\$0.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Loo, Tong Shing**] TongShing.Loo@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 25/10/2018]**

Driver/Custodian: **AARON GOH JIN HAO (WU RENHAO)** (31 / Male), NRIC: S8725486J, Tel: +6590227055 Email: AARONGOH@HOTMAIL.COM

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (18/10/2018): Alert - Adj Mandate Approved (S\$13100.00) - SCA818S - Claim Handler: Loo, Tong S...
- AIG_SG (17/10/2018): SCA818S / OD / 12/10/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCA818S (7730996898SG)
OD

Oct 12 2018 6:50PM
[AARON GOH JIN HAO (WU RENHAO)]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▼

1 per page ▼ ☒

Assessment Reports			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Load HTM
1	16/10/18 16:44	Adjuster Immediate Advice		

3 per page ▼ ☒

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Load JPG ☒
1	16/10/18 16:26	General View		Load JPG ☒
2	16/10/18 16:26	General View		Load JPG ☒
3	16/10/18 16:26	General View		Load JPG ☒
4	16/10/18 16:26	General View		Load JPG ☒
5	16/10/18 16:26	General View		Load JPG ☒
6	16/10/18 16:26	General View		Load JPG ☒
7	16/10/18 16:26	General View		Load JPG ☒
8	16/10/18 16:26	General View		Load JPG ☒
9	16/10/18 16:26	General View		Load JPG ☒
10	16/10/18 16:26	General View		Load JPG ☒
11	16/10/18 16:26	General View		Load JPG ☒
12	16/10/18 16:26	General View		Load JPG ☒
13	16/10/18 16:26	General View		Load JPG ☒
14	16/10/18 16:26	General View		Load JPG ☒
15	16/10/18 16:26	General View		Load JPG ☒
16	16/10/18 16:26	General View		Load JPG ☒
17	16/10/18 16:26	General View		Load JPG ☒
18	16/10/18 16:26	General View		Load JPG ☒
19	16/10/18 16:26	General View		Load JPG ☒
20	16/10/18 16:26	General View		Load JPG ☒
21	16/10/18 16:26	General View		Load JPG ☒
22	16/10/18 16:26	General View		Load JPG ☒
23	01/02/19 16:20	Reinspection Photo		Load JPG ☒
24	01/02/19 16:20	Reinspection Photo		Load JPG ☒
25	01/02/19 16:20	Reinspection Photo		Load JPG ☒
26	01/02/19 16:20	Reinspection Photo		Load JPG ☒
27	01/02/19 16:20	Reinspection Photo		Load JPG ☒
28	01/02/19 16:20	Reinspection Photo		Load JPG ☒
29	01/02/19 16:20	Reinspection Photo		Load JPG ☒
30	01/02/19 16:20	Reinspection Photo		Load JPG ☒
31	01/02/19 16:20	Reinspection Photo		Load JPG ☒
32	01/02/19 16:20	Reinspection Photo		Load JPG ☒
33	01/02/19 16:20	Reinspection Photo		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	01/02/19 16:20	Reinspection Photo		Load JPG ☒
35	01/02/19 16:20	Reinspection Photo		Load JPG ☒
36	01/02/19 16:20	Reinspection Photo		Load JPG ☒
37	01/02/19 16:20	Reinspection Photo		Load JPG ☒
38	01/02/19 16:20	Reinspection Photo		Load JPG ☒
39	01/02/19 16:20	Reinspection Photo		Load JPG ☒
40	01/02/19 16:20	Reinspection Photo		Load JPG ☒
41	01/02/19 16:20	Reinspection Photo		Load JPG ☒
42	01/02/19 16:20	Reinspection Photo		Load JPG ☒
43	01/02/19 16:20	Reinspection Photo		Load JPG ☒
44	01/02/19 16:20	Reinspection Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/18 16:45	Singapore Accident Statement		Load PDF
2	16/10/18 16:46	Certificate of Insurance		Load PDF
3	16/10/18 16:46	Insured's Driving License		Load PDF
4	16/10/18 16:46	MARK ESTIMATE		Load PDF
5	01/03/19 09:41	DISCHARGE VOUCHER		Load PDF
6	01/03/19 09:41	SUPPLEMENTARY		Load PDF
7	01/03/19 09:41	WORKSHOP INVOICE		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/18 15:10	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/18 15:02	Accident Photo		Load JPG ☒
2	13/10/18 15:02	Accident Photo		Load JPG ☒
3	13/10/18 15:02	Accident Photo		Load JPG ☒
4	13/10/18 15:02	Accident Photo		Load JPG ☒
5	13/10/18 15:02	Accident Photo		Load JPG ☒
6	13/10/18 15:02	Accident Photo		Load JPG ☒
7	13/10/18 15:02	Accident Photo		Load JPG ☒
8	13/10/18 15:02	Accident Photo		Load JPG ☒
9	13/10/18 15:02	Accident Photo		Load JPG ☒
10	13/10/18 15:02	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/18 14:52	Sketch Plan		Load JPG ☒
2	13/10/18 14:52	Sketch Plan #2		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset Save Print

3/1/2019

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18018743/AVBS2
Date: 01/03/2019

REFERENCE

Insured/Claimant: AARON GOH JIN HAO (WU RENHAO)
Date of Loss: 12/10/2018

Policy No:
Nature of Claim: OD Claim No: 7730996898SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCA818S
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)
Reg. Date: 29/06/2016 (Man. Year: 2016)
Colour: White
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): Market Value/New Car Price

Engine No: CVN009457
Chassis No: WAUZZZF45GA074222
Odometer: 45170 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):
Handbrake (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Yes
No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18
Front Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm

Rear Tyre Size: 245/40R18
Rear Left Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,986.00	8,399.92	6,586.08	43.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,899.93	3,649.93	1,250.00	25.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,885.93	12,049.85	7,836.08	39.41
+ GST 7.00/7.00% (S\$)	1,392.02	843.49	548.53	39.41
Nett Amount (S\$)	21,277.95	12,893.34	8,384.61	39.41

INSPECTION

Date of Assignment: 16/10/2018

Date Inspected: 16/10/2018

Estimated Period of Repair: 5.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/1/2019

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Not Necessary	245.00 FS	*- FS
3	1		*SECURING STRIP	Not Necessary	30.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	171.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	73.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	972.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cracked	118.00 FS	*94.00 FS
9	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	32.00 FS	*25.36 FS
10	1		*FOAM FILLER PIECE	Not Necessary	107.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Not Necessary	702.00 FS	*- FS
12	1		*FRONT BUMPER COVER	Not Necessary	109.00 FS	*- FS
13	1		*SIGN CAUTION	Not Necessary	12.00 FS	*- FS
14	1		*STICKER FOR AIR CONDITIONER	Not Necessary	7.00 FS	*- FS
15	1		*FRONT BUMPER SUPPORT - RH	Not Necessary	24.00 FS	*- FS
16	1		*LOCK CARRIER BRACKET	Damaged	118.00 FS	*94.00 FS
17	1		*FRONT FENDER - RH	Dented	665.00 FS	*532.00 FS
18	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	45.00 FS	*- FS
19	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	44.00 FS	*34.56 FS
20	1		*FRONT FENDER BRACKET - RH	Damaged	31.00 FS	*24.16 FS
21	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	43.00 FS	*- FS
22	1		*FRONT FENDER BRACE - RH	Bent	103.00 FS	*82.40 FS
23	1		*FRONT WHEEL HOUSING LINER - RH	Torn	209.00 FS	*167.20 FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	78.00 FS	*62.00 FS
25	1		*FRONT WHEEL SPOILER - RH	Cracked	63.00 FS	*50.16 FS
26	1		*FRONT WHEEL SPOILER END PLATE - RH	Not Necessary	31.00 FS	*- FS
27	1		*STONE CHIP GUARD	Not Necessary	44.00 FS	*- FS
28	1		*FRONT FENDER LEDGE COVER - RH	Not Necessary	27.00 FS	*- FS
29	1		*FRONT FENDER LEDGE COVER PROTECTOR FILM - RH	Necessary	20.00 FS	*15.36 FS
30	1		*LED HEADLIGHT - RH	Cracked	6,973.00 FS	*5,578.40 FS
31	1		*LED HEADLIGHT POWER MODULE - RH	Not Necessary	695.00 FS	*- FS
32	1		*LED HEADLIGHT CONTROL UNIT - RH	Not Necessary	657.00 FS	*- FS
33	1		*LED HEADLIGHT LIFT CYLINDER - RH	Damaged	184.00 FS	*147.20 FS
34	1		*FRONT NO. PLATE	Not Necessary	25.00 FS	*- FS
35	1		*SUNDRIES	Necessary	300.00 FS	*13.92 FS
Total Parts (S\$)					14,986.00	8,399.92

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER.	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
5	TO CARRY OUT PAINT PROTECTION.	New	747.93	747.93
Gross Labour Cost (S\$)			4,899.93	3,649.93

Report was unsubmitted during this print-out.

< END OF ESTIMATES >