

ASS. REC. BY:

REF:

CS/AGZ18018757/KTB<sup>n2</sup>

Special Instruction:

Surveyor

Kohmet.

## ASSIGNMENT (Office)

From (Person): Albert Hung of AGZ Date/Time: 16-10-2018 1:40pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 740X Insured: SKW 279Lat Workshop m/s Tions (ch) Tel: 6387 6666of No. 2 Amk St 63Policy No: \_\_\_\_\_ Claim No: C10002127

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 13-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: \_\_\_\_\_Date/Time: 16-10-2018 1:40pm Person Contacted: Arunda Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHF 740X - x
	SKW 279L - x

ASS. REC. BY:

REF:

AGZ/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

65 days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

17/10 File pass to Catherine

B 11098.25 (Red: 35344.51, 76%)

RECEIVED 13 OCT 2018

Date/Time, File Pass to?

1) 10/10 Typist

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.L (\$ 11098.25

TP

450

Veh No:

S/HF 740X Yr Regn: 06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Latitude c.c. 1.985

Colour:

M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading

320157 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL 15AUC 282 718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: KIT / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

13/10/18

D.O.I.

16/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

**Catherine Chong (LKK Auto)**

---

**From:** Albert Hong <albert.hong@budgetdirect.com.sg>  
**Sent:** Tuesday, 16 October, 2018 1:40 PM  
**To:** 'assignments'  
**Cc:** 'SUR'  
**Subject:** Appoint LKK to conduct TP survey; Our Ref: C10002127  
**Attachments:** image004.wmz; img-X16110246.pdf

Hi Team,

Please accept survey assignment and liaise with TP workshop.

Regards,

**Albert Hong**  
**Senior Executive, Claims**

T +65 6540 2182  
F +65 6725 0853  
E [albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)

**Budget  
Direct**  
insurance

**Customer Care:** +65 6221 2111  
**Claims:** +65 6221 2199  
**Claims (Int.):** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

---

**From:** Amanda Tay <amanda.tay@transcab.com.sg>  
**Sent:** Tuesday, 16 October, 2018 11:13 AM  
**To:** Julie Mangubat <julie.m@budgetdirect.com.sg>; Lincoln Yeo <lincoln.yeo@budgetdirect.com.sg>; Albert Hong <albert.hong@budgetdirect.com.sg>  
**Cc:** 'Candy Kong' <candy.kong@transcab.com.sg>  
**Subject:** Arrange for survey for SHF740X

Dear all,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SKW279L - 13.10.2018 at 1330Hrs – SHF740X

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

*Thks & Rdgs*  
*Amanda Tay*  
*Claims Service Assistant*



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHF740X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002975
Chassis No.:	VF1ABL15AUC282718
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2024
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	29 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$26,505.00
<b>Total Rebate Amount:</b>	<b>\$41,503.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/10/2018 09:45
Date Of Accident	13/10/2018 13:30
Exact Location Of Accident	CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF740X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TOH TECK GUAN @ SOH TECK HUAT
NRIC No	S1445748H
Date Of Birth	15/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	28/11/1979
Driving Experience	38 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96658677
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 147 YISHUN STREET 11 #06-69
Postcode	760147
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TOH GEOK HAY GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 13.10.2018 at about 1330 hours, I was stationary on the fourth lane along CTE when Vehicle in front of me made a stop and so I followed suit. Moment later while stationary. Suddenly I felt an impact. Vehicle B (SKW279L) hit onto my taxi's rear portion. I alighted to check and realised I was engaged in a chain collision accident involving Vehicle B and Vehicle C (SGQ5915E).

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW279L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KATHLEEN LIM BENG LING
NRIC/Passport Number	S6906341A
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGQ5915E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAY YONG CHIN
NRIC/Passport Number	S6831114D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TOH TECK GUAN @ SOH TECK HUAT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHF740X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Amanda  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

plc see the attach G1A report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Amanda

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 740X****AAD1810-158***Not Authorized**Resumy B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHF 740X**

VF1ABL15AUC282718

RENAULT

LATITUDE

13.10.2018

**AUTO & GENERAL**

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bz</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Bz</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>D.Y</i> 113.47 ✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>D.Y</i> 135.97 ✓
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61 ✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bz</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bz</i> 225.95 ✓
13	1 BOOT REAR	\$	<i>Bz</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>AM</i> 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>AM</i> 493.35 ✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>AM</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>AM</i> 225.36 ✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45 } X
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81

**Trans-cab Auto Services Pte Ltd****AAD1810-158**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 740X**

30	1 FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	X
31	1 WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i>	671.45	X
33	1 FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	X
34	1 WHEELARCH REAR RH	\$	<i>Sn</i>	543.47	X
35	1 TAILLAMP RH	\$	<i>mgim</i>	552.55	✓
36	1 TAILLAMP PANEL RH	\$	<i>R</i>	986.70	X
37	1 TAILLAMP LH	\$	<i>Sn</i>	552.55	X
38	1 TAILLAMP PANEL LH	\$	<i>R</i>	986.70	X
39	1 OUTER PANEL REAR (End Panel)	\$	<i>B</i>	1,471.77	✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>nn</i>	404.56	—
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	X
42	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21	X
43	1 EXHAUST REAR	\$	<i>R</i>	7,489.05	X
44	1 EXHAUST CAP REAR	\$	<i>R</i>	230.49	X

<b>TOTAL</b>	<b>\$</b>	<b>35,197.49</b>
<b>10%</b>	<b>\$</b>	<b>3,519.75</b>
	<b>\$</b>	<b>31,677.74</b>

**Special Nett**

1	1SET PARKING AID	\$	<i>shot</i>	700.00	<i>Goan</i>
2	1SET REAR BUMPER CLIP	\$	<i>nn</i>	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>nn</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>nn</i>	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>nn</i>	30.00	—
13	1 BOOT STICKER "6555-3333"	\$	<i>nn</i>	30.00	—
14	1 BOOT INNER TRIM CLIP	\$	<i>nn</i>	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i>	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	X

**Trans-cab Auto Services Pte Ltd****AAD1810-158**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 740X**

18	1 FENDER INNER TRIM CLIP LH	\$	nn 28.00 X
19	1 TAILLAMP CLIP RH	\$	nn 5.00 ✓
20	1 TAILLAMP CLIP LH	\$	nn 5.00 X
21	2 REAR WINDSCREEN SELANT	\$	nn 80.00 X
22	1 WINDSCREEN MOULDING	\$	nn 100.00 X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00 X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn 385.00 X
25	1 SPARE TYRE	\$	sn 330.00 X

**TOTAL \$ 2,225.02****TOTAL PARTS \$ 33,902.76****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 6000
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 6000
To Rust-Proofing Of The Affected Areas.	\$	170.00 600
To reinstall rear bumper parking sensor.	\$	170.00 600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 600
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 600
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X

## Trans-cab Auto Services Pte Ltd

AAD1810-158

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 740X

To supply and re-do rear luggage floor panel insulation padding.

\$ ~ 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ ~ 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ ~ 170.00 X

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ ~ 380.00 X

**TOTAL \$ 12,540.00**

**Over All Total \$ 46,442.76**

46822.74

**(LUMP SUM)**

**Repair Days**

~~20 DAYS~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18018757/Ktbn2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 23-10-2018



Code : AGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 279L	Veh. Inspected	SHF 740X
Policy No.		Coverage (\$)	0.00
Claim No.	C10002127	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	16/10/2018

## 2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC282718	Colour	METALLIC WHITE / RED
Odometer	320157	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
----------------------------------------------------------------------------

## 5. General Information

Accident Date	13/10/2018	Inspection Date	16/10/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 740X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	BENT	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	DISTORTED	135.97	135.97
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	BENT	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	CUT	323.05	323.05
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	DENTED	493.35	493.35
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-

Report Ref No. CS/AGI18018757/Ktbn2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	DENTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,519.75	-974.25
			31,677.72	8,768.25
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-

Report Ref No. CS/AGI18018757/Ktbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TRYE (SN)	SERVICEABLE	330.00	-
			2,225.02	830.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,FENDER PANEL REAR LH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR AND EXHAUST CAP REAR.		4,200.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST..	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/AGI18018757/Ktbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	1,500.00
	<b>GRAND TOTAL</b>		<b>46,822.74</b>	<b>11,098.25</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>11,098.25</b>

Report Ref No. CS/AGI18018757/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.