

杰 汽車修理服務中心
ZENITH DANIEL AUTO SERVICES

Blk 1009 Bukit Merah Lane 3 #01-96 S(159723)
HP: 9737 2883 / Off: 9232 9816 E: daniel9633@hotmail.co.uk

Mailing Address: Blk 507 Ang Mo Kio Ave 8 #08-2706 S(560507)

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way, #07-16
Singapore 079120
Tel: 6419 3000 / FAX: 68357416

Dear Sir,

Replacement of parts

1. Rear boot lid	bt \$1073.00
2. Rear boot lid lamp (RH)	at \$710.00
3. Tail lamp (RH)	wa \$788.00
4. Rear bumper	ce \$688.00
5. Rear lower bumper	at \$347.00
6. Rear bumper reflector (RH)	at \$99.00
7. Rear bumper inforcement	ce \$313.00
8. Rear end panel	phot ? \$274.00
9. KIA emblem	ce \$37.00
10. CERATO emblem	ce \$35.00
11. K3 emblem	ce \$30.00
12. C&C emblem	ce \$20.00

Total: \$4414.00

Less 20%: \$882.80

Total: \$3531.20

LABOUR CHARGES

1. I/O remove rear end damaged parts, pull out, cut off, replace rear end panel and re-fix all new parts & re-align.	✓ \$600.00
2. I/O respray rear boot lid, rear end panel, rear bumper and all affected area.	700 \$700.00
3. I/O to remove supply and replace reverse sensor	200 \$200.00

Grand Total: \$5031.20

QUOTATION

NO.: QZD0107

VEHICLE NO.: SLM2370A

VEHICLE MODEL: KIA CERATO K3

DATE OF ACCIDENT: 6/10/18

YOUR REF: SKQ914T

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Daniel Tan 9737 2883

Tanpin 9249 5249
up
16/10/18 @ 1700
5 days
Resurvey after repair
sur@lkkauto.com