

INSURANCE

INS. CASE OWNER:

CC 4/AIG1801

8760, 6/10/18

LRK:

IDAC:

Surveyor:

862

DOI:

ASSIGNMENT

16/10/18

Date / Time:

15/10/18

Registered in Merime:

16/10/18

Pre-assign / CCU / FTE

SLJ 32205



Insured Vehicle No.:

MOHAMMAD SUFFIAN BIN SAKET

Claim No.:

28875642259

Name of Insured:

Policy No.:

21004975-01

Insured Tel No.:

HP:

9025606

Make / Model:

WISSAM

Excess Sec II :SS

D.O.A.:

14/10/18

Place of Accident:

PLE TMS TRAS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VTC YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLJ 32205



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

AT.  
WSP.



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

11/11/18  
WISSAM

SLJ 32205

SLJ 32205

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call 01

As call 1st to 01

15/11/19  
WISSAM

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to 01

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOJA S/N No.:

27

If NO or B 28, Ass, Lia:

Repair Cost:

SS 2300.00

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

500.00

(S 100 x 5 days)

Loss of Income (LOI):

SS

(S x days)

LOR only LOU only

LOU only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

Legal Cost:

SS

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

2807.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2807.45

Name 1:

AT Auto Consultant

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

11/10/19

TP

\$320

Guo Guo

REF:

ML7

C1002C

# ASSIGNMENT

(-2023)

From: \_\_\_\_\_ Date: 16-10-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJG 3267Y  
at Workshop m/s: AT Auto Consultant  
of: Blk 75m Ming Ind Est #01-82

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Alan - 8386 8989

(Policy Condition)

after 106m



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$32k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJG 3267Y Yr Regn: 26 Jun 2008

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda stream c.c 1799

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 194933 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/508R17  
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 16-10-18

Survey held at: w/s 2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/1 - \$2300 (Red \$3628.83 / 61%)

Date/Time: File Pass to?

☐ : Prell. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

2)

Transportation

Add Fee: ☐ Site Insp (\$

\$ + RS \$

☐ Interview (\$

Photos

☐ Tech Invs (\$

Others

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18018760/Gwb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 16-10-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 3220S	Veh. Inspected	SJG 3267Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/10/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	14/10/2018	Inspection Date	16/10/2018
Survey held at	A T AUTO CONSULTANT 113 TECK WHYE LANE #05-650 SINGAPORE 680113		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113  
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com  
Co. Reg. No. : 53368526E

Date of Estimate: 15.10.2018  
Vehicle No: SJG3267Y  
Owner: City Limo Pte Ltd  
Date of Accident: 14.10.2018  
Make & Model: Honda Stream RSZ  
Chassis No : RN6-1063996

## ESTIMATE FOR ACCIDENT VEHICLE NO SJG3267Y

### LABOUR

- 1) Panel beating for replace and repair affected parts
- 2) Spray painting on accident areas
- 3) Wiring charges
- 4) Remove/refix reverse sensor
- 5) Remove/refix reverse camera
- 5) Transfer tailgate glass
- 6) Transfer tailgate component
- 7) Remove/refix rear exhaust
- 8) Apply undercoating to above affected areas

SUB TOTAL (LABOUR)

400 \$800.00  
500 \$800.00  
NN x \$100.00  
40 \$80.00  
40 \$80.00  
140 \$150.00  
NN 60 \$150.00  
x \$100.00  
60 \$120.00  
\$2,380.00

### PARTS

- 1) 1 Tailgate / Buc (New local photos)
- 2) 1 Tailgate inner trim X
- 3) 1 Tailgate lock X
- 4) 1 Tailgate striker X
- 5) 1 Tailgate outer moulding X
- 6) 1 Tailgate number plate light R
- 7) 3 Tailgate windscreen moulding
- 8) 1 Tailgate weatherstrip X
- 9) 1 Tailgate emblem X
- 10) 1 Rear bumper RSZ Sports
- 11) 2 Rear bumper side retainer LH/RH X
- 12) 2 Rear bumper lower bracket X
- 13) 1 Rear end panel X
- 14) 1 Rear end panel top garnish X
- 15) 2 Taillamp LH/RH X
- 16) 1 Rear exhaust silencer X
- 17) 1 Rear exhaust mounting X

SUB TOTAL

LESS 20 %

DISCOUNTED SUB TOTAL

903 \$1,379.00  
\$456.30  
\$485.20  
\$98.00  
\$389.00  
@ \$35.00 ✓ \$70.00  
@ \$82.50 118 \$247.50  
\$210.40  
\$68.50  
688.9 \$1,023.00  
@ \$41.00 \$82.00  
@ \$35.20 \$70.40  
\$828.00  
\$367.90  
@ \$635.70 \$1,271.40  
\$780.50  
\$78.00  
1813.4  
\$7,905.10  
\$1,976.28  
\$5,928.83

### S. NETT ITEM

- 1) 1set Rear bumper clips / MC
- 2) 3 Rear end panel top garnish clips X
- 3) 1set Reverse sensor X
- 4) 1set Reverse camera
- 5) 1 Tailgate windscreen sealant / MC

SUB TOTAL

LESS 0 %

DISCOUNTED SUB TOTAL

30 \$50.00  
@ \$5.00 \$15.00  
\$280.00  
200 \$350.00  
50 \$100.00  
\$795.00  
\$0.00  
\$795.00

SUB TOTAL (S.NETT)

SUB TOTAL (PARTS)

\$795.00

\$5,928.83

- Pre repair inspection request - SJG3267Y VS SLJ3220S (OI) DOA 14/10/2018

From: Azlan, Syazairdina  
To: admin-a@ikkauto.com, assignments@ikkauto.com  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marisa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweerjeetkaur; Chan, Yoke Shi; Kaur, Baljit  
Sent: Monday, 15 October, 2018 1:52:53 PM  
Attachments: [image.jpg](#); [DOA/AG.pdf](#)

Hi,

Please refer to the enclosed request from A T AUTO CONSULTANT.

Claim no : 38835643325G003  
Case Owner : CHIT YAN FOO

If you have any queries/concerns, please let us know.  
Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thanks and regards,

Syazairdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations / AIG Shared Services

From: Tan Alan (mailto:atautoconsultant@gmail.com)  
Sent: Monday, October 15, 2018 1:52 PM  
To: Azlan, Syazairdina  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marisa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweerjeetkaur; Chan, Yoke Shi; Kaur, Baljit  
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ3220S AND SJG3267Y ON 14/10/2018

Hi all,

We are agreeable to select LKK Cin Guo Qiang as the SJE for the above mentioned case. Thank you.

Rgds  
Alan  
83868989

On Mon, 15 Oct 2018, 10:06 Azlan, Syazairdina, <Syazairdina.Azlan@aig.com> wrote:



Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email by error or are unsure if you have received this email, please notify the sender of this error. Please do not copy, retransmit, disseminate, or otherwise use this information.

Secured by PGP/Email Encryption, Copyright © 2004-2007 PGP/Email, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina Azlan@aig.com  
To: ataautoconsultant@gmail.com  
Cc: Andy-SY Fong@aig.com; Lee-Ying Chin@aig.com; NoorMarisa.AbuKassim@aig.com; imran.ishak@aig.com; ShengYang.Lim@aig.com; Aashweerjeetkaur.Mithoosingh@aig.com; yokeshi.chan@aig.com; Baljit.Kaur@aig.com  
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ3220S AND SJG3267Y ON 14/10/2018  
Date: Mon, 15 Oct 2018 02:06:35 +0000  
Without Prejudice

Your Reference : SJG3267Y

15-10-2018 @ 2:19pm  
Alan veh not in

Our Reference : SLJ3220S

Dear Sir/Madam,

We refer to your Notice of Accident of even date

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SIG Claims Operations | AIG Shared Services

From: Lim, Sheng Yang  
Sent: Monday, October 15, 2018 8:20 AM  
To: Azlan, Syazairdina  
Subject: FW: ACCIDENT INVOLVING YOUR INSURED VEHICLE SLJ3220S & SJG3267Y ALONG PIE TOWARDS TUAS ON 14.10.18

From: Tan Alan [mailto:atautoconsultant@gmail.com]  
Sent: Sunday, October 14, 2018 10:00 PM  
To: Supramaniam, Darshene; Fong, Andy-SY; Lim, Sheng Yang  
Subject: ACCIDENT INVOLVING YOUR INSURED VEHICLE SLJ3220S & SJG3267Y ALONG PIE TOWARDS TUAS ON 14.10.18

Dear Sir,

attached herewith the Notification Of Accident for your reference.

Kindly let us have a list of your ten surveyors as your nominated SJE for our consideration within the stipulated timeline under the NIMA Protocol.

**\*\*Vehicle will be arranged at Blok 7 Sin Ming Industrial Estate Sector C #01-82\*\***

Thank you

Rgds  
Alan Tan  
83868989  
A T Auto Consultant

# A T AUTO CONSULTANT

BLK 113 Teck Whye Lane #05-650 Singapore 680113

TEL: 8386 8989

Co. Regn. No. 53368526E

25<sup>th</sup> September 2019

Our Ref: AT190139/SJG3267Y

Your Ref: SLJ3220S

## Motor Claims Department

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 Chartis Building

Singapore 079120

Dear Sirs,

### **ACCIDENT INVOLVING SLJ3220S / SJG3267Y ON 14.10.2018**

We are the representative for **CITY LIMO PTE LTD**, whose vehicle registration number **SJG3267Y** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration **SLJ3220S**. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

Cost of repairs	\$ 2300.00 (as agreed with your Single Joint Expert)
Loss of use 05 days @\$100.00	\$ 500.00 (including 1 day of PRI)
LTA search fee	\$ 7.45
	<u>\$ 2807.45</u>

Enclosed are the supporting documents for your perusal:-

GIA

LTA search

Repair bill

Kindly let us have your payment of **\$2807.45** in our workshop's name within the next 14 days.

Please do not hesitate to contact our Mr Tan at 8386 8989 or email [atautoconsultant@gmail.com](mailto:atautoconsultant@gmail.com) should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Encl.





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18018760/Gwb3

16 May 2019

**Mohamad Suffian Bin Salleh**  
**Blk 145 Toa Payoh Lor 2**  
**#04-300**  
**Singapore 310145**

Dear Sir/Madam,

**ACCIDENT INVOLVING SLJ 3220S AND SJQ 3267Y ON 14/10/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



LETTER OF AUTHORITY

We/I, City Limo Pte Ltd ("the third party claimant") of UEN/NRIC No. 207611002C, owner of vehicle Reg.No SJ6 3267Y hereby authorize M/s A 1 Auto Consultant ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use and/or survey fee ("claim") for my vehicle no. SJ6 3267Y that was damaged pursuant to the accident which occurred on 14/10/2018 along P1E Towards Tuas involving vehicle no/s SJ2 J3220S ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 15 of Oct 20 18



  
Signed by the third party claimant

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, AT AUTO CONSULTANT ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,300.00 (Repair Cost), S\$500.00 (Loss of Use/Rental), S\$7.45 (Disbursement) for vehicle no. SJG 3267Y that was damaged pursuant to the accident which occurred on 14/10/2018 (date) along PIE TOWARDS TUAS (BEFORE TOH GUAN EXIT) (location) involving vehicle no/s SLJ 3220S. This is pursuant to the inspection conducted on 16/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CITY LIMO PTE LTD ("the third party claimant") of vehicle no. SJG 3267Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJG 3267Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28 (day) of 09 (month) 2019 (year)



X4Q

Signed by appointed surveyor



Signed by "the workshop" (with chop)

This Discharge Voucher applies strictly for claimant's claim for property damages only and does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and /or his driver and

# A T AUTO CONSULTANT

Reg No: 53368526E

Block 113 Teck Whye Lane #05-550 Singapore 680113 Tel: 8388 8989 Email:atautoconsultant@gmail.com

M/S : CITY LIMO PTE LTD

Date : 25/09/2019

Tax Invoice No.: AT190139

Vehicle No : SJG3267Y

Accident Date : 14/10/2018

## PARTS & LABOUR

Lump Sum Repair	\$2300.00
-----------------	-----------

TOTAL	\$2300.00
-------	-----------

Thank you for your support. Kindly arrange for payment as soon as possible. All cheque must be crossed and marked A/C Payee Only and made payable to A T AUTO CONSULTANT.

For A T AUTO CONSULTANT



A handwritten signature in black ink, appearing to be "R. S. Tan".

Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 14 Oct 2018 / 21:36:12

Receipt Date/Time : 14 Oct 2018 / 21:35:59

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-181014-000821

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLJ3220S				
As at 14 Oct 2018/18:30:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLJ3220S			
	Enquiry Fee	7.00	0.49	7.49
	20181014213505892966			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
	<b>Paid By</b>			
	xxxxxxxxxxxxx2327		Credit Card: Visa /MasterCard	7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING


































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2018 <a href="#">Edit Reg</a>		15 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	MOHAMAD SUFFIAN BIN SALLEH, ID: S7923047B								
Main Claimant:	CITY LIMO PTE LTD, Co. Reg. No.: 201611002C								
Vehicle Reg. No.:	SJG3267Y	Date of Loss:	14/10/2018 00:00 - 159 [123 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 38835643325G	Policy/Cover Note No.:	2100492925 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLJ32205	Policy No. (Claimant):	5104381012						
		Excess:							
Repairer:	A T Auto Consultant (HQ) B/113 Teck Whye Lane, #05-650, 680113 Teck Whye - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/10/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (17/10/2018): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJG3267Y (38835643325G)  
[SLJ3220S]  
TP  
CITY LIMO PTE LTD  
Oct 14 2018 12:00AM  
[MOHAMAD SUFFIAN BIN SALLEH]  
A T Auto Consultant

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <span>View in Browser</span>		
Letters/Correspondences														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown										1	Edit				
Photos/Images														3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
2	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
3	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
4	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
5	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
6	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
7	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
8	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
9	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
10	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
11	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
12	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
13	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
14	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
15	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
16	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
17	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
18	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
19	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
20	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
21	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
22	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
23	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
24	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
25	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
26	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
27	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
28	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
29	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
30	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
31	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
32	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
33	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
34	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
35	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
36	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
37	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
38	26/09/19 09:22	General View										1	Load JPG	<input checked="" type="checkbox"/>			
39	26/09/19 09:24	Odometer Reading										1	Load JPG	<input checked="" type="checkbox"/>			
40	26/09/19 09:24	Chassis Number										1	Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/09/19 09:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/09/19 09:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/09/19 09:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/09/19 09:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/09/19 09:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/09/19 09:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/09/19 09:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/09/19 09:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/09/19 09:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/18 15:27	EMAIL FROM AIG DD 15102018	 Load PDF	
2	16/10/18 15:27	NOTICE	 Load PDF	
3	17/10/18 18:58	TP ESTIMATE- MARKED	 Load PDF	
4	17/10/18 18:58	TP GIA REPORT	 Load PDF	
5	16/10/19 14:14	WORKSHOP INVOICE	 Load PDF	
6	16/10/19 14:14	AUTHORISATION TO ACT FORM	 Load PDF	
7	16/10/19 14:14	Release Voucher	 Load PDF	
8	16/10/19 14:14	LTA SEARCH	 Load PDF	
9	16/10/19 14:14	LOD	 Load PDF	
10	16/10/19 14:14	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/10/18 11:52	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLJ3220S (Insd veh)	Model:	HONDA STREAM 1.7 (A)
	SJG3267Y (TP veh)		
Date of Accident:	14/10/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	9,499.08
Final Repair Cost	:	\$	2,300.00
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,807.45

5.00 days at \$100.00 per day  
days

Is Third Party Workshop GIA Registered?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
	BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	A T Auto Consultant	:	\$ 2,807.45
2)		:	\$
3)		:	\$

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
16 Oct  
2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18018760/GDB3Q2

Date: 16/10/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492925  
 Claimant Vehicle No: SJG3267Y Insured Vehicle No: SLJ3220S  
 Date of Loss: 14/10/2018 Nature of Claim: TP Claim No: 3883564332SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJG3267Y  
 Make & Model: HONDA STREAM, 1.7 (A) Engine No: R18A1771159  
 Reg. Date: 26/06/2008 (Man. Year: 2008) Chassis No: RN61063996  
 Colour: White Odometer: 194933 km  
 Engine Capacity: 1799 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 215/50Z R17 Rear Tyre Size: 215/50Z R17  
 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm  
 Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,119.08	1,730.72	5,388.36	75.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,200.00	1,180.00	49.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,499.08</b>	<b>2,930.72</b>	<b>6,568.36</b>	<b>69.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,499.08</b>	<b>2,300.00</b>	<b>7,199.08</b>	<b>75.79</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,807.45</b>		

## INSPECTION

Date of Assignment: 15/10/2018  
 Date Inspected: 16/10/2018 Inspected At: BLK 7 SIN MING IND EST #01-82  
 Repairer: A T Auto Consultant (HQ)  
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Buckled	1,379.00 FL	*903.00 FL
2	1	*TAILGATE INNER TRIM	Not Necessary	456.30 FL	*- FL
3	1	*TAILGATE LOCK	Not Necessary	485.20 FL	*- FL
4	1	*TAILGATE STRIKER	Not Necessary	98.00 FL	*- FL
5	1	*TAILGATE OUTER MOULDING	Not Necessary	389.00 FL	*- FL
6	2	*TAILGATE NUMBER PLATE LIGHT	Distorted (1 PCS ONLY)	70.00 FL	*35.00 FL
7	1	*TAILGATE WINDSCREEN MOULDING (3 PCS)	Necessary	247.50 FL	*118.00 FL
8	1	*TAILGATE WEATHERSTRIP	Not Necessary	210.40 FL	*- FL
9	1	*TAILGATE EMBLEM	Necessary	68.50 FL	*68.50 FL
10	1	*REAR BUMPER RSZ SPORTS	Deformed	1,023.00 FL	*688.90 FL
11	2	*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	82.00 FL	*- FL
12	2	*REAR BUMPER LOWER BRACKET	Not Necessary	70.40 FL	*- FL
13	1	*REAR END PANEL	Repair	828.00 FL	*- FL
14	1	*REAR END PANEL TOP GARNISH	Not Necessary	367.90 FL	*- FL
15	2	*TAILLAMP LH/RH	Not Necessary	1,271.40 FL	*- FL
16	1	*REAR EXHAUST SILENCER	Repair	780.50 FL	*- FL
17	1	*REAR EXHAUST MOUNTING	Not Necessary	78.00 FL	*- FL
18	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	3	*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	15.00 FS	*- FS
20	1	*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
21	1	*SET REVERSE CAMERA	Necessary	350.00 FS	*200.00 FS
22	1	*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,700.10</b>	<b>2,093.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,581.02</b>	<b>362.68</b>
<b>Total Parts (\$\$)</b>	<b>7,119.08</b>	<b>1,730.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	800.00	400.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	800.00	500.00
3	WIRING CHARGES	New	100.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
5	REMOVE/REFIX REVERSE CAMERA	New	80.00	40.00
6	TRANSFER TAILGATE GLASS	New	150.00	100.00
7	TRANSFER TAILGATE COMPONENT	New	150.00	60.00
8	REMOVER/REFIX REAR EXHAUST	New	100.00	0.00
9	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	120.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,380.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >