

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 15.10.2018
Vehicle No: SJG3267Y
Owner: City Limo Pte Ltd
Date of Accident: 14.10.2018
Make & Model: Honda Stream RSZ
Chassis No : RN6-1063996

ESTIMATE FOR ACCIDENT VEHICLE NO SJG3267Y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's price(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4 Days.
Lump sum repair.
After repair photos
Buc Cup
16/10/18

LABOUR

- 1) Panel beating for replace and repair affected parts
- 2) Spray painting on accident areas
- 3) Wiring charges
- 4) Remove/refix reverse sensor
- 5) Remove/refix reverse camera
- 5) Transfer tailgate glass
- 6) Transfer tailgate component
- 7) Remove/refix rear exhaust
- 8) Apply undercoating to above affected areas

SUB TOTAL (LABOUR)

400	\$800.00
500	\$800.00
X	\$100.00
40	\$80.00
40	\$80.00
140	\$150.00
60	\$150.00
X	\$100.00
60	\$120.00
	\$2,380.00

PARTS

- 1) 1 Tailgate / Buc (New local photos) \$1,379.00
- 2) 1 Tailgate inner trim X \$456.30
- 3) 1 Tailgate lock X \$485.20
- 4) 1 Tailgate striker X \$98.00
- 5) 1 Tailgate outer moulding X \$389.00
- 6) 2 Tailgate number plate light @ \$35.00 \$70.00
- 7) 3 Tailgate windscreen moulding @ \$82.50 \$247.50
- 8) 1 Tailgate weatherstrip X \$210.40
- 9) 1 Tailgate emblem X \$68.50
- 10) 1 Rear bumper RSZ Sports \$1,023.00
- 11) 2 Rear bumper side retainer LH/RH X \$41.00 \$82.00
- 12) 2 Rear bumper lower bracket X \$35.20 \$70.40
- 13) 1 Rear end panel X \$828.00
- 14) 1 Rear end panel top garnish X \$367.90
- 15) 2 Taillamp LH/RH X @ \$635.70 \$1,271.40
- 16) 1 Rear exhaust silencer X \$780.50
- 17) 1 Rear exhaust mounting X \$78.00

SUB TOTAL

LESS 20 %

DISCOUNTED SUB TOTAL

\$7,905.10
\$1,976.28
\$5,928.83

S. NETT ITEM

- 1) 1set Rear bumper clips / MC \$50.00
- 2) 3 Rear end panel top garnish clips X \$5.00 \$15.00
- 3) 1set Reverse sensor X \$280.00
- 4) 1set Reverse camera / MC \$350.00
- 5) 1 Tailgate windscreen sealant / MC \$100.00

SUB TOTAL

LESS 0 %

DISCOUNTED SUB TOTAL

\$795.00
\$0.00
\$795.00

SUB TOTAL (S.NETT)

\$795.00

SUB TOTAL (PARTS)

\$5,928.83