



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MR KWEK JU YANG MARK (GUO ZUYANG MARK) 87 LORONG K TELOK KURAU SINGAPORE 425779	Cust No/Name /MR KWEK JU YANG MARK (GUO ZUYAN) Reg No/Reg Date SKZ4869S / 26/01/2016 Date In/Mileage / 0 Chassis No VF73ABHZTFJ811999 Engine No 10JBHD3020538 Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT Colour/Trim 1SM / 8MF
Contact No Mobile: 92210281	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	15/10/2018/ 12:03	TLC	442 / CocoLu	13832

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR DOOR LH, SIDE SILL LH, REPAIR REAR FENDER LH, REAR BUMPER				3900 4200.00
E PNT88000 REMOVE & INSTALL DOOR TRIMS & GLASS				✓ 240.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				✓ 120.00
M SUNDRY TRANSFER RIM TO TYRE				✓ 30.00
E PNT98000 SPRAY PAINT FOR SIDE SILL LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER				✓ 2100.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40 80.00
M SUNDRY Sundry				✓ 20.00
M REAR DOOR LH ASS	1.00	1361.00	0.00	bt 1361.00
M REAR DOOR SEAL LH	1.00	193.00	0.00	ne 193.00
M SEALING PANEL LH	1.00	106.00	0.00	ner 106.00
M DECOR STRIP LH	1.00	146.00	0.00	ner 146.00
M DOOR FIXINGS	1.00	219.00	0.00	ner 219.00
M SIDE WINDOW LH	1.00	251.00	0.00	ne 251.00
M WINDOW LIFTER LH	1.00	550.00	0.00	? 550.00
M UNDER-BODY LH	1.00	847.00	0.00	bt 847.00
M ALLOY WHEEL 6.5 J16 CH5-47	1.00	571.00	0.00	out 571.00

SURVEYOR NAME: TanpinSURVEYOR SIGNATURE: TanpinDATE: 23/10/18REMARKS: Resurvey before paint
su@lkhands.com
10 days.

Confirm & accepted by

Parts	4,244.00
Labour	6,660.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	130.00
Total (w/o GST)	11,034.00

Authorized signatory and company stamp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Validity of this estimate is 14 days from date of quotation. This is subject to confirmation of document, no signature is required.

Estimated costs quoted are excluding GST. We would inform you that we have a limited liability on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally, worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date: