



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2013 VOLKSWAGEN GOLF 2.0 GTI (SKN5353U)
Date of Loss	12 October 2018
Time of Loss	15.00
Loss Description	SKN5353U (INSD) HIT REAR OF SKS8534T (TP)
Comment	

Workshop Details

Total Rebate Amount	69856
Nett Loss Amount	\$13,144.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	169



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SKN5353U

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

29/10/2013



Mileage

64312

Age of Vehicle

4

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2013

2013

Make

VOLKSWAGEN

VOLKSWAGEN

Model

GOLF 2.0 GTI

GOLF GTI 2.0 T

Driver Details

CATEGORY

FNOL
INFORMATION

POST SURVEY INFORMATION

Driver Name

Date of Birth

dd/mm/yyyy



Age

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	WWWZZZAUZDW154966	WWWZZZAUZI
Engine No	CHH003356	CHH003356
Engine Capacity		1984
Sum Insured	0	0
Market Value	0	83000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation		
Education Qualification		
Driving Experience		
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address		
Address type		

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender		
Marital status		
Identification #		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

17/10/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/40R18

Rear Tyre Size

225/40R18

Front left side

GOODYEAR7mm

Rear left side

GOODYEAR7mm

Front right side

GOODYEAR7mm

Rear right side

GOODYEAR7mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐		1	1			FRT NO PLATE BRKT (WCP) (10%)			Bent	66				66	Reviewing	
☐		2	1			FRONT BUMPER COVER (WCP) (10%)			Buckled	506				506	Reviewing	
☐		3	1			FRT CTR COWL GRILLE (WCP) (10%)			Cracked	82.5				82.5	Reviewing	
☐		4	1			L/F INNER SENSOR			Serviceable	0	0	0	0	0	Deny	
☐		5	1			R/F INNER SENSOR			Serviceable	0	0	0	0	0	Deny	
☐		6	1			L/F CTR SENSOR BRKT			Repair	0	0	0	0	0	Deny	
☐		7	1			R/F CTR SENSOR BRKT			Repair	0	0	0	0	0	Deny	
☐		8	1			L/F OUT SENSOR BRKT (WCP) (10%)			Cracked	27.5				27.5	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPL/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		9	1			R/F OUT SENSOR BRKT (WCP) (10%)			Cracked	27.5				27.5	Reviewing	
		10	1			L/F INN SENSOR BRKT (WCP) (10%)			Necessary	27.5				27.5	Reviewing	
		11	1			R/F INN SENSOR BRKT (WCP) (10%)			Necessary	27.5				27.5	Reviewing	
		12	1			L/F BUMPER GUIDE (WCP) (10%)			Damaged	33				33	Reviewing	
		13	1			FRONT GUIDE (WCP) (10%)			Cracked	60.5				60.5	Reviewing	
		14	1			R/F BUMPER GUIDE (WCP) (10%)			Damaged	33				33	Reviewing	
		15	1			FRT BUMPER C-MEMBER			Repair	0	0	0	0	0	Deny	
		16	1			FRT BUMPER SUPPORT (WCP) (10%)			Cracked	297				297	Reviewing	
		17	1			PLASTIC PRIMER			Serviceable	0	0	0	0	0	Deny	
		18	1			APPLICATOR			Serviceable	0	0	0	0	0	Deny	
		19	1			2-COMP ADHESIVE SENS			Serviceable	0	0	0	0	0	Deny	
		20	1			GRILLE (WCP) (10%)			Cracked	308				308	Reviewing	
		21	1			BONNET (WCP) (10%)			Buckled	539				539	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		22	1			LEFT BONNET HINGE (WCP) (10%)			Damaged	71.5				71.5	Reviewing	
		23	1			RIGHT BONNET HINGE (WCP) (10%)			Damaged	71.5				71.5	Reviewing	
		24	1			BONNET INSULATOR			Serviceable	0	0	0	0	0	Deny	
		25	1			LOWER LOCK			Repair	0	0	0	0	0	Deny	
		26	1			SAFETY LATCH (WCP) (10%)			Damaged	66				66	Reviewing	
		27	1			BONNET GAS STRUT			Serviceable	0	0	0	0	0	Deny	
		28	1			BONNET REL CABLE (WCP) (10%)			Damaged	71.5				71.5	Reviewing	
		29	1			BONNET SEAL			Serviceable	0	0	0	0	0	Deny	
		30	1			L/F COVER SEAL			Serviceable	0	0	0	0	0	Deny	
		31	1			R/F COVER SEAL			Serviceable	0	0	0	0	0	Deny	
		32	1			LEFT HEADLAMP ASSY (WCP) (10%)			Cracked	979				979	Reviewing	
		33	1			RIGHT HEADLAMP ASSY (WCP) (10%)			Cracked	979				979	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE *
		34	1			L/F WING (WCP) (10%)			Bent	368.5				368.5	Reviewing	
		35	1			R/F WING (WCP) (10%)			Buckled	368.5				368.5	Reviewing	
		36	2			L/F NUT			Serviceable	0	0	0	0	0	Deny	
		37	2			R/F NUT			Serviceable	0	0	0	0	0	Deny	
		38	1			L/F WING BADGE			Serviceable	0	0	0	0	0	Deny	
		39	1			R/F WING BADGE			Serviceable	0	0	0	0	0	Deny	
		40	1			FRT LOCK CARRIER (WCP) (10%)			Cracked	539				539	Reviewing	
		41	1			L/HEADLAMP MOUNTING			Serviceable	0	0	0	0	0	Deny	
		42	1			R/HEADLAMP MOUNTING			Serviceable	0	0	0	0	0	Deny	
		43	1			L/CTR INN H-LAMP BRK			Repair	0	0	0	0	0	Deny	
		44	1			R/CTR INN H-LAMP BRK			Repair	0	0	0	0	0	Deny	
		45	1			L/LOCK CARRIER STRUT (WCP) (10%)			Buckled	66				66	Reviewing	
		46	1			R/LOCK CARRIER STRUT (WCP) (10%)			Buckled	66				66	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		47	1			LOCK CARRIER SUPPORT			Serviceable	0	0	0	0	0	Deny	
		48	1			L/F WATER DEFLECTOR			Serviceable	0	0	0	0	0	Deny	
		49	1			R/F WATER DEFLECTOR (WCP) (10%)			Damaged	55				55	Reviewing	
		50	1			CONDENSER			Serviceable	0	0	0	0	0	Deny	
		51	1			RADIATOR			Serviceable	0	0	0	0	0	Deny	
		52	1			FAN SHROUD			Serviceable	0	0	0	0	0	Deny	
		53	1			L/ELECTRIC FAN			Serviceable	0	0	0	0	0	Deny	
		54	1			INTERCOOLER			Serviceable	0	0	0	0	0	Deny	
		55	1			TOWING CVR			Serviceable	0	0	0	0	0	Deny	
		56	4			PARKING SENSOR SEAL			Serviceable	0	0	0	0	0	Deny	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		PANEL / MECHANICAL	639	0	0	Reviewing		
		2		PAINTWORK	634.5	0	0	Reviewing		
		3		CORR PROT INTERNAL 5 WU	22.5	0	0	Reviewing		
		4		PAINT / MATERIAL COSTS	254.41	0	0	Reviewing		



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 6
DAYS

Reviewing



2

FRT
NUMBER
PLATE

Reviewing

35

DENTED



3

RAD
COOLANT

Reviewing

20

NECESSARY



4

AIRCON
GAS

Reviewing

50

NECESSARY





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$7,391.91

Claim Amount

\$7,391.91

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$5,736.50

\$5,736.50

Labour

\$1,550.41

\$1,550.41

Miscellaneous

\$105.00

\$105.00

[Submit for Review](#)