

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

15-Oct-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6007 G

|          |                                |                |    |          |
|----------|--------------------------------|----------------|----|----------|
| 1 pc     | Front bumper emblem            | <del>*</del> ✓ | \$ | 44.00    |
| 1 pc     | Front bumper                   | X report       | \$ | 531.00   |
| 1 pc     | Front bumper n/s side retainer | X              | \$ | 16.00    |
| 1 pc     | Front n/s fender               | ✓              | \$ | 384.00   |
| 1 pc     | Front n/s fender inner shield  | X              | \$ | 120.00   |
| 1 pc     | Front n/s wheel cover          | X report       | \$ | 116.00   |
|          |                                |                | \$ | 1,211.00 |
| Less 10% |                                |                | \$ | 121.10   |
|          |                                |                | \$ | 1,089.90 |

### S/NETT

|                                                                                                                                                   |                                     |   |    |                       |
|---------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|---|----|-----------------------|
| 1 set                                                                                                                                             | Front n/s fender inner shield clips | X | \$ | 28.00                 |
| 1 set                                                                                                                                             | Front bumper clips                  | X | \$ | 48.00                 |
| 1 pc                                                                                                                                              | Front n/s fender sticker            | X | \$ | 30.00                 |
| Sundry                                                                                                                                            |                                     |   | \$ | <del>50.00</del> 20   |
| To check wheel alignment                                                                                                                          |                                     |   | \$ | <del>80.00</del> X    |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.                            |                                     |   | \$ | <del>180.00</del> X   |
| To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc |                                     |   | \$ | <del>550.00</del> 400 |
| To putty and spray painting on front bumper, front n/s fender                                                                                     |                                     |   | \$ | <del>400.00</del> 360 |
| To apply rustproofing on the repaired and replaced panels.                                                                                        |                                     |   | \$ | <del>80.00</del> 20   |
|                                                                                                                                                   |                                     |   | \$ | 2,535.90              |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Kalish IDCKY  
15/10/18 1330 hrs  
3 Days  
Lfs  
After Repair photo