

ASS. REC. BY:

REF: es/MSG18018783/ Usd3 / n² Special Instruction:Survivor
menner

Manus

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time: 16/10/18 @ 2.11pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 3795Y

Insured:

GBA 5772T

at Workshop m/s

Hua Ho Trading

Tel:

6284 4487

of

Blk 6 Defu Lane 10 # 01-540

Policy No:

29094517TMV

Claim No:

573015

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/10/2018

17/10/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

lup

Date/Time: 3:32pm @ 16/10/18

Person Contacted:

Mdm. Tan

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBN 3795Y-X

GBA 5772T-X

19/10/18

@ 15:33 revised IA to Irene Tan Gile Ing via
messenger.

REF: MSIG

ASSIGNMENT

From:

Date:

17/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBN 3795Y

at Workshop m/s

Hua Ho trading

of

31k 6 June 10 # 01-540

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

10k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

131

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (up)

L1A 4181

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBN 3795Y

Y. Regn:

.918

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha SNIPER

C.C.

15-0

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

10th fly

T/Radio:

Insured / Std / NI / NA

Eng/No:

MH3U60740J0120063

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70-90-17

R:

120-70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

IRC

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

6/10/18

D.O.I.

17/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & 1/5 body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Tp owner want everything replace because only 3week bike.

31/10/18 \$ 2218.30 confirmed with MARCUS

31/10/18 Confirmed P/P \$ 2,218.30 @ 4 days with Marcus
(\$ 815.70 Red - 27%)

RECEIVED 01 NOV 2018

Date/Time, File Pass to?

01/11/18



Preli. Report



Final Report

1)

Typist

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

150

Transportation:

10

Add Fee:



Site Insp (\$

) \$ + RS. \$



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

) TOTAL

Report Format:

Lump Sum / I.B.I. (\$) 2,218.30 P/P

160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 19 Oct 2018

Preliminary Advice

Insured Vehicle No	: GBA5772T	Accident Date	: 06/10/2018
TP Vehicle No	: FBN3795Y	Assignment Date	: 16/10/2018
Make	: YAMAHA SNIPER T150	Est. Duration of Repair	: 4 days
Date of Inspection	: 17/10/2018		
Inspection At	: Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C Singapore 539187		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,034.00
Revised Amount	:S\$	1,734.00
Check Items (Estimated)	:S\$	587.70
Total	:S\$	2,321.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		16 Oct 2018 14:11 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HERAEUS MATERIALS SINGAPORE PTE.LTD., Co. Reg. No.: 198501914Z		
Main Claimant:	MUHAMMAD UZAIR BIN KAMAL, ID: S9708681H		
Vehicle Reg. No.:	FBN3795Y	Date of Loss:	06/10/2018 12:00 - :59 [16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 573015	Policy/Cover Note No.:	29094517TMV (Third Party Only) Coverage: 06/09/2018 - 05/03/2019
Vehicle Reg. No. (Insured):	GBA5772T	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C, 539187 Defu Lane - Tel: 62844487		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/10/2018]		
Adj Asg. Remarks:	LIABILITY NOT CLEAR (NON REPORTING) Please appoint KALVIN ANG from LKK AUTO to conduct the survey , Kindly contact the workshop directly @ 6284487		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Bike model

Yamaha MXi T150 Sniper

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▾

Yamaha MXi T150 Sniper (/listing/usedbike/yamaha-yamaha-mxi-t150-sniper/9909/)



(/listing/usedbike/yamaha-yamaha-mxi-t150-sniper/9909/)

SGD \$8500

Reg : 06/02/2017

Type: Cubs

150cc

14000km

First owner. Accident free. Original stock. Interested contact me.

Posted on : 12/10/2018

★ DIRECT SELLER

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-MXI-T150-SNIPER/9909/)

Yamaha MXi T150 Sniper (/listing/usedbike/yamaha-yamaha-mxi-t150-sniper/1907/)



(/listing/usedbike/yamaha-yamaha-mxi-t150-sniper/1907/)

Reg : 13/01/2016

Type: Cubs

150cc

21000km

Selling off my beloved yamaha sniper with rare movistar coverset. Condition: internal 9/10 external 10/10. All stock parts. Fully paid. Finance ur own bank loan if necessary. Transfer fee to b...

Posted on : -

★ DIRECT SELLER

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-MXI-T150-SNIPER/1907/)

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FBN3795Y
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Chassis No.:	MH3UG0740J0120063
Propellant:	Petrol
Engine No.:	G3E6E0423185
Engine Capacity:	150 cc
Maximum Power Output:	-
Maximum Laden Weight:	266 kg
Unladen Weight:	116 kg
Year Of Manufacture:	2018
Original Registration Date:	20 Sep 2018
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
Quota Premium:	\$4,214.00
COE Expiry Date:	19 Sep 2028
Road Tax Expiry Date:	19 Mar 2019
Inspection Due Date:	19 Sep 2021
Intended Transfer Date:	16 Oct 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

[OK](#)

[Print](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8681H
Vehicle Details	
Vehicle No.:	FBN3795Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2018
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G3E6E0423185
Chassis No.:	MH3UG0740J0120063
Maximum Power Output:	-
Open Market Value:	\$2,085.00
Original Registration Date:	20 Sep 2018
First Registration Date:	20 Sep 2018
Transfer Count:	1
Actual ARF Paid:	\$313.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,214.00
COE Rebate Amount:	\$4,181.00
Total Rebate Amount:	\$4,181.00

The information contained herein is correct as at 17 Oct 2018

OK

和 好 貿 易

HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FBN3795Y

p/p #2218.30/-


*not Allowed
the
photo after
repair.
17/10/18*

19/10/18

Items	Price
Rear Mugguard	\$96 <i>DIS ✓</i>
Mugguard Bracket	\$38 <i>3rd ✓</i>
Rear Left Signal Light	\$35 <i>cut ✓</i>
Exhaust Pipe <i>510</i>	\$588 <i>m/del ✓</i>
Exhaust Pipe Rear Protector	\$60 <i>DIS ✓</i>
Rear Foot Rest Bracket Left	\$65 <i>suc X</i>
Rear Foot Rest Bracket Right	\$65 <i>3rd ✓</i>
Rear Number Plate	\$16 <i>3rd 10 S.N</i>
Number Plate Bracket	\$34 <i>3rd ✓</i>
Number Plate Light	\$36 <i>cut ✓</i>
Rear Tyre 120/70/17	\$185 <i>cut 90% 150 90% 135 S.N</i>
Rear Rim	\$190 <i>3rd/moped ✓</i>
Left Side Tail Box	\$210 <i>cut X</i>
Handle Bar End Left	\$32 <i>scr ✓</i>
Handle Bar	\$86 <i>3rd ✓</i>
Main Stand	\$52 <i>2 X</i>
Rear Swing Arm	\$420 <i>3rd/100 ✓</i>
Left Foot Rest Front	\$65 <i>cut ✓</i>
Magnetic Coil Cover <i>215</i>	\$238 <i>cut ✓</i>
Gear Level	\$65 <i>3rd ✓</i>
Tailight Panel	\$48 <i>PA X</i>
Towing Fee	\$60 <i>35</i>
Labour Charge	\$350 <i>250</i>
Total	\$3034

150 90% 135 S.N

WZ



HUA HO TRADING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*p-1987
102
1788.30
S.N 145
labour - 285
2218.30*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18018783/USD3N2

Date: 02/11/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29094517TMV
Claimant Vehicle No :	FBN3795Y	Insured Vehicle No :	GBA5772T
Date of Loss:	06/10/2018	Nature of Claim:	TP
		Claim No:	573015

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN3795Y	Engine No:	G3E6E0423185
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740J0120063
Reg. Date:	20/09/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	120-70-17
Front Left Side:	IRC 8 mm	Rear Left Side:	IRC 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,624.00	1,933.30	690.70	26.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	410.00	285.00	125.00	30.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,034.00	2,218.30	815.70	26.89

INSPECTION

Date of Assignment:	16/10/2018	
Date Inspected:	17/10/2018	Inspected At: Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C Singapore 539187
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Nov 2018)
Parts:	N/A YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN3795Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR MUGGUARD	Distorted	96.00 F	*96.00 FL
2	1		*MUGGUARD BRACKET	Bent	38.00 F	*38.00 FL
3	1		*REAR LEFT SIGNAL LIGHT	Cut	35.00 F	*35.00 FL
4	1		*EXHAUST PIPE	Dented/Bent	588.00 F	*550.00 FL
5	1		*EXHAUST PIPE REAR PROTECTOR	Distorted	60.00 F	*60.00 FL
6	1		*REAR FOOT REST BRACKET LEFT	Serviceable	65.00 F	*- FL
7	1		*REAR FOOT REST BRACKET RIGHT	Bent	65.00 F	*65.00 FL
8	1		*NUMBER PLATE BRACKET	Bent	34.00 F	*34.00 FL
9	1		*NUMBER PLATE LIGHT	Cracked	36.00 F	*36.00 FL
10	1		*REAR RIM	Bent/Warped	190.00 F	*190.00 FL
11	1		*LEFT SIDE TAIL BOX	Repair	210.00 F	*- FL
12	1		*HANDLE BAR END LEFT	Scratched	32.00 F	*32.00 FL
13	1		*HANDLE BAR	Bent	86.00 F	*86.00 FL
14	1		*MAIN STAND	Repair	52.00 F	*- FL
15	1		*REAR SWING ARM	Bent/Dented	420.00 F	*420.00 FL
16	1		*LEFT FOOT REST FRONT	Cut	65.00 F	*65.00 FL
17	1		*MAGNETIC COIL COVER	Cut	238.00 F	*215.00 FL
18	1		*GEAR LEVEL	Bent	65.00 F	*65.00 FL
19	1		*TAILLIGHT PANEL	Not Necessary	48.00 F	*- FL
20	1		*REAR NUMBER PLATE	Bent	16.00 FS	*10.00 FS
21	1		*REAR TYRE 120/70/17 (\$150)(90%)	Cut	185.00 FS	*135.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,624.00	2,132.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	198.70
Total Parts (\$\$)	2,624.00	1,933.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	60.00	35.00
2	LABOUR CHARGE	New	350.00	250.00
Gross Labour Cost (S\$)			410.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >