

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 19 Oct 2018

Preliminary Advice

Insured Vehicle No : GBA5772T

TP Vehicle No : FBN3795Y

Make : YAMAHA SNIPER T150

Date of Inspection : 17/10/2018

Inspection At : Hua Ho Trading (HQ)
Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C
Singapore 539187

Accident Date : 06/10/2018

Assignment Date : 16/10/2018

Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,034.00
Revised Amount	:S\$	1,734.00
Check Items (Estimated)	:S\$	587.70
Total	:S\$	2,321.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.