

REPAIR ESTIMATE\*

VEHICLE NO : SHC 3055L

DATE 15/10/2018 15:01

MAKE :

MODEL : HYUNDAI IONIQ

LKK/Kalvin

pbyP

EQ NS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,227.50
	Front Bumper Cover X 14-2			\$ 418.30
	Front Bumper Moulding (LH) ✓			\$ 93.60
	Headlamp (LH) ✓			\$ 1,198.80
	<b>SUB TOTAL</b>			<b>\$ 2,938.20</b>
	<b>LESS 20%</b>			<b>\$ 587.64</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,350.56</b>
	Front Number Plate ✓			\$ 25.00 <b>Nett</b>
	Front No Plate Trim Cover ✓			\$ 30.00 <b>Nett</b>
				<b>\$ 55.00</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ <del>220.00</del>
	Spray Painting Charge			\$ <del>220.00</del> <b>200</b>
	Wiring Charge			\$ <del>30.00</del> <b>20</b>
	<b>TOTAL LABOUR</b>			<b>\$ 470.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,875.56</b>
<p>Kalin 16/11</p> <p>15/10/18 1525h</p> <p>200</p> <p>PIP</p> <p>Before Paint photo</p> <div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				