

ASS. REC. BY:

REF: CS/AIG18018791/Asd3

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Azlan Syazaidin

of

AIG

Date/Time:

16/10/18 @ 2:45pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SCV 833L

Insured:

SGT 73612

at Workshop m/s

Reliable Carz

Tel:

8166 9797

of

8 kuki Bkt Ave 4 #05-50 premier

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/10/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

3:58pm @ 16/10/18

Person Contacted:

Jason

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SCV 833L - NA/INC18018705/24

DOA: 12/10/18

SGT 73612 - NA/INC18018705/24

DOA: 12/10/2018

19/11/18

Confirmed L/S \$2,000/- @ 5 days with Adrian  
( \$1,170.00 Red - 37% )

REF: AIG

## ASSIGNMENT

23/12/08.

From: Date: 17/10/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCV 833L  
at Workshop m/s: Reliable Carz  
of: 8 kaki Bkt Ave 4 # 05-50

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SCV 833L Yr Regn: 2008, DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Murano C.C. 2488.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 260317 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1TDAZ5020000983.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/65R18-

R: 235/65R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 17/10/18

Survey held at: Reliable

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

RECEIVED 19 NOV 2018

MV: 161K  
PV: 141K  
Nett: 21K.

Date/Time, File Pass to?

19/11/08

1) 7/11/08

Date/Time, File Return to?

2)

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) 2,000/- 2/5

250

20

270

- Pre repair inspection request - SCV833L VS SGT7361Z (OI) DOA 12/10/2018

From: Azlan, Syazairdina  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit  
Sent: 16/10/2018 2:45:26 PM  
Attachments: 20181015151344.pdf, tmpF919.tif

Hi,

Please refer to the enclosed request from **VISION LAW LLC**.

Claim no : 8856723520SG003  
Case Owner : WAN NUR SALIHA BINTE SYED YUSOFF

If you have any queries/concerns, please let us know.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

From: Azlan, Syazairdina  
Sent: Tuesday, October 16, 2018 9:45 AM  
To: jactan@visionlawllc.com  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit  
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGT7361Z AND SCN833L ON 12/10/2018

Without Prejudice

Your Reference : R28-SCV833L-18  
Our Reference : 8856723520SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

From: Lim, Sheng Yang  
Sent: Monday, October 15, 2018 3:20 PM  
To: Azlan, Syazairdina  
Subject: FW: Our Ref: R28-SCV833L-18 -PRE-REPAIR SURVEY NOTICE

From: Jacqueline Tan [mailto:jactan@visionlawllc.com]  
Sent: Monday, October 15, 2018 3:13 PM  
To: Abu Kassim, Noor Mariesa; Lim, Sheng Yang  
Subject: Our Ref: R28-SCV833L-18 -PRE-REPAIR SURVEY NOTICE

Dear Sirs,

Enclosed herewith our letter of 15-10-2018 for your attention.

Regards

Jacqueline Tan  
Secretary  
Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811, Fax: 6535-6802

---

VISION LAW LLC  
Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI M MURTHY  
SEGA PARAM  
ANG KIM NOI DIANE  
RAVENDELA KRISHNASAMY  
JANICE HAN JIA LIN  
TAN VINCIXIAN, SELWYN  
CHEONG YUNHUI, CLARISSA  
EDISON TAM CHYI RU  
SONIA LIM WEI LEE

Unique Entity Number :200721148H  
✓ **HEAD OFFICE:** 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : jactan@visionlawllc.com

## BRANCH

TEL : 65 63580703  
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

**Our Ref:** AM.jl.Ins.R28.108368-18  
**Your Ref:** 8856723520SG003

16 October 2018

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attention: Motor Claims Department**

**BY FAX (6835 7416)**  
**(6415 3727)**

Email: syazairdina.azlan@aig.com  
email: shengyang.lim@aig.com

Dear Sirs,

**ACCIDENT INVOLVING SCV 833 L & SGT 7361 Z & SKJ 3154 C ON 12 OCTOBER 2018 ALONG CHIN SWEE ROAD AT ABOUT 2025 HOURS  
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Reliable Carz Pte Ltd  
8 Kaki Bukit Avenue 4  
#05-50 Premier @Kaki Bukit  
Singapore 415875  
Contact Person: Jason 8166-9797

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALI M  
(HEAD OFFICE)

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

cc: SCV 833 L – by email: reliablecarzpl@gmail.com only

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0609J

### Vehicle Details

Vehicle No.:	SCV833L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	MURANO 2.5
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	QR25425900A
Chassis No.:	JN1TDAZ50Z0000983
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$27,745.00
Original Registration Date:	24 Dec 2008
First Registration Date:	24 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$27,745.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2018
PARF Rebate Amount:	\$13,872.00

### Intended COE Rebate Details

COE Expiry Date:	23 Dec 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$6,501.00
COE Rebate Amount:	\$117.00
<b>Total Rebate Amount:</b>	<b>\$13,989.00</b>

The information contained herein is correct as at 18 Oct 2018

OK

# RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Vehicle No.: SCV 833 L

Model: NISSAN MURANO

REF: RC3121

## QTY DESCRIPTION

### List Items:

- 1 Rear bumper *Red*
- 2 Rear bumper retainer @52.00 *green*
- 1 Rear bumper sponge *Red*
- 1 Rear bumper reinforcement *Red*
- 1 Tail lamp RH *green*
- 1 Tail lamp LH *green*
- 2 Rear bumper bracket @65.00 *Red*
- 1 Rear end panel *Red*
- 1 Rear exhaust pipe box *Red*
- 1 Trunkid *Red*
- 1 Trunkid emblem "LOGO" *green*
- 1 Trunkid emblem "MURANO" *green*
- 1 Front bumper *Red*
- 1 Front bumper reinforcement *green*
- 1 Front bumper sponge *green*
- 2 Front bumper retainer @172.90
- 1 Front grille assy *Red*
- 1 Front number plate bracket *Red*

## AMOUNT (S\$)

1043.10	✓
104.00	✓
126.20	✓
679.70	✓
214.70	✓
214.70	✓
130.00	✓
528.30	✓
692.70	✓
2635.50	✓
50.90	✓
78.00	✓
863.30	✓
721.30	✓
126.20	✓
345.80	✓
589.40	✓
87.40	✓
9231.20	
Less 20%	(1846.24)
Subtotal	7384.96

### Special Nett Items:

- 1 Front number plate 8 base *Red*
- 1 Front bumper clip (set) *Red*
- 1 Rear bumper clip (set) *Red*
- 1 Reverse sensor *Red*

50.00	✓
50.00	✓
50.00	✓
250.00	✓
Subtotal	400.00

### Labour Charges:

- To remove & refit reverse sensor system
- To check wiring system
- To apply under coat
- To jacking, knocking & replace front portion part
- To welding, jacking, remove & repair rear portion part
- To spray painting on affected area

120.00	✓
80.00	✓
120.00	✓
650.00	✓
1000.00	✓
1200.00	✓
Subtotal	3170.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To follow damaged parts list during resurvey
- Parts prices are subject to final approval
- Third party survey is on "No Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11878.08  
10,954.96

Total: 2700.64  
K/S: 2K 4/5 17/10/18  
(Nett Value) 050mgs

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18018791/ASD3N2

Date: 21/11/2018

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100015745
Claimant Vehicle No :	SCV833L	Insured Vehicle No :	SGT7361Z
Date of Loss:	12/10/2018	Nature of Claim:	TP
		Claim No:	8856723520SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SCV833L	Engine No:	QR25425900A
Make & Model:	NISSAN MURANO, 2.5 (A)	Chassis No:	JN1TDAZ50Z0000983
Reg. Date:	24/12/2008 (Man. Year: 2007)	Odometer:	260317 km
Colour:	Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	235/65R18	Rear Tyre Size:	235/65R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,708.08	1,620.64	7,087.44	81.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	1,080.00	2,090.00	65.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,878.08</b>	<b>2,700.64</b>	<b>9,177.44</b>	<b>77.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,878.08</b>	<b>2,000.00</b>	<b>9,878.08</b>	<b>83.16</b>

## INSPECTION

Date of Assignment:	16/10/2018		
Date Inspected:	17/10/2018	Inspected At:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50 Singapore 415875
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,043.10 FL	*1,043.10 FL
2	2		*REAR BUMPER RETAINER	Necessary	104.00 FL	*104.00 FL
3	1		*REAR BUMPER SPONGE	Cracked	126.20 FL	*126.20 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	679.70 FL	*- FL
5	1		*TAIL LAMP RH	Not Necessary	214.70 FL	*- FL
6	1		*TAIL LAMP LH	Not Necessary	214.70 FL	*- FL
7	2		*REAR BUMPER BRACKET	Not Necessary	130.00 FL	*- FL
8	1		*REAR END PANEL	Repair	528.30 FL	*- FL
9	1		*REAR EXHAUST PIPE BOX	Not Necessary	692.70 FL	*- FL
10	1		*TRUNKID	Repair	2,635.50 FL	*- FL
11	1		*TRUNKID EMBLEM LOGO	Necessary	50.90 FL	*50.90 FL
12	1		*TRUNKID EMBLEM MURANO	Necessary	78.00 FL	*78.00 FL
13	1		*FRONT BUMPER	Repair	863.30 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	721.30 FL	*- FL
15	1		*FRONT BUMPER SPONGE	Not Necessary	126.20 FL	*- FL
16	2		*FRONT BUMPER RETAINER	Not Necessary	345.80 FL	*- FL
17	1		*FRONT GRILLE ASSY	Not Necessary	589.40 FL	*- FL
18	1		*FRONT NUMBER PLATE BRACKET	Deformed	87.40 FL	*87.40 FL
19	1		*FRONT NUMBER PLATE & BASE	Cracked	50.00 FS	*50.00 FS
20	1		*SET FRONT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,631.20</b>	<b>1,769.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>923.12</b>	<b>148.96</b>
<b>Total Parts (\$\$)</b>	<b>8,708.08</b>	<b>1,620.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REVERSE SENSOR SYSTEM	New	120.00	50.00
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	TO APPLY UNDER COAT	New	120.00	-
4	TO JACKING,KNOCKING & REPLACE FRONT PORTION PART	New	650.00	300.00
5	TO WELDING,JACKING,REMOVE & REPAIR REAR PORTION PART	New	1,000.00	200.00
6	TO SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	500.00
Gross Labour Cost (\$\$)			3,170.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >