

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-008864-2

Estimate

12/10/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SLS5947T

Veh Model :- MAZDA MAZDA2 AT R

Estimate# :- CK418116

Claim # :-

ACC. Date :- 11/10/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR DOOR STICKER LH <i>neu</i>	1 PC	35.80	35.80
2.	REAR DOOR STICKER LH <i>neu</i>	1 PC	32.00	32.00
3.	REAR DOOR GLASS WINDOW LH <i>X</i>	1 PC	324.60	324.60
4.	REAR DOOR POWER WINDOW MOTOR LH <i>?</i>	1 PC	160.70	160.70
5.	REAR DOOR WINDOW REGULATOR LH <i>?</i>	1 PC	159.00	159.00
6.	REAR DOOR MOULDING OUTER LH <i>neu</i>	1 PC	107.60	107.60
7.	REAR DOOR INNER MOULDING LH	1 PC	93.00	93.00
8.	REAR DOOR LOCK LH <i>X</i>	1 PC	291.00	291.00
9.	REAR DOOR CATCH LH <i>X</i>	1 PC	53.80	53.80
10.	REAR DOOR HANDLE SMALL LH <i>X</i>	1 PC	56.00	56.00
11.	REAR DOOR HANDLE BIG LH <i>X</i>	1 PC	86.00	86.00
12.	REAR DOOR TRIM INNER LH <i>?</i>	1 PC	286.70	286.70
13.	SIDE SKIRT LH - REPAIR	1 PC		
14.	SIDE SKIRT CLIP LH <i>X</i>	10 PC	4.80	48.00
15.	REAR DOOR HINGE UPPER LH <i>X</i>	1 PC	72.80	72.80
16.	REAR DOOR HINGE LOWER LH <i>X</i>	1 PC	72.80	72.80
17.	REAR DOOR CHECKER LH <i>X</i>	1 PC	67.00	67.00
18.	REAR FENDER LH - REPAIR <i>X</i>	1 PC		
19.	ROCKER PANEL LH - REPAIR	1 PC		
20.	DOOR FRAME LH - REPAIR	1 PC		
LIST TOTAL S\$				1,946.80
20% DISCOUNT S\$				-389.36
				1,557.44
SPECIAL NET ITEMS :				
1.	REAR ROCKER PANEL SIDE STEP CHROME LH (MAZDA) <i>X</i>	1 PC	150.00	150.00
2.	REAR DOOR LH MATTE BLACK (STICKER) <i>cut</i>	1 PC <i>150</i>	300.00	300.00
3.	REAR SIDE SKIRT MATTE BLACK (STICKER) <i>cut</i>	1 PC <i>100</i>	200.00	200.00
SPECIAL NET TOTAL S\$				650.00
LABOUR :				
TO REPAIR SIDE SKIRT LH, DOOR FRAME REAR LH, ROCKER PANEL LH, REAR FENDER LH. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS				<i>300</i> 700.00
TO SPRAY PAINT ON ACCIDENT DAMAGE PARTS				<i>300</i> 650.00
TO REMOVE & REPLACE REAR DOOR LH MECHANISM, DOOR LOCK & OTHER ATTACHMENT PARTS				<i>60</i> 80.00
TO RUST PROOF ACCIDENT AFFECTED AREAS				<i>40</i> 60.00
TO TINTED REAR DOOR LH WINDOW				<i>X</i> 100.00
LABOUR TOTAL S\$				1,590.00

Estimate

12/10/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 132886
 Veh # :- SLS5947T
 Veh Model :- MAZDA MAZDA2 AT R
 Estimate# :- CK418116
 Claim # :-
 ACC. Date :- 11/10/18
 Terms :- C.O.D Days
 Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,797.44

GST @ 7 % 265.82

AMOUNT DUE S\$ 4,063.26

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068

4 days

4/5

22/10/18 @ 1555

Resy after review