



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLR1979H

Date of Accident : 12 October 2018

Mr Lim Pang Ann

Date : 16 October 2018

*not Authorized
24/10/18
take photo After repair
1 day.*

LKK - Marcus

24/10/18 @ 1300h

Estimate To Repair SFM858C - Toyota C-HR Hybrid 1.8S CVT
Chassis No : ZYX102051855

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper upper <i>71</i>	\$ 1,341.90 <i>X</i>
02	1 pc	rear bumper lower <i>24/10/18</i>	\$ 500.00
03	1 pc	rear bumper lower tow cover <i>11</i>	\$ 51.50 <i>X</i>
04	1 pc	rear bumper reinforcement <i>11</i>	\$ 322.30 <i>X</i>
05	2 ps	rear bumper side retainers @ \$101.20 <i>11</i>	\$ 202.40 <i>X</i>
06	2 ps	rear bumper side holders @ \$87.20 <i>11</i>	\$ 174.40 <i>X</i>
07	10 ps	rear bumper clips @ \$4.00 <i>11</i>	\$ 40.00 <i>X</i>
08	2 ps	rear bumper side reflectors @ \$62.50 <i>11</i>	\$ 125.00 <i>X</i>
09	2 ps	rear bumper side reflector garnish @ \$112.50 <i>11</i>	\$ 225.00 <i>X</i>
			\$ 2,982.50
Less 25 %			\$ 745.63
			\$ 2,236.88
<u>SPECIAL NETT ITEMS</u>			
10	1 set	rear bumper lower parking sensor <i>11</i>	\$ 450.00 <i>X</i>
11	1 pc	rear bumper lower third brake light <i>11</i>	\$ 250.00 <i>X</i>
			\$ 700.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 150.00 <i>7180</i>
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		Putty and spray painting of the affected portion.	\$ <i>11</i> 550.00 <i>X</i>
			\$ 1,200.00
Total			\$ 4,136.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: