

# 振明 摩 哆

## CHIN MENG MOTOR SERVICES PTE LTD

1 Kaki Bukit Ave 6 #01-40 / #01-63 Autobay Singapore 417883

Tel: 6747-4810 6741-0879

Fax: 6745-5018 Email: cmm@cmm.sg

Reg. No. 201332629M

GST No. 201332629M

TP Lon Pac.  
Kion Tong

## ESTIMATE

Our Ref: ESTS307/18/TP

Your Ref: TP claim against SJZ7099P

8-Oct-18

### Lonpac Insurance Bhd

100 Beach Road

Shaw Towers

#19-00

Singapore 189702

Dear Sir/Ms,

### Re: Estimated cost of repair to Iveco Trakker no: XD8747X

Date of accident: 06-10-2018

#### Parts supply(S/N)

2 pcs Rear taillamp @\$250.00

2 pcs Taillamp brackets @\$200.00

1 pc Rear no. plate (S/Nett)

1 assy Truck Mounted Attenuator

2H ended  
Best  
Disturbed

450 SN: 43025  
405

500.00 250  
400.00 200  
25.00 ✓  
45,500.00 43k.  
46,425.00

#### Labour Charges

To remove TMA, install TMA, testing and commissioning.

1000

SS 3,000.00 1000  
49,425.00

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling +tel 44430

15/10/18 45(10%): 40K

2/3 \$40k

07 Aug