



3A Automobile Pte Ltd

Office Address : No 120 Lower Delta Road #02-15 Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

To : AXA Insurance Pte Ltd
Tel : 6880 4625
Fax : 6880 5501
Email : motor.survey@axa.com.sg

Vehicle Number: GBG 2809 K
Make and Model: TOYOTA HIACE 3.0
Date Of Accident: 11-10-18
Time Accident: 1415HRS

Unit	List Items	Unit Price	Prices	
1 pc	Rear Bumper	\$ 374.45	\$ 374.45	de
1 pc	Rear Door	\$ 1,712.45	\$ 1,712.45	bt
1 pc	Rear Windscreen Moulding	\$ 271.60	\$ 271.60	ne
1 pc	Rear Door (Toyota Logo) Chrome	\$ 121.25	\$ 121.25	ne
1 pc	Rear Door (Toyota Hiace) Sticker	\$ 132.10	\$ 132.10	ne
1 pc	Rear Door Lock	\$ 374.45	\$ 374.45	?
1 pc	Rear Door (Inner Board)	\$ 381.90	\$ 381.90	de
15 pcs	Rear Door (Inner Board) Clips	\$ 8.50	\$ 127.50	ne
1 pc	Rear Door Handle Garnish	\$ 274.45	\$ 274.45	and
1 pc	Rear Door Lower Lock Assembly	\$ 255.10	\$ 255.10	bt
1 pc	Rear Right Tail Lamp	\$ 381.90	\$ 381.90	X
1 pc	Rear End Panel	\$ 581.10	\$ 581.10	bt
1 pc	Rear Right Panel (Below Tail Lamp)	\$ 231.35	\$ 231.35	de
2 pc	Rear Bumper Bracket (L/R)	\$ 141.45	\$ 282.90	?
2 pcs	Rear Bumper Retainer (L/R)	\$ 132.25	\$ 264.50	ne
1 pc	Rear Door Lock Catch (Below)	\$ 274.75	\$ 274.75	right
12 pc	Rear Bumper Clips	\$ 8.00	\$ 96.00	ne
S/Total:			\$ 6,137.75	
Less 20%			\$ (1,227.55)	

1 pc	Rear Number Plate + Frame	\$ 40.00	\$ 40.00	bt 30.
1 set	Reverse Camera	\$ 250.00	\$ 250.00	X
1 set	Reverse Sensor	\$ 200.00	\$ 200.00	rw

\$ 5,400.20

	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on the Affected Areas & Components with Oven Spray Booth Facilities	\$ 1,100.00	\$ 1,100.00	600.
	To Remove & Replace the Damaged Parts as Listed Above, including Reinstallments of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts	\$ 900.00	\$ 900.00	700 600
	To Remove & Replace the Rear Windscreen and Tested for water leaking	\$ 500.00	\$ 500.00	120.

Total

\$ 7,900.20

Regards,

3A Automobile Pte Ltd
Person to contact : Johnny / Bowie
Mobilephone : 9786 8677 / 6223 1122

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
- WP
16/10/18 @ 430pm
6 days
Resurvey after repair
sur@lkkauto.com