PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

17-Oct-18

ESTIMATE REPAIR BILL FOR HYUNDAI 130 (A) REGN NO: SHD 1663 P

	1 pc	Front o/s fender @ \$514.02 × 50°				
	1 pc	The state of the s		\$	514.02	
	2 pcs	Front o/s door XAPA-		\$	1,723.60	
		Front o/s door hinges @ \$36.10 × 54		\$	72.20	
	1 pc	Rear o/s door × tep->		\$	2,017.48	
	2 pcs	Rear o/s door hinges @ \$39.00 × 5°C		\$	78.00	
	1 pc	Rear o/s rim @ \$246.00 × 14		\$	246.00	
		Remob Forder empair		\$	4,651.30	
		Le	ss 20%	\$	930.26	
	S/NETT			\$	3,721.04	
	-	A.4				
	1 set	o/s door stickers		S	100.00	
	1 pc	Rear o/s fender sticker		S	60.00	
					00.00	
		Sundry		\$	50.00-	
		To dismantle / refit the inner garnishes, inner linings, inner		φ	20	
		trims, cushion seat, carpet, etc to facilitate repairs.		\$	180-Arr	
		To dismantle and refit the inner components of the front o/s			19200 50	>
		door & rear o/s door into new shell door		\$	300-00	- 22
		To labour charge for dismantle and renew the accident			00,00	
		darriaged parts. Including knock-out, straighten, repair				
		reshape and adjust of the o/s rocker panel garnish, rear o/s fender, etc.			400	
				\$	850.00	
		To putty and spray painting on front o/s fender, front o/s			720	
		door, rear o/s door, o/s rocker panel garnish,		\$	800.00	
		To apply rustproofing on the repaired and replaced panels.		\$	120.00 X	- 12
				-		
		(ALL THE REPAIR COSTS ARE SUBJECTED TO GST/K Auto Continue Repairer	sultants hen	<u>rationally</u>	0,101.04	
		THE ABOVE STANDARD OF THE REPORT THE REPORT OF	of the lollown dore/after spray	painting		
		THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE THE REPAIR DO NOT IN	naged part(s) du	ring resul? dirmation	ey	
		Pans prices.	movis on a "Wil	hout Preju	dice" basis	
		No illegal mo	Ollicons, re.		word and	
		is subject to	ary item(s) must final approval fir	om Insurar	ce Company	
		3 Pays. Acknowledge Sinnature:	d by Repairer			
		Signature:				, ,
		After Report phot. Signature.		SEATE SOLUTION CO.	19/0/	18 Cm
		After Report			/ /	1
						1

19/0/18 Chl pips/13s 3 by