

DING AUTOMOTIVE PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/10/2018 11:24

JOB-NO: 50111033

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHC7917Z
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP

TRANS: AUTO
SA: Ding Auto User 1

CHASSIS: KMHLB41UMEU061563
ENGINE: D4FDEU461323

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00 <i>200</i>		Y	
2 TO CHECK WIRING AND LIGHTING SYSTEM & DIAGNOSTIC CLEAR FAULT CODE	1.00	250.00	0.00	250.00 X		Y	
3 R&R REAR PASSENGER SIT & SPEAKER PANEL GARNISH & WINDSCREEN INNER TRIM TO REPLACE SPEAKER PANEL	1.00	350.00	0.00	350.00 X		Y	
4 REPAIR REAR WIRE HARNESS- REVERSE SENSOR	1.00	200.00	0.00	200.00 X		Y	
5 SPRAY REAR BUMPER	1.00	250.00	0.00	250.00 <i>200</i>		Y	
6 SPRAY REAR BUMPER REINFORCEMENT	1.00	250.00	0.00	250.00 <i>?</i>		Y	
7 SPRAY REAR END PANEL	1.00	250.00	0.00	250.00 X		Y	
8 SPRAY REAR REVERSE SENSOR & TAIL LAMP INNER PANEL LHS/RHS	1.00	150.00	0.00	150.00 X		Y	
TOTAL:		2,700.00	0.00	2,700.00			
MATERIALS							
1 REAR BUMPER	1.00	599.68	119.94	479.74 <i>de</i>	L	Y	
2 REAR BUMPER REINFORCEMENT	1.00	484.40	96.88	387.52 X	L	Y	
3 REAR BUMPER REINFORCEMENT ARM LHS	1.00	98.63	19.73	78.90 X	L <i>old damage</i>	Y	
4 REAR BUMPER REINFORCEMENT ARM RHS	1.00	98.63	19.73	78.90 X	L <i>old damage</i>	Y	
5 REAR BUMPER REINFORCEMENT SPONGE	1.00	89.62	17.92	71.70 X	L <i>old damage</i>	Y	
6 REAR BUMPER RETAINER LHS	1.00	42.63	8.53	34.10 X	L	Y	
7 REAR BUMPER RETAINER RHS	1.00	42.63	8.53	34.10 X	L	Y	
8 REAR BUMPER DIFFUSER	1.00	228.40	45.68	182.72 <i>cut</i>	L	Y	
9 REAR END PANEL	1.00	626.95	125.39	501.56 X	L <i>old damage</i>	Y	
10 REAR END PANEL TOP GARNISH	1.00	215.45	43.09	172.36 X	L	Y	
11 REAR FENDER INNER PANEL TRIM LHS	1.00	198.45	39.69	158.76 X	L <i>old damage</i>	Y	
12 REAR FENDER INNER PANEL TRIM RHS	1.00	198.45	39.69	158.76 X	L <i>old damage</i>	Y	
13 TAIL LAMP LHS	1.00	697.80	139.56	558.24 X	L <i>old damage</i>	Y	
14 REAR BUMPER CLIP	1.00	35.00	0.00	35.00 <i>new</i>	S	Y	
15 REAR BUMPER RUBBER PROTECTOR PAD	1.00	180.00	0.00	180.00 <i>new</i>	S	Y	
16 REAR BUMPER REVERSE SENSOR	1.00	230.00	0.00	230.00 X	S	Y	
17 REAR BUMPER INNER UPPER MOULDING LHS	1.00	15.00	0.00	15.00 X	S	Y	
18 REAR BUMPER INNER UPPER MOULDING RHS	1.00	15.00	0.00	15.00 X	S	Y	
19 REAR BUMPER INNER LOWER MOULDING	1.00	15.00	0.00	15.00 X	S	Y	
20 REAR END PANEL FLOOR LHS	1.00	35.00	0.00	35.00 X	S	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
21 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	X S	Y	
22 REAR FENDER INNER PANEL TRIM CLIP	1.00	35.00	0.00	35.00	X S	Y	
TOTAL:		4,231.72	724.36	3,507.36			
TOTAL PARTS & LABOUR :		6,931.72	724.36	6,207.36			

EXCESS/LOADING:\$ 0.00

No. Of Day: 2 daysRE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM: \$DATE OF SURVEY: 15 / 10 / 18 @ 1145SURVEYED BY: RASULCONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: