

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1183/2018/PH
Date : 17-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle is : SKF 2772 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Leslie Lee Chee Sieong
Address : Blk 317D Anchorvalve Road
#12-210
Singapore 544317

Telephone : HP +65 97693572
Type of Claim : Third Party Claim
Policy No. : 1800070654
Vehicle No : **SMA 7169 S**
Model Code : Audi A3 1.0 TFSI
Model / Year : Jun-18
Engine No : CHZ 465632
Chassis No : WAUZZZ8V8J1068864
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Oct-18
Place of Accident : UPPER SERANGOON RD/WOLSKEL RD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 7169 S .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid.Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper assy. Re-organize rear crash management components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray rear bumper	\$ 800.00 550	
4	To carry out diagnostic check	S/N \$ 192.00 ✓	
LABOUR CHARGES		: <u>\$ 2,172.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 7169 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER <i>Revised</i>	\$ 1,697.00	✓
2	FIXING PARTS FOR FRONT BUMPER <i>Revised</i>	\$ 166.00	?
3	STICKY PADS <i>Revised</i>	4 TBC	✓
4	ADAPTER WHEEL HOUSING LINER - LH/RH <i>Revised</i>	2 \$ 64.00	✗
5	GUIDE SECTION - LH/RH <i>Revised</i>	2 \$ 28.00	✗
6	LOCKING MECHANISM <i>Revised</i>	2 \$ 50.00	✗
7	FRONT BUMPER SPOILER <i>Revised</i>	\$ 206.00	✗
8	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>Revised</i>	2 \$ 70.00	✗
9	SIDE REINFORCEMENT	\$ 501.00	✗
10	BRACKET - LH/RH	2 \$ 48.00	✗
11	GUIDE SECTION - LH/RH	2 \$ 114.00	✗
12	SENSOR - LH/RH	2 \$ 421.00	✗
13	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 3,665.00	
TOTAL LABOUR CHARGES		: \$ 2,172.00	
GRAND TOTAL		: \$ 5,837.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King.
Surveyed Date : 19/10/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant