

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: SIM WEE SIANG	Document No.	: SQT18004376	Page	1
	887A WOODLANDS DRIVE 50	Date	: 12. Oct 2018		
	#05-569	Customer No.	: ****3165I		
	SINGAPORE 731887	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SLF6314G	Engine No	: L15B4530236		
Chassis No	: JHMRU1830GX200236	Date Time	: 12. Oct 2018 8:42:03 PM		
Model	: HRV LX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: SIM WEE SIANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 12/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: SIM WEE SIANG						
	OWNER INSURER: LIBERTY						
	ACC DATE: 12/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LONPAC						
	TP VEH: GX7427Y						
68100-T7A-J20ZZ	TAIL GATE COMP	1	838.90	25	629.17	44.04	673.21 <i>DEF</i>
68210-T5A-J03ZZ	HINGE COMPTAILGATE	2	30.20	25	45.30	3.17	48.47 ?
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07 ?
74800-T7A-J02	LOCK ASSYTAILGATE	1	81.90	25	61.42	4.30	65.72 ?
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER	1	103.20	25	77.40	5.42	82.82 ?
74813-T5A-003	STRIKER ASSYTAILGATE	1	24.70	25	18.52	1.30	19.82 ?
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	186.00	25	139.50	9.77	149.27 ?
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1	126.90	25	95.17	6.66	101.83 ?
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	133.40	25	100.05	7.00	107.05 ?
84433-T7A-J01ZA	LINING ASSYTAILGATE UPPER	1	58.10	25	43.57	3.05	46.62 ?
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35 <i>NE</i>
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31 <i>NE</i>
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58 <i>NE</i>
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05 <i>NE</i>
33502-T7A-J01	LAMP UNITR.	1	428.70	25	321.52	22.51	344.03 <i>SV</i>
33552-T7A-J01	LAMP UNITL.	1	428.70	25	321.52	22.51	344.03 <i>SV</i>
34150-T7A-J01	LIGHT ASSY,R.LID	1	264.60	25	198.45	13.89	212.34 ?
34155-T7A-J01	LIGHT ASSYL.LID	1	264.60	25	198.45	13.89	212.34 ?
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11 <i>DEF</i>
71593-T7A-J00	SPACER R,RR.BPR S	1	19.20	25	14.40	1.01	15.41 <i>me</i>
71598-T7A-J00	SPACER,L,RR.BPR S	1	19.20	25	14.40	1.01	15.41 <i>me</i>



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SIM WEE SIANG
 887A WOODLANDS DRIVE 50
 #05-569
 SINGAPORE 731887

Registration No : SLF6314G
 Chassis No : JHMRU1830GX200236
 Model : HRV LX-SIN CVT YM 2016
 Owner's Name : SIM WEE SIANG
 Ins Policy No. :
 Date of Accident : 12/10/2018

Document No. : SQT18004376
 Date : 12. Oct 2018
 Customer No. : ****3165I
 Svc Advisor : ANIKKA LAI SWEE KAM
 Engine No : L15B4530236
 Date | Time : 12. Oct 2018 8:42:03 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	151.80	25	113.85	7.97	121.82
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	151.80	25	113.85	7.97	121.82
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
66100-T7A-300ZZ	PANEL COMPRR.	1	365.70	25	274.27	19.20	293.47
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	662.20	25	496.65	34.77	531.42
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR	1	81.20	25	60.90	4.26	65.16
74890-T7A-J12ZS	GARNISH ASSYRR.LICENSE	1	186.10	25	139.57	9.77	149.34
18307-T7A-901	SILENCER COMPEXHUAST	1	528.00	25	396.00	27.72	423.72
74646-T7A-010	COVERRR.FLOOR UN	1	118.30	25	88.72	6.21	94.93
74410-T7A-J01ZN	PROTECTOR,R,RR.WHEEL ARCH	1	165.40	25	124.05	8.68	132.73
74450-T7A-J01ZE	PROTECTORL.RR.WHEEL ARCH	1	172.10	25	129.07	9.03	138.10
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	46.62
74940-TR0-003	BUZZER ASSYSMART	1	58.90	25	44.17	3.09	47.26
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09	32.01
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
Sum Item					5111.35	357.81	5,469.16
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00		100.00	7.00	107.00
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	200.00		200.00	14.00	214.00

Printed on 13/10/2018 12:19:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SIM WEE SIANG
887A WOODLANDS DRIVE 50
#05-569
SINGAPORE 731887

Registration No : SLF6314G
Chassis No : JHMRU1830GX200236
Model : HRV LX-SIN CVT YM 2016
Owner's Name : SIM WEE SIANG
Ins Policy No. :
Date of Accident : 12/10/2018

Document No. : SQT18004376 Page 3
Date : 12. Oct 2018
Customer No. : ****3165I
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B4530236
Date | Time : 12. Oct 2018 8:42:03 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1	220.00		220.00	15.40	235.40 ?
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	9.80	149.80 ?
BM103D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	500.00		500.00	35.00	360 535.00 / NE
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00		800.00	56.00	856.00 56
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20 3
BMU30R	RMOVE & REPLACE EXHAUST SYSTEM.(N)	1	800.00		800.00	56.00	856.00 56
BKRP21B	CUT OFF & RENEW RR FLOOR PANEL & DAMAGE PARTS.	1	5600.00		5600.00	392.00	5992.00 196
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00		3500.00	245.00	3745.00 377
Sum Labor					12720.00	890.40	13.610.40

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 17,831.35 1,248.21 19,079.56
Total (Inclusive of GST) 19,079.56

NA2 LKK
12/10/18 1230
PLP
5 DAYS
- CHECK ITEMS PHOTOS
- BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/10/2018 12:19:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)