

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

2 Days.
part by part.
before part photos.
Gue Qian
6/10/18

(3rd party claim against 11 insured SNA3921Y

Estimate repair

Vehicle No. : SNA 5340 B
Make & Model : Mercedes benz
Chassis No. : E250 C61

Submitted by :

COE expiry :

Engine No. :

Bur

30-03-2020

Date of survey :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Top rear bumper / Re			\$1625	1513
02	Lower rear bumper (garnish) / Re			\$1010	485.15
					1998.15
				-10%	1798.34
	<u>Special note</u>				
01	Clips @ \$11.00 x 4 / MC	01	\$44.00		
	<u>Labour Description</u>				
01	Dismantle / Assemble of affected part	01	\$260.0	260	
02	Spray painting of affected parts	01	\$260.0	260	
03	Re-adjust / make sensor work on new bumper	01	\$180.0	40.	2282.34
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and quoted in a separate report from Insurance Company Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary. Acknowledged by Repairer Signature: Date:					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.