



Case Details

Case Reference Number : TAX/10/18/2025
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF150Z

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4039-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 06/10/2018 10:18 AM
 Vehicle Age(In Months) : 10

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
			Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ✓ /CRA
One Time Key In			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	0	0	Not Given ✓ /NLC
One Time Key In			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ✓ /NLC
One Time Key In			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ✓ /NLC
One Time Key In			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ✓ /NLC
One Time Key In			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Given ✓ XNN
One Time Key In			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Given ✓ XSVL
One Time Key In			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Given ✓ XSVL
One Time Key In			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ✓ /NLC
One Time Key In			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Given ✓ XSVL
One Time Key In			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Given ✓ XSVL
One Time Key In			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace ✓ /CRA
One Time Key In			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace ✓ /DEF
One Time Key In			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace ✓ /NLC
Total Spare Part Cost								1,504.80		Surveyor Total	889.79	
Lump Sum Discount (%)								0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost								1,499.85		Final Sur Total	889.79	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		558.00	200.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	NN
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
3	TO WASH AND VACUUM	60.00	0	NN
Total:		260.00	40.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,499.85	889.79
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	260.00	40.00
Overall Total	2,655.85	1,329.79
Lump Sum Repair Option		
Lump Sum Total	0.00	1,329.79
Surveyor Approved Amount		1,329.79
No of Repair Days*	2	2
Remarks		Surveyor Remarks PART BY PART .2 DAYS BEFORE PAINT PHOTOS.
Surveyor Name		Naz
Signature		
Survey Date	11/10/2018	

Save

Clear

NAZ LKK
9/10/18 1100
PART BY PART
2 DAYS
BEFORE PAINT PHOTOS.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: