

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

10/10/18 *01452*

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0444/2018
DATE : 10-OCT-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

OWNER'S NAME : MR OH CHIN YUAN BENJAMIN (HU QINYUAN BENJAMIN)
ADDRESS : 38 JALAN LEBAN

S(577575)
TELEPHONE NO : 97304949/96435780

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SLQ18942
VEHICLE NO : SLJ1042C
MODEL CODE : JDRNRRZT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20904607B
CHASSIS NO : JN1JANT32Z0002749
MILEAGE : 1 KM
DATE IN : 10/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 04/10/2018

LICK
was
green?
12/10/18
LOA
wait...

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ1042C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	?
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	?
4	ZZ/001	REPAIR END PANEL AND RENEW REAR BUMPER	900.00	390
5	ZZ/002	S/PAINT REAR BUMPER (2 TONE) AND END PANEL	900.00	350
TOTAL LABOUR CHARGES			2130.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ1042C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 ORNAMENT ASSY RH REFLECTOR BUMPER	26560-JJ90A	55.00 ?		
2 CLIP ARC \$3.00 EA X 03	76882-JG10A	9.00 10.00 ?		
3 GROMMET ARC \$4.50 EA X 03	76881-JG00A	13.50 15.00 ?		
4 GROMMET ARC \$2.50 EA X 02	76848-JG00B	5.00 ?		
5 CLIP ARC \$2.50 EA X 02	76847-JG00A	5.00 ?		
6 CLIP ARC \$2.50 EA X 03	01553-10641	7.50 ?		
7 FILLET-MLDG RH REAR ARC	78860-4CE0A	150.00 ?		
8 GROMMET BUMPER \$1.80 EA X 02	01281-00711			3.60 10.00
9 CLIP BUMPER \$1.20 EA X 04	01553-10501	4.80 10.00		
10 STAY-RR BUMPER RH	H5210-4CCMA	174.80 ?		
11 REINF-BUMPER RR	85032-4CC0A	533.80 ?		
12 BRACKET-BUMPER RH	85220-4CE0A	35.90 100.00 ?		
13 FACE-RR BUMPER	85022-4CE0H	623.80 100.00		
14 SUNDRIES	NPN			100.00 20
15 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 100.00
SUB TOTAL		1618.10	0.00	313.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		323.62	0.00	0.00
GRAND TOTAL		1294.48	0.00	313.60
OVERALL TOTAL		1608.08		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ1042C

TOTAL LABOUR CHARGES	2130.00
TOTAL SPARE PARTS CHARGES	1608.08
GRAND TOTAL	3738.08 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - 1790010068
SURVEYED DATE	:	17/10/18 @ 1040
AUTHORIZED DATE	:	2 days
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	Reby bl paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: