

ASS. REC. BY:

REF: CS/MSG18018845 TlvD3 72
Special Instruction:

Surveyor:

caufich

ASSIGNMENT (Office)

From (Person):

chia myuk pui

of

MSG

Date/Time: 17/10/2018 11:03am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL148C

Insured:

8MD 2115P

at Workshop m/s

zhong cheng Enterprise

Tel:

9750 6777 / 9338 2859

of

Blk 6, Woodlands Rd, 349J Yew Tee Ind. Est.

Policy No:

A29093822 QMY

Claim No:

573145

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:26am @ 17/10/18

Person Contacted:

Winson

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SL148C-X
	8MD 2115P-X
19/10/18	Send preli. revision via merimen
15/11/18	LS \$6300 confirmed by email (Ref 8858-08, 5990)

Signature: *Tanpin*

REF:

MS16

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

u.p.

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL/48C Yr Regn: 17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Senta C.C. 1496
Colour: Bronze A/C: Insured / Std / NI / NA
Sp. Reading: 53387 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MHF 2 281138.00025067
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/60R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook
Front: 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 17/10/18 @ 1715
Survey held at Zhang cheng
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>u/s will nail G/L</i>

RECEIVED 15 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) *15/11 - typist*

Report Format: *merimen*

Lump Sum / I.B.I: (\$) *6200 f*

Days Of Repair: *9*

Resurvey No. of Trip: *1*

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + R\$ \$

) Photos

) Others

TOTAL:

200
10
210

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 19 Oct 2018

Preliminary Advice

Insured Vehicle No	: SMD2115P	Accident Date	: 12/10/2018
TP Vehicle No	: SLL148C	Assignment Date	: 17/10/2018
Make	: TOYOTA SIENTA	Est. Duration of Repair	: 7.00
Date of Inspection	: 17/10/2018		
Inspection At	: ZHONG CHENG ENTERPRISE PTE LTD - WOODLANDS (HQ) BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE SINGAPORE 678008		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,958.58
Revised Amount	:S\$	5,430.43
Check Items (Estimated)	:S\$	2,554.13
Total	:S\$	7,984.56

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2018 18:18		17 Oct 2018 11:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA BEE TIN, ID: S1165681A		
Main Claimant:	LEE MAN YEE, ID: S8371159J		
Vehicle Reg. No.:	SLL148C	Date of Loss:	12/10/2018 20:00 - :59 [20 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 573145	Policy/Cover Note No.:	A29093822QMY (Comprehensive) Coverage: 08/08/2018 - 07/08/2019
Vehicle Reg. No. (Insured):	SMD2115P	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Zhong Cheng Enterprise Pte Ltd - Woodlands (HQ) BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE, 678008 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/10/2018]		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100%. CONTACT:AH SIONG 9826 4959		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 November 2018 3:38 PM
To: Zhong Cheng; SUR
Subject: RE: SLL 148C-DOA: 12/10/2018

Dear Sini,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zhong Cheng <zhongchengauto@gmail.com>
Sent: Thursday, 15 November 2018 3:34 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: SLL 148C-DOA: 12/10/2018

Hi Veron,

Ok to accept \$6200 and 9 working days.

Thanks

Best Regards

Sini Tan

Zhong Cheng Enterprise Pte Ltd

Blk 6, 399J

Yew Tee Industrial Est

S678008

HP: 93382859 Fax: 68942883

On Tue, Nov 13, 2018 at 4:26 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Sini,

WITHOUT PREJUDICE

Offer Lump Sum \$6200/- @ 9 working days.

Please check and confirm.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 7 November 2018 11:47 AM
To: Zhong Cheng (zhongchengauto@gmail.com) <zhongchengauto@gmail.com>
Subject: SLL 148C-DOA: 12/10/2018

Dear Sini,

Kindly advise vehicle status.

If vehicle has been repaired, please forward us resurvey photos and finalize with us.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1159J
Vehicle Details	
Vehicle No.:	SLL148C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5 CVT STD
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	2NRX116776
Chassis No.:	MHFZ28H3800025067
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$17,902.00
Original Registration Date:	10 Feb 2017
First Registration Date:	10 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$17,902.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Feb 2027
PARF Rebate Amount:	\$13,426.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$42,283.00
Total Rebate Amount:	\$55,709.00

The information contained herein is correct as at 19 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 11:42
Date Of Accident	12/10/2018 20:15
Exact Location Of Accident	CTE/SLE EXPRESSWAY TOWARDS EXIT BRADELL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL148C
Insured/Policyholder	
Name Of Registered Owner	LEE MAN YEE
NRIC No	S8371159J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83283727
Alternative Phone No	OFFICE-83283727

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097662644
Cover Note Number	

Driver

Name of Driver	HENG KAH IN
NRIC No	S8326457H
Date Of Birth	29/08/1983
Occupation	INDOOR
Date Of Driving Pass	02/02/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83283727
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11 JALAN MATA AYER #04-62
Postcode	759154
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE MAN YEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC2115P
Vehicle Make/Model/Colour	KIA/WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No:

Sketch Plan #2

SKETCH PLAN

Vehicle A SLL 1482

Vehicle B SMD 2115P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At The mention date & time of accident 12/10/2018 about 20:15pm
 I was driving along CTE SLE Expressway towards exit bridge
 There was total 5 lanes and I am on the left 4th lanes
 and I notice instant vehicle brake and stop as I also slow
 down and brake to stop. suddenly vehicle B "SMD 2115P" collided
 onto my rear left car portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/ FIN No.:

Vehicle No: SLL148C
Model : Toyota Sianta

No	List Items	Oty	Unit Price	List Price
1	Rear Bumper	1	\$495.90	de ✓ \$495.90
2	Rear Bumper (LH)	1	\$295.50	nm ✓ \$295.50
3	Rear Bumper Trim (Center)	1	\$235.80	de ✓ \$235.80
4	Rear Bumper Trim (LH)	1	\$198.50	de ✓ \$198.50
5	Rear Bumper Retainer	2	\$58.00	nei ✓ \$58.00
6	Rear Undercarriage Trim Cover	1	\$189.20	de ✓ \$189.20
7	Rear Bumper Clips	10	\$18.00	nei ✓ \$18.00
8	Rear Bootlid Cover	1	\$1,653.80	bt ✓ \$1,653.80
9	Rear Bootlid Chrom Trim	1	\$230.50	nm x \$230.50
10	Rear Bootlid Chrom Trim Clips	4	\$20.00	nm x \$20.00
11	Rear Bootlid Emblem	1	\$55.30	nei ✓ \$55.30
12	Sianta Emblem	1	\$58.00	nei ✓ \$58.00
13	G Emblem	1	\$42.70	nei ✓ \$42.70
14	Rear bootlid lamp (LH)	1	\$554.50	bt ✓ \$554.50
15	Rear Bootlid lock unit	1	\$185.20	BT ✓ \$185.20
16	Rear Bootlid lock connector	2	\$20.50	nm x \$20.50
17	Rear Bootlid Catch	1	\$35.30	RY ✓ \$35.30
18	Rear Boot weather strip (Inner)	1	\$185.20	nm x \$185.20
19	Rear Boot weather strip (outer)	1	\$163.40	de ✓ \$163.40
20	Rear Bootlid wiper motor	1	\$375.10	x nm \$375.10
21	Rear windscreen (with moulding)	1	\$1,453.50	nm x \$1,453.50
22	Rear Bootlid Trim	1	\$489.00	nm x \$489.00
23	Rear Bootlid Trim Clips	8	\$36.00	nm x \$36.00
24	Rear Boot floor Trim	1	\$132.60	nm x \$132.60
25	Rear Boot floor Trim Clips	4	\$36.00	nm x \$36.00
26	Rear Boot inner Trim (LH)	1	\$383.60	de ✓ \$383.60
27	Taillamp LH	1	\$898.50	nei ✓ \$898.50
28	Rear exhaust muffler	1	\$853.60	nm x \$853.60
29	Rear exhaust insulator	1	\$166.00	nm x \$166.00
30	Rear fender LH	1	\$898.90	bt ✓ \$898.90
31	Rear End Panel	1	\$495.00	bt ✓ \$495.00

Rear End Panel top scratch de ✓ \$ 230.00 List Price \$10,913.10
Rear Bumper LH Reflector lamp nei ✓ \$ 115.00 -25% \$2,728.28
Total \$8,184.83

No	Special Nett Items	Qty	Unit Price	Nett Price
1	Revers Sensor	1 set	\$250.00	\$250.00
2	Windscreen Sealent	1Pc	\$80	\$80.00
3	Rear end panel sealent	2 Pcs	\$60	\$120.00
4	Rear number plate	1pc	\$30.00	\$30.00
5	Rear number plate casing	1pc	\$25.00	\$25.00
Total				\$505.00

1180

280

200 NW ✓
nei ✓
40 NW ✓
x nm
x nm

Labour

To Remove front bumper, rear bumper, rear bootlid, rear fender LH and other attachment items to conduct cutting, welding, panel beating and replace affected damage parts. \$1,600.00 1000

To spray paint on front bumper (upper), front bumper (lower), rear bootlid, rear bumper, rear bumper (LH), rear bumper (RH), rear end panel and rear floor panel. \$1,500.00 1000

Remove and replace rear bootlid wiper motor & lock unit. \$180.00 x n n

Remove and replace reveals sensor. \$80.00 30.

Remove and refix rear seat. \$150.00 60

Remove and refix rear boot interior. \$150.00 50.

Remove and replace rear windscreen. \$150.00 120.

Remove and replace rear exhaust muffler. \$120.00 x n n.

Electrical and wiring check. \$80.00 30

Total \$4,010.00

12,958.58

Tanfika 97495749 15,058.08
- WP

17/10/18 @ 1715

Resurvey after repair.

sur E (Kkanta w m

9 days

19/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle No: SLL148C
Model : Toyota Sianta

SUPPLEMENTARY

No	List Items	Oty	Unit Price	List Price
1	Taillamp panel	1		bt ✓ \$0.00
2	Air vent duct	1		de ✓ \$0.00
3	Rear fender upper garnish	1		cu ✓ \$0.00
4	Spare tyre panel	1		Rx \$0.00
5	End panel top garnish clips	1 set	\$38.00	nei ✓ \$38.00

\$698.00 220
\$110.00
\$270.00
\$830.00

List Price ~~\$38.00~~
-25% ~~\$9.50~~
Total ~~\$28.50~~

Labour

To remove & refix fuel tank
To vaccum & clean interior cushion
To straighten rear chassis member

\$120.00 60
\$150.00 X n n
\$250.00 X n n

Total \$520.00

Special Net listing

spare tyre panel sealant
taillamp panel sealant

\$60 X n n

\$60 40 nee ✓

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18018845/T1VD3N2

Date: 21/11/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29093822QMY
Claimant Vehicle No :	SLL148C	Insured Vehicle No :	SMD2115P
Date of Loss:	12/10/2018	Nature of Claim:	TP
		Claim No:	573145

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL148C	Engine No:	2NRX116776
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	MHFZ28H3800025067
Reg. Date:	10/02/2017 (Man. Year: 2017)	Odometer:	53357 km
Colour:	Bronze		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,528.07	5,474.25	5,053.82	48.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	2,350.00	2,180.00	48.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,058.07	7,824.25	7,233.82	48.04
Approved Total (Overridden) (\$\$)		6,200.00		
Nett Amount (\$\$)	15,058.07	6,200.00	8,858.07	58.83

INSPECTION

Date of Assignment:	17/10/2018	
Date Inspected:	17/10/2018 Inspected At:	Zhong Cheng Enterprise Pte Ltd - Woodlands (HQ) BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE Singapore 678008
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2018)
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL148C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	495.90 FL	*495.90 FL
2	1		*REAR BUMPER (LH)	Not Necessary	295.50 FL	*- FL
3	1		*REAR BUMPER TRIM (CENTER)	Deformed	235.80 FL	*235.80 FL
4	1		*REAR BUMPER TRIM (LH)	Deformed	198.50 FL	*198.50 FL
5	2		*REAR BUMPER RETAINER	Necessary	58.00 FL	*58.00 FL
6	1		*REAR UNDERCARRIAGE TRIM COVER	Deformed	189.20 FL	*189.20 FL
7	10		*REAR BUMPER CLIPS	Necessary	18.00 FL	*18.00 FL
8	1		*REAR BOOTLID COVER	Bent	1,653.80 FL	*1,180.00 FL
9	1		*REAR BOOTLID CHROME TRIM	Not Necessary	230.50 FL	*- FL
10	4		*REAR BOOTLID CHROME TRIM CLIPS	Not Necessary	20.00 FL	*- FL
11	1		*REAR BOOTLID EMBLEM	Necessary	55.30 FL	*55.30 FL
12	1		*SIENTA EMBLEM	Necessary	58.00 FL	*58.00 FL
13	1		*G EMBLEM	Necessary	42.70 FL	*42.70 FL
14	1		*REAR BOOTLID LAMP (LH)	Cut	554.50 FL	*280.00 FL
15	1		*REAR BOOTLID LOCK UNIT	Bent	185.20 FL	*185.20 FL
16	2		*REAR BOOTLID LOCK CONNECTOR	Not Necessary	20.50 FL	*- FL
17	1		*REAR BOOTLID CATCH	Repair	35.30 FL	*- FL
18	1		*REAR BOOT WEATHER STRIP (INNER)	Not Necessary	185.20 FL	*- FL
19	1		*REAR BOOT WEATHER STRIP (OUTER)	Deformed	163.40 FL	*163.40 FL
20	1		*REAR BOOTLID WIPER MOTOR	Not Necessary	375.10 FL	*- FL
21	1		*REAR WINDSCREEN (WITH MOULDING)	Not Necessary	1,453.50 FL	*- FL
22	1		*REAR BOOTLID TRIM	Not Necessary	489.00 FL	*- FL
23	8		*REAR BOOTLID TRIM CLIPS	Not Necessary	36.00 FL	*- FL
24	1		*REAR BOOT FLOOR TRIM	Not Necessary	132.60 FL	*- FL
25	4		*REAR BOOT FLOOR TRIM CLIPS	Not Necessary	36.00 FL	*- FL
26	1		*REAR FENDER INNER TRIM (LH)	Deformed	383.60 FL	*383.60 FL
27	1		*TAILLAMP LH	Cracked	898.50 FL	*898.50 FL
28	1		*REAR EXHAUST MUFFLER	Not Necessary	853.60 FL	*- FL
29	1		*REAR EXHAUST INSULATOR	Not Necessary	166.00 FL	*- FL
30	1		*REAR FENDER LH	Bent	898.90 FL	*898.90 FL
31	1		*REAR END PANEL	Bent	495.00 FL	*495.00 FL
32	1		*REAR END PANEL TOP GARNISH	Deformed	230.00 FL	*230.00 FL
33	1		*REAR BUMPER LH REFLECTOR LAMP	Cracked	115.00 FL	*115.00 FL
34	1		*TAILLAMP PANEL	Bent	698.00 FL	*220.00 FL
35	1		*AIR VENT DUCT	Deformed	110.00 FL	*110.00 FL
36	1		*REAR FENDER UPPER GARNISH	Cracked	270.00 FL	*270.00 FL
37	1		*SPARE TYRE PANEL	Repair	830.00 FL	*- FL
38	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	38.00 FL	*38.00 FL
39	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
40	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
41	2		*REAR END PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
42	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
43	1		*REAR NUMBER PLATE CASING	Not Necessary	25.00 FS	*- FS
44	1		*SPARE TYRE PANEL SEALANT	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*TAILLAMP PANEL SEALANT	Necessary	60.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					13,829.10	7,179.00
- List Item Discount on L Items 25.00/25.00% (S\$)					3,301.03	1,704.75
Total Parts (S\$)					10,528.07	5,474.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE FRONT BUMPER,REAR BUMPER,REAR BOOTLID,REAR FENDER LH AND OTHER ATTACHMENT ITEMS TO CONDUCT CUTTING,WELDING,PANEL BEATING AND REPLACE AFFECTED DAMAGE PARTS	New	1,600.00	1,000.00
2	TO SPRAY PAINT ON FRONT BUMPER (UPPER),FRONT BUMPER (LOWER),REAR BOOTLID,REAR BUMPER,REAR BUMPER (LH),REAR BUMPER (RH),REAR END PANEL AND REAR FLOOR PANEL	New	1,500.00	1,000.00
3	REMOVE AND REPLACE REAR BOOTLID WIPER MOTOR & LOCK UNIT	New	180.00	-
4	REMOVE AND REPLACE REVERSE SENSOR	New	80.00	30.00
5	REMOVE AND REFIX REAR SEAT	New	150.00	60.00
6	REMOVE AND REFIX REAR BOOT INTERIOR	New	150.00	50.00
7	REMOVE AND REPLACE REAR WINDSCREEN	New	150.00	120.00
8	REMOVE AND REPLACE REAR EXHAUST MUFFLER	New	120.00	-
9	ELECTRICAL AND WIRING CHECK	New	80.00	30.00
10	TO REMOVE & REFIX FUEL TANK	New	120.00	60.00
11	TO VACCUM & CLEAN INTERIOR CUSHION	New	150.00	-
12	TO STRAIGHTEN REAR CHASSIS MEMBER	New	250.00	-
Gross Labour Cost (S\$)			4,530.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >