

22/07/2007

ASS. REC. BY:

REF:

CS/FCI 18018849 / Ncd30

Special Instruction:

Surveyor:

CWS

Naz

ASSIGNMENT (Office)

From (Person):

Lurene juw

of

FCI

Date/Time:

17/10/18 @ 10.43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SQ 3277S

Insured:

SHA 0888E

at Workshop m/s

World Auto

Tel:

63621776

of

No. 1 Kranji Loop

Policy No:

Claim No:

D18007507MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/10/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

11.14am @ 17/10/18

Person Contacted:

Ainee

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SQ 3277S - X
	SHA 0888E - CC3 / TMT 16013777 / H/vbn 2
	Report IA thru email.

2018/07/07

128-1-10

REF:

FCI

Surveyor: NAZ

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X			
X	N/S	O/S	
X			

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 32773 Yr Regn: 4 JUL 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda SHUTLE HYBRID c.c. 1,496Colour: BLACK A/C: Insur. d / Std / NI / NASp. Reading: 99,344 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP710 44184Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185 / 60 R 15R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 15/10/18 D.O.A. 18/10/18Survey held at WORLD AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NAZ, PLS see my remarks. FCI PIP

18/12/18 FINALIZED PART BY PART REPAIR \$5106.00 / 6 DAYS

(Red 4118.08, 442)

RECEIVED DEC 2018

24110

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

S + RS: _____ SI

Photos

Others

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

Report Format: TPLump Sum / (B.I.): (\$ 5,106.00)

170
50
50
23
293

MOTOR SURVEY ASSIGNMENT

Date	16-10-2018	Our Ref No. D18007507MFSH
Accident Date	15-10-2018	Claim Type. Third Party
Insured Vehicle	SHA0888E	Third Party Vehicle. SLQ3277S
Survey Location	NO.1, KRANJI LOOP	
Contact Person.	AINEE	
Contact No.	63621776/ 0	Fax No. 63631250
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/245095)



PRI Documents



Close



PRI Header Details

Claim No	D18007507MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & WORLD A
Workshop Name	WORLD AUTO PTE LTD (Contact Person : AINEE)	Survey Location & Contact Details	NO.1, KRANJI LOOP Mobile: 0 , Phone: 63621776 , Fax: 63631250 EmailId: AINEE31@WORLD AUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0888E	TP Vehicle No	SLQ3277S
PRI Recieved Date	16-10-2018 07:10:21 PM	Surveyor Appointed Date	17-10-2018 10:42:31 AM	Surveyor Accept Date	17-10-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	17-10-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Your Ref: D18007507MFSHDate: 24 October 2018Our Ref: CS/FCI18018849/Nrd3The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 3277S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/10/2018 at the premises of M/s WORLD AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 9,224.08 .
Revised Estimate Amount	: S\$ 5,587.20 .
"Check" Items Amount	: S\$ 357.28 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the n/s body.



Yours faithfully

NAZRIL
Automotive Assessor

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLQ3277S
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	LEB4264159
Chassis No.:	GP71044184
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$22,445.00
Original Registration Date:	04 Jul 2017
First Registration Date:	04 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jul 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,106.00
COE Rebate Amount:	\$45,271.00
Total Rebate Amount:	\$49,021.00

The information contained herein is correct as at 24 Dec 2018

OK

SAT
FLI

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 15:28
Date Of Accident	15/10/2018 09:45
Exact Location Of Accident	MARINA BLVD & CHANJI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ3277S
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995070
Cover Note Number	

Driver

Name of Driver	CHUA KAI YI, DARREN
NRIC No	S8729194D
Date Of Birth	19/09/1987
Occupation	OUTDOOR
Date Of Driving Pass	05/11/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87878653
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NONAME GENDER: : FEMALE
Passenger 2	NAME: : NONAME GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA888E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A 2 Q 3 2 7 7 5

B 5 4 A 8 8 8 E



Sketch Plan #2

Describe Circumstances of the Accident

On 15/10/18 at about 0945hrs, along the junction of Marina Blvd turning towards Sheares Avenue heading towards ECP, an accident occurred.

I was travelling on lane 3 of Marina Blvd turning left onto Sheares Ave towards ECP when a yellow colour ComfortDelgro taxi went straight and knock onto the left side of my car. The impact left my vehicle to steer away. The taxi was going straight on a left turn only lane. At first point of accident, there were 2 female passenger sitting in the rear passenger seat.

Declaration

We declare the foregoing particulars are true in every respect.







Policyholder's Signature / Date & Time

[Signature] 11/15/18 15/10/18

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan #3



47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201897

Date : 15/10/2018

Vehicle Num. : SLQ 3277S (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 15/10/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT FENDER LH		489.90
2.	1	FRONT FENDER UNDER DUST COVER LH		192.00
3.	1	FRONT FENDER HYBRID EMBLEM LH		88.60
4.	1	FRONT DOOR - LH		1,050.00
5.	2	FRONT DOOR HINGE LH	110.00	220.00
6.	1	FRONT DOOR CHECKER LH		98.60
7.	1	FRONT DOOR INNER LOCK LH		280.00
8.	1	FRONT DOOR POWER WINDOW REGULATOR LH		420.00
9.	1	FRONT DOOR GLASS OUTER MOULDING LH		68.00
10.	1	REAR DOOR - LH		1,080.00
11.	1	REAR DOOR SUB RUBBER SEAL LH CENTRE		60.00
12.	1	ROCKER PANEL LH		320.00
13.	1	SIDE SKIRT LH		420.00
14.	1	FRONT FENDER DOOR SEAL MOULDING - LH		68.00
List TotalS\$:				4,855.10
20.00% Discount S\$:				971.02
				3,884.08
SPECIAL NETT ITEMS :				
1.	1SET	FRONT FENDER UNDER DUST COVER CLIPS		30.00
2.	1SET	FRONT DOOR INNER TRIM BOARD CLIPS		30.00
3.	1SET	REAR DOOR INNER TRIM BOARD CLIPS		30.00
4.	1SET	SIDE SKIRT CLIPS		30.00
Special Nett Total S\$:				120.00
LABOUR :				
TRANSFER DOOR MECHANISM (X2 DOORS)				360.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201897

Date : 15/10/2018

Vehicle Num. : SLQ 3277S (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 15/10/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY		180.00 ^{to high.}
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS		1,800.00 ^(1,100)
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)		1,600.00 ^{1,100}
		REMOVE INTERIOR UPHOLSTERY INCLUDING FRONT AND REAR CAR SEATS, FLOOR PANEL LINING, IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME		380.00 ³⁰⁰
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00 ^{too high}
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00 ³⁰⁰
		Labour Total S\$:		5,220.00

E. & O.E.

for WORLD AUTO PTE LTD

N42 LKK
18/10/18 1100
PIP
6 Days
- CHECK ITEM PHOTOS
- BEFORE PAINT PHOTOS

Total S\$: 9,224.08

LKK Auto Insurance notify the Repairer on the following:

- To resurvey or let spray painting
- To disassemble part(s) during resurvey
- Part price is subject to confirmation
- This party is on a "Without Prejudice" basis
- Further distribution(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201897

Date : 15/10/2018

Vehicle Num. : SLQ 3277S (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 15/10/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | | | |
|-----|---|--------------------------------------|--------|----------|
| 1. | 1 | FRONT FENDER LH | 480 | 489.90 |
| 2. | 1 | FRONT FENDER UNDER DUST COVER LH | | 192.00 |
| 3. | 1 | FRONT FENDER HYBRID EMBLEM LH | 80 | 88.60 |
| 4. | 1 | FRONT DOOR - LH | | 1,050.00 |
| 5. | 2 | FRONT DOOR HINGE LH | 110.00 | 220.00 |
| 6. | 1 | FRONT DOOR CHECKER LH | | 98.60 |
| 7. | 1 | FRONT DOOR INNER LOCK LH | | 280.00 |
| 8. | 1 | FRONT DOOR POWER WINDOW REGULATOR LH | | 420.00 |
| 9. | 1 | FRONT DOOR GLASS OUTER MOULDING LH | 60 | 68.00 |
| 10. | 1 | REAR DOOR - LH | DP | 1,080.00 |
| 11. | 1 | REAR DOOR SUB RUBBER SEAL LH CENTRE | DP | 60.00 |
| 12. | 1 | ROCKER PANEL LH | BT | 320.00 |
| 13. | 1 | SIDE SKIRT LH | | 420.00 |
| 14. | 1 | FRONT FENDER DOOR SEAL MOULDING - LH | 41 | 68.00 |

List TotalS\$:

20.00% Discount S\$:

3,170	4,855.10
1,634	971.02
2,536	3,884.08

SPECIAL NETT ITEMS :

- | | | | | |
|----|------|-------------------------------------|-----|-------|
| 1. | 1SET | FRONT FENDER UNDER DUST COVER CLIPS | | 30.00 |
| 2. | 1SET | FRONT DOOR INNER TRIM BOARD CLIPS | NEC | 30.00 |
| 3. | 1SET | REAR DOOR INNER TRIM BOARD CLIPS | NEC | 30.00 |
| 4. | 1SET | SIDE SKIRT CLIPS | | 30.00 |

Special Nett Total S\$:

90	120.00
----	--------

LABOUR :

TRANSFER DOOR MECHANISM (X2 DOORS)

100	360.00
120	

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201897

Date : 15/10/2018

Vehicle Num. : SLQ 3277S (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 15/10/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY		180.00
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	900	1,800.00
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	900	1,600.00
		REMOVE INTERIOR UPHOLSTERY INCLUDING FRONT AND REAR CAR SEATS, FLOOR PANEL LINING, IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME		380.00
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	250	450.00
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)	250	450.00
		Labour Total S\$:		5,220.00
		PARTS \$3,170		
		LESS 20% \$2,536		
		NETT \$ 90		
		LABOUR \$2,480		
		TOTAL \$5,106 / 6 DAYS		
		E. & O.E.	Total S\$:	9,224.08

for WORLD AUTO PTE LTD

NA2 LKK

18/10/18 1100

PIP

6 DAYS

- CHECK ITEM PHOTOS

- BEFORE PAINT PHOTOS

Rong by paint
19/10/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18018849/Ncd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-12-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 888E	Veh. Inspected	SLQ 3277S
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18007507MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	17/10/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71044184	Colour	BLACK
Odometer	99344	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	PIRELLI	5 mm
L/H Front Tyre	185/60 R15	PIRELLI	5 mm
R/H Rear Tyre	185/60 R15	PIRELLI	5 mm
L/H Rear Tyre	185/60 R15	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/10/2018	Inspection Date	18/10/2018
Survey held at	NO. 1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 3277S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER LH	CRACKED	489.90	480.00
1	FRONT FENDER UNDER DUST COVER LH	SERVICEABLE	192.00	-
1	FRONT FENDER HYBRID EMBLEM LH	NECESSARY	88.60	80.00
1	FRONT DOOR - LH	DEFORMED	1,050.00	1,050.00
2	FRONT DOOR HINGE LH @\$110.00	TO REPAIR SEE LABOUR	220.00	-
1	FRONT DOOR CHECKER LH	TO REPAIR SEE LABOUR	98.60	-
1	FRONT DOOR INNER LOCK LH	SERVICEABLE	280.00	-
1	FRONT DOOR POWER WINDOW REGULATOR LH	SERVICEABLE	420.00	-
1	FRONT DOOR GLASS OUTER MOULDING LH	NECESSARY	68.00	60.00
1	REAR DOOR - LH	DENTED	1,080.00	1,080.00
1	REAR DOOR SUB RUBBER SEAL LH CENTRE	NOT NECESSARY	60.00	-
1	ROCKER PANEL LH	TO REPAIR SEE LABOUR	320.00	-
1	SIDE SKIRT LH	CRACKED	420.00	420.00
1	FRONT FENDER DOOR SEAL MOULDING - LH	NOT NECESSARY	68.00	-
	LESS 20% DISCOUNT		-971.02	-634.00
			3,884.08	2,536.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT FENDER UNDER DUST COVER CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET FRONT INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	SET SIDE SKIRT CLIPS (SN)	NECESSARY	30.00	30.00
			120.00	90.00
<u>LABOUR</u>				
	TRANSFER DOOR MECHANISMS (X2 DOORS)		360.00	100.00
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	80.00

Report Ref No. CS/FCI18018849/Ncd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGE LH, FRONT DOOR CHECKER LH AND ROCKER PANEL LH.	NOT NECESSARY	1,800.00	900.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER / OUTER)		1,600.00	900.00
	REMOVE INTERIOR UPHOLSTERY INCLUDING FRONT AND REAR CAR SEATS, FLOOR PANEL LINING, IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME.		380.00	-
	DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	250.00
	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	250.00
			5,220.00	2,480.00
GRAND TOTAL			9,224.08	5,106.00
RECOMMENDED COST OF REPAIRS				5,106.00

Report Ref No. CS/FCI18018849/Ncd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.