

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

SURVEYOR COPY

Claim Reference:
Assessment Number: AH000954
Version: AHLIM001/1
Date Calculated: 16/10/2018 03:45

Full Report - V1
Registration: SLJ8775A
Printed: 16/10/2018 10:46

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ahlim ahlim	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:


Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	BASE MODEL
Model Sheet Number:	HVE 01
Registration:	SLJ8775A
Registration Month:	December
Registration Year:	2016
VIN Number:	RU11108064
Manufacture Year:	2015
Odometer:	Not Known
Colour:	
Engine Number:	L15B4028030
Fuel Level:	%

Model Specs

FOG LAMPS	1.5 LTR 88KW
TWO COAT METALLIC	PREPARE OFF VEHICLE





6 days

Not Authorised
I.B.I
Assessing B4 paint
Ex 8500.
Ex: 62564315

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	16/10/2018
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

Ah Lim Motor Company**Claim Reference:****Assessment Number: AH000954****Version: AHLIM001/1****Date Calculated: 16/10/2018 03:45****Full Report - V1****Registration: SLJ8775A****Printed: 16/10/2018 10:46****Addresses****Cost Summary**

Total Labour	\$1,084.50
Total Paint/Material	\$231.09
Total Parts	\$4,716.80
Total of Additional Costs	\$215.00
Excess:	TBA
Grand Total Exc GST:	\$6,247.39
7 % GST:	\$437.32
Grand Total Inc GST:	\$6,684.71

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	RENEW FRONT PANEL	32.0	144.00
8101A2B	RENEW FRONT BUMPER	15.0	67.50
813110)	RENEW RADIATOR GRILLE	3.0	13.50
812100	RENEW BONNET	11.0	49.50
	INCLUDES: R + R BONNET AND		
	REQUIRED ATTACHED PARTS ASSEMBLE		
NO NUMBER	R + R BOTH FRONT WINGS	17.0	76.50
	(BUMPER REMOVED)		
	INCLUDES: R + R FRONT HEADLAMPS,		
	SILL COVER AND REQUIRED		
	ATTACHED PARTS.		
7421B0)	R + R WASHER RESERVOIR	2.0	9.00
8131B3	R + R L/ENGINE COMPARTMENT PROTECTION	3.0	13.50
8131B4	R + R R/ENGINE COMPARTMENT PROTECTION	3.0	13.50
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	
NO NUMBER	RIGHT FRONT WING RUST PROOFING	1.0	
8571G3	R + R LEFT LOWER A-PILLAR TRIM	1.0	4.50
710100	R + R BATTERY	3.0	13.50
1211E1	R + R AIR FILTER INTAKE PIPE	2.0	9.00
1141G7)	R + R RADIATOR	12.0	54.00
616100)	R + R CONDENSER	2.0	9.00
620020	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
4211A6	R + R R/F WHEEL	2.0	9.00
1482	REPAIR RIGHT FRONT DOOR	10.0*	45.00

LABOUR COST**Total Work Units**

128.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Ah Lim Motor Company**Claim Reference:****Assessment Number: AH000954****Version: AHLIM001/1****Date Calculated: 16/10/2018 03:45****Full Report - V1****Registration: SLJ8775A****Printed: 16/10/2018 10:46**

Sub Total
Paint Labour
Total Labour

12.5HRS **\$562.50**
11.6HRS **\$522.00**
24.1HRS **\$1,084.50**

PAINT WORK**Time Basis 10 WU = 1 HR. Price = \$45.00/HR****Guide Number Description****WU****Cost Price (\$)**

- TWO COAT METALLIC
 - PREPARE OFF VEHICLE
 471 BONNET NEW PART PAINTING
 742 R/F WING NEW PART PAINTING
 1009 FRONT PANEL CPL SURFACE PAINT
 283 FRONT BUMPER NEW PART PAINT K1R
 300 FRT TOWING EYE COVER NEW PART PAINT K1R
 424 RAD GRILLE COVER NEW PART PAINT K1R
 1482 RIGHT FRONT DOOR REPAIR PAINTING >50%
 741 L/F WING SURFACE PAINT

21.0
9.0
6.0
10.0
3.0
5.0
27.0
5.0

LABOUR COST - PAINT**TIME(PAINT)****86.0****Preparation Main Work Plastic****5.0****Preparation Main Work Metal****25.0****Preparation Work Multi Layer Paint****0.0****Total Work Units (10WU/HR)****116.0****Total Paintwork Labour****11.6HRS****\$522.00****MATERIAL COST - PAINT****Cost Price****New Part Painting****\$81.53****New Part Painting - Plastic K1R****\$55.11****Material-Constant Main Work Metal****\$28.60****Surface-/Blend Paint****\$18.93****Repair Painting****\$37.92****Material-Const Main Work Plastic****\$9.00****Total Excluding Pearlescent Uplift****\$231.09****Pearlescent Uplift @ 0.0%****\$0.00****Total Paint Material Cost****\$231.09****PARTS**

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
282	1	FRONT LOWER BUMPER	04712T7WA90		0%	150.00*
283	1	FRONT BUMPER	71101T8NT00ZZ		0%	210.00*
300	1	FRT TOWING EYE COVER	71104T7A000ZR		0%	12.00*
319	1	L/F UPP BUMPER BRKT	71198T7A000		0%	12.00*
320	1	R/F UPP BUMPER BRKT	71193T7A000		0%	12.00*
340	1	FRT BUMPER SUPPORT	71130T8NT00ZZ		0%	210.00*
344	1	R/BUMPER CORNER BRKT	71140T7A000		0%	25.00*
345	1	L/F AIR DUCT	71116T8NT50		0%	25.00*
346	1	R/F AIR DUCT	71111T8NT50		0%	25.00*
351	1	LOWER FRONT GRILLE	71103T7JH00		0%	50.00*
410	1	GRILLE	71121T8NT50		0%	200.00*
413	1	RAD GRILLE BRACKET	71150T7JH00		0%	25.00*
416	1	R/RAD-GRILLE BRACKET	71151T7JH00		0%	12.00*
424	1	RAD GRILLE COVER	71122T8NT50		0%	150.00*
431	1	GRILLE BADGE	75700TA0A00		0%	20.00*

Ah Lim Motor Company**Claim Reference:****Assessment Number: AH000954****Version: AHLIM001/1****Date Calculated: 16/10/2018 03:45****Full Report - V1****Registration: SLJ8775A****Printed: 16/10/2018 10:46**

471	1	BONNET	60100T8NT00ZZ	0%	400.00*	✓
485	8	INSULATION MNTG KIT	91501SWA003	0%	20.00*	✓
492	1	BONNET LOCK	74120T7WA01	0%	70.00*	✓
562	1	R/F HEADLAMP CPL	33100T7SE51	0%	820.00*	✓
638	1	R/F FOG LAMP	33900SLEJ51	0%	150.00*	✓
650	1	R/FOG LAMP COVER	71105T7JH00	0%	20.00*	✓
742	1	R/F WING	60210T8NT00ZZ	0%	200.00*	✓
788	1	R/WING MOULDING	74107T7MH01	0%	50.00*	✓
790	5	R/F WING CLAMP KIT	934050601608	0%	20.00*	✓
1009	1	FRONT PANEL CPL	60400T8NT00ZZ	0%	330.00*	✓
4465	1	CONDENSER	80110T7AJ01	0%	350.00*	✓
7761	1	RADIATOR	1901052XZ51	0%	720.00*	✓
f: OEM Parts			Sub Total		\$4,288.00	
g: Original			Mark Up From Cost (10 %)		\$428.80	
h: Secondhand			Total Parts		\$4,716.80	
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
COOLANT	0%	\$30.00
NO. PLATE		\$35.00
CHK WIRING	0%	\$30.00
A/C GAS		\$120.00
Total Extras		\$215.00

Final Calculation

Total Parts	\$4,716.80
Labour	
Total Panel/Mechanical	\$562.50
Total Paintwork	\$522.00
Total Labour	\$1,084.50
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$215.00
Total of Additional Costs	\$215.00
Total Paint/Material Costs	\$231.09
Grand Total Excludes GST	\$6,247.39
GST @ 7 %	\$437.32
Grand Total Includes GST	\$6,684.71

Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: