

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 636A**AAD1810-149***Not Authorized
Resurvey By painting*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 636A

VF1ABL15AUC283390

RENAULT

LATITUDE

11.10.2018

CHINA TAIPING**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Buck</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>not</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>AK</i> 777.52	? NN
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>AK</i> 225.95	} X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>AK</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>AK</i> 1,471.77	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56	
15	1 TAILLAMP RH	\$	<i>SL</i> 552.55	
16	1 TAILLAMP PANEL RH	\$	<i>AK</i> 986.70	
17	1 TAILLAMP LH	\$	<i>SL</i> 552.55	
18	1 TAILLAMP PANEL LH	\$	<i>AK</i> 986.70	
19	1 BOOT REAR	\$	<i>AK</i> 2,872.68	
20	1 BOOT FINISHER	\$	<i>SL</i> 470.06	
21	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	
22	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	
23	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	
24	1 BOOT BADGE 'RENAULT'	\$	<i>AK</i> 225.36	
25	1 BOOT BADGE	\$	<i>AK</i> 225.36	
26	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	
27	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
28	1 BOOT HINGE LH	\$	<i>AK</i> 367.84	
29	1 BOOT HINGE RH	\$	<i>AK</i> 367.84	

Trans-cab Auto Services Pte Ltd

AAD1810-149

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 636A

30	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	<i>X</i>
31	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	<i>X</i>
32	1 BOOT LOCK	\$	<i>n</i> 202.67	<i>X</i>
33	1 BOOT LOCK CATCH	\$	<i>n</i> 74.40	<i>X</i>
		\$	16,046.87	
		10% \$	7.44	
		\$	16,039.43	

Special Nett

1	1SET PARKING AID	\$	<i>Sn</i> 700.00	<i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>nn</i> 66.00	<i>—</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00	<i>—</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00	<i>X</i>
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00	<i>X</i>
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00	<i>X</i>
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 20.00	<i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00	<i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00	<i>—</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	<i>X</i>
11	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	<i>X</i>
12	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	<i>X</i>
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	<i>X</i>

TOTAL \$ 1,244.82**TOTAL PARTS \$ 17,284.25****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	<i>2200</i> 3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>2000</i> 2,200.00

Trans-cab Auto Services Pte Ltd

AAD1810-149

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 636A

To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
TOTAL	\$	6,610.00

Over All Total	\$	39,933.69
-----------------------	-----------	------------------

22,296.99

(PART-BY-PART)**Repair Days****10-DAYS**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: