

ASS. REC. BY:

REF:

CS/SPF18018868 / A + ber

Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): Koh Kim Seng of SPF Date/Time: 17.10.2018Estimated Cost: Bill to: **OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**To Inspect Vehicle No: SDT 1070M Insured: Public Liabilityat Workshop m/s Premium Carz Tel: 6636 9100of Blok 1 Kaki Bukit Ave 6 #01-90Policy No: Claim No: 17/20181014 / 2000Sum Insured: Excess: Make of Veh: D.O.A. 14.10.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 17.10.2018 1.53pm Person Contacted: Candys H.O.D. Endorsement: Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SDT 1070M - x
	Public liability - x
	Submit lump sum \$2350/- (Red: 6902 4575.68, 66%)
	Range Repair \$2000/- - \$3000/-

REF:

ASSIGNMENT

31/01/08.

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDT1070M.Yr Regn: 2008 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Stream.C.C. 1799Colour: Brown.

A/C: Insured / Std / NI / NA

Sp. Reading: 157399.

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRN68408S200590Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16.R: 205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06. mm

D.O.A. _____

D.O.I. 17/10/18.Survey held at Premium Carz.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP SPF.

COE Expiry: 30/01/23.

RECEIVED 30 NOV 2018

Date/Time, File Pass to?

1) 29/11 Typist ☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 280

Transportation

Photos

Others

TOTAL

280Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) 23701-



SINGAPORE POLICE FORCE

PCG Logistics & Admin Branch
Police Coast Guard
No. 11 Brani Way
Singapore 098658

Our Ref : M/20181014/2000

Tel: 63767036

Date : 17 October 2018

Fax: 63767119

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

RTA ON 14 OCTOBER 2018 INVOLVING VEH SDT 1070M AND ANTI-DASH BOLLARD INSIDE POLICE COAST GUARD BRANI BASE

We refer to the above matter.

- 2 Please arrange for a Pre Repair Inspection of vehicle no. SDT 1070M at Premium Carz Services Pte Ltd of 1 Kaki Bukit Avenue 6 #01-90, Autobay@Kaki Bukit, Singapore 417883.
- 3 For appointment please contact Logesh (98164317 / 91860532).
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours sincerely,

Koh Kim Seng
Logistics Officer
for Head Logistics and Admin (PCG)

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/10/2018 16:37
Date Of Accident	14/10/2018 00:05
Exact Location Of Accident	11 BRANI WAY PCG HEADQUARTERS BRANI BASE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDT1070M
Insured/Policyholder	
Name Of Registered Owner	LOGESH RANGANATHAN
NRIC No	S8424844D
Email Address	LOGESH_84@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91860532
Alternative Phone No	OTHERS-91860532

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM SUNROOF 1.8L A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV201800003281
Cover Note Number	N.A

Driver

Name of Driver	LOGESH RANGANATHAN
NRIC No	S8424844D
Date Of Birth	18/08/1984
Occupation	INDOOR
Date Of Driving Pass	16/12/2009
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91860532
Fax Number	
Contact Number	OTHERS-91860532
Email Address	LOGESH_84@HOTMAIL.COM

Address	HDB SEGAR PALMVIEW, 550A SEGAR ROAD #18-612
Postcode	671550
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TAN HAO ZHE GENDER: : MALE
Passenger 2	NAME: : BERNAND CHIA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	PCG BRANI BASE
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to Police Report Ref: M/20181014/2000 lodged at PCG Brani Base. On 14 Oct 2018 at about 0005hrs, informant left base from PCG Brani carpark heading towards Brani maingate to proceed home. Suddenly he hit on the bollard which in the process of rising up. There is no traffic controller or blinkers to acknowledge that the bollard being rise up. Informant was travelling at required speed limit, 30km/h. The informant car, Honda Stream (SDT 1070M), have damaged and dent on the front bumper due to the collision with the bollard.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	BOLLARD
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



**VERIFIED BY AJAX MARS
REPORTING OFFICER**


Muhammad Faizal

Bin Pabla

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre
Personnel

Sketch Plan

Police Report



**SINGAPORE
POLICE FORCE**



M/2018/1014/2000

1 of 2

POLICE REPORT (NP299)

Report No. M/2018/1014/2000

Police Station Of Origin
PCG Brani Base
11 Brani Way SINGAPORE 098658
Tel No: 63750000

Date/Time Report Made 14/10/2018 01:00		Vide Report No.		Station Diary No.	
Name Of Informant Logesh Ranganathan		Address APT BLK 550A SEGAR ROAD #18-612 SEGAR PALMVIEW SINGAPORE 671550			
ID Type / ID No. NRIC NO / S8424844D		Contact No. Home/Office		Mobile 95164317	
Nationality SINGAPORE CITIZEN		Email Address			
Occupation Itio		Sex Male	Age 34	Date of Birth 18/08/1984	Race Indian
Institution/School Name		Language			
Date/Time Of Incident 14/10/2018 00:05 - 14/10/2018 00:06		Location Of Incident 11 BRANI WAY PCG HEADQUARTERS BRANI BASE* SINGAPORE 098658			

Brief details.

On 14 October 2018 at about 0005hrs informant left base from PCG Brani carpark heading towards Brani maingate to proceed home. Suddenly he hit on the bollard which was in the process of rising up. There is no traffic controller or blinkers to acknowledge that the bollard being rise up. Informant was travelling at required speed limit, 30km/h. The informant car, Honda Stream (SDT 1070 M), have damaged and dent on the front bumper due to the collision with the bollard.

Signature Of Officer Recording The Report: PCG / Insp YAP ENG SIANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/10/2018 01:00
Officer In-Charge Of Case PCG / PCG Brani Base / Sr Staff Sgt MOHAMMAD NUREMI BIN KAMSANI Contact No.: 65463205	Classification Of Case:

Authentication Stamp

SINGAPORE
POLICE FORCE

M/20181014/2000

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. M/20181014/2000

Subjects involved

Victim

Person Name Logesh Ranganathan (Informant)

Signature Of Officer Recording The Report:

PCG / Insp YAP ENG SIANG

Signature Of Interpreter:
Not applicableOfficer In-Charge Of Case:
PCG / PCG Brani Base /
Sr Staff Sgt MOHAMMAD NUREMI BIN KAMSANI
Contact No. 65463205

Authentication Stamp



Signature Of Informant:

Date/Time:
14/10/2018 01:00

Classification Of Case:

Date : 15/10/2018

TO: PCG Logistics & Admin Branch
Police Coast Guard
No. 11 Brani Way
Singapore 098658

Tel: 6376 7036

Fax: 6376 7119

TPSPF

Denise

Our Customer : Logesh Ranganathan

Vehicle No : SDT1070M

Model : Honda Stream

Manufacture Year : 2008

Date of Accident : 14/10/2018

Total Estimate Repair Days : 7

Total Pages : 2

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper <i>Detached</i>	1	\$826.30	\$826.30	683.
2	Front bumper side retainer RH <i>3mm</i>	1	\$29.50	\$29.50	✓
3	Front bumper side retainer LH <i>3mm</i>	1	\$29.50	\$29.50	✓
4	Front bumper lower grille <i>Detached</i>	1	\$132.60	\$132.60	✓
5	Front support panel <i>7 Repairs</i>	1	\$782.50	\$782.50	✓
6	Fog lamp garnish RH <i>3mm</i>	1	\$121.00	\$121.00	✓
7	Fog lamp garnish LH <i>3mm</i>	1	\$121.00	\$121.00	✓
8	Radiator <i>Here</i>	1	\$1,716.10	\$1,716.10	✓
9	Air-con condenser <i>Painted</i>	1	\$1,131.10	\$1,131.10	✓
10	Air-con condenser mounting bracket <i>Here</i>	2	\$35.00	\$70.00	✓
11	Engine under cover <i>Here</i>	1	\$285.00	\$285.00	✓
	Total			\$5,244.60	
			Less 20%	\$1,048.92	
	Sub Total 1			\$4,195.68	
A.	Spare Parts (S/Nett)				
1	Coolant <i>Here</i>	1	\$60.00	\$60.00	40
2	Front bumper clip <i>m</i>	10	\$4.50	\$45.00	30
3	Engine under cover clip <i>m</i>	10	\$4.50	\$45.00	30
4	Front bumper lower lid <i>Detached</i>	1	\$350.00	\$350.00	✓
	Sub-Total 2			\$500.00	
	Total for Parts			\$4,695.68	
B.	Labour				
1	To check wiring and refocus headlamp.			\$60.00	✓
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$600.00	400
3	Spray painting all affected parts & areas.			\$700.00	400
4	To spray anti-rust undercoat.			\$90.00	✓
5	To remove and replace damaged air-con condenser; to vacuum and charge up gas.			\$250.00	60
6	To remove and replace damaged radiator and to conduct pressure test.			\$250.00	60
7	To remove and replace front support panel.			\$280.00	✓
	Total Labour			\$2,230.00	
	Total Repair Cost			\$6,925.68	

920



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 2974.56.
L/S: 2350 ✓
04 Days.

2-3K
Strange Repair




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18018868/Atbe2		
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333 ATTN : KOH KIM SENG		Date : 03-12-2018		
		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SDT 1070M	
Policy No.		Coverage (\$)	0.00	
Claim No.	M/20181014/2000	Excess (\$)	0.00	
Assign From	KOH KIM SENG	Assign Date	17/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMRN68408S200590	Colour	BROWN	
Odometer	157399	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/10/2018	Inspection Date	17/10/2018	
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDT 1070M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	826.30	683.00
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	29.50	29.50
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	29.50	29.50
1	FRONT BUMPER LOWER GRILLE	DEFORMED	132.60	132.60
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	782.50	-
1	FOG LAMP GARNISH RH	NOT NECESSARY	121.00	-
1	FOG LAMP GARNISH LH	NOT NECESSARY	121.00	-
1	RADIATOR	NOT NECESSARY	1,716.10	-
1	AIR-CON CONDENSER	DENTED	1,131.10	1,131.10
2	AIR-CON CONDENSER MOUNTING BRACKET @\$35.00	NOT NECESSARY	70.00	-
1	ENGINE UNDER COVER	NOT NECESSARY	285.00	-
	LESS 20% DISCOUNT		-1,048.92	-401.14
			4,195.68	1,604.56
<u>SPECIAL NETT ITEMS</u>				
1	COOLANT (SN)	NECESSARY	60.00	40.00
10	FRONT BUMPER CLIP @\$4.50 (SN)	NECESSARY	45.00	30.00
10	ENGINE UNDER COVER CLIP @\$4.50 (SN)	NECESSARY	45.00	30.00
1	FRONT BUMPER LOWER LID (SN)	DEFORMED	350.00	350.00
			500.00	450.00
<u>LABOUR</u>				
	TO CHECK WIRING AND REFOCUS HEADLAMP.	NOT NECESSARY	60.00	-
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		600.00	400.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		700.00	400.00
	TO SPRAY ANTI-RUST UNDERCOAT.	NOT NECESSARY	90.00	-
	TO REMOVE AND REPLACE DAMAGED AIR-CON CONDENSER; TO VACUUM AND CHARGE UP GAS.		250.00	60.00
	TO REMOVE AND REPLACE DAMAGED RADIATOR AND TO CONDUCT PRESSURE TEST.		250.00	60.00
	TO REMOVE AND REPLACE FRONT SUPPORT PANEL.	NOT NECESSARY	280.00	-
			2,230.00	920.00
GRAND TOTAL			6,925.68	2,974.56

Report Ref No. CS/SPF18018868/Atbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,350.00
---	--	--	----------

Report Ref No. CS/SPF18018868/Atbe2

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.