

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5910E - DOA 11.10.2018**AAD1810-148***Not Authorised*
61 Sep 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5910E

VF1ABL15AUC281430

RENAULT

LATITUDE

11.10.2018

III

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Buc / cm</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>DIT</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	TOW COVER FRT	\$	<i>SL</i> 28.61
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22
1	HORN	\$	<i>SL</i> 314.17
1	HORN BRACKET	\$	<i>R</i> 40.45
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43 ✓
1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>DIT</i> 278.84 ✓
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84 X
1	AUTO COMPUTER	\$	<i>SL</i> 5,032.17 X
1	INJECTION COMPUTER	\$	<i>SL</i> 4,706.30 X
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	<i>SL</i> 5,154.52 X
1	STEERING PUMP ELECTRIC	\$	<i>SL</i> 2,306.90 X

Trans-cab Auto Services Pte Ltd**AAD1810-148**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5910E - DOA 11.10.2018

1	STEERING PINION RACK	\$	4,413.11	?
1	DOOR HARNESS WIRE	\$	Sn 2,670.00	}
1	DOOR WAIST SEAL OUTER FRT RH L70Y (DOOR CHROME)	\$	Sn 291.27	
1	DOOR GLASS FRT RH L70Y	\$	Sn 625.96	
1	DOOR PANEL FRT LH	\$	N 2,844.66	
1	DOOR HINGE UPPER LH L70Y	\$	N 261.28	
1	DOOR HINGE LOWER LH	\$	N 300.55	
1	DOOR CHECK FRT LH	\$	Sn 194.77	
1	DOOR CHECK BOLT	\$	Sn 22.69	
1	DOOR LOCK FRT LH	\$	N 908.75	
1	DOOR CATCH FRT LH	\$	Sn 131.23	
1	DOOR HANDLE OUTER FRT LH	\$	Sn 477.76	
1	DOOR HANDLE COVER FRT LH	\$	Sn 13.22	
1	DOOR HANDLE MODULE FRT LH	\$	Sn 133.60	
1	DOOR REGULATOR FRT LH	\$	N 505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	Sn 796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	Sn 120.97	
1	DOOR FINISHER FRT RH L70Y	\$	Sn 515.06	
1	DOOR MOULDING FRT RH L70Y	\$	Sn 176.82	
1	FENDER PANEL REAR LH	\$	N 3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	Sn 671.45	} X
1	WHEELARCH REAR LH	\$	Sn 543.47	
1	BUMPER COVER REAR	\$	N 1,108.46	
1	BUMPER LOWER REAR	\$	Sn 768.84	
1	BUMPER BRACKET CTR REAR	\$	N 113.47	
1	BUMPER RETAINER LH REAR	\$	Sn 44.99	
1	BUMPER BEAM REAR	\$	N 777.52	
1	BUMPER BEAM BRACKET LH REAR	\$	Sn 225.95	
1	DOOR MIRROR ASSY LH	\$	Sn 1,483.40	
1	TAILLAMP LH	\$	Sn 552.55	
1	ROCKER PANEL INNER GARNISH LH	\$	Sn 466.51	
1	ROCKER PANEL INNER LH	\$	N 1,024.79	
1	ROCKER PANEL CENTER LH	\$	N 990.25	
1	BONNET	\$	N 1,941.63	
1	BONNET INSULATOR	\$	Sn 405.73	
1	BONNET STRUT LH	\$	Sn 88.61	
1	BONNET STRUT RH	\$	Sn 88.61	
1	BONNET HINGE LH	\$	N 348.31	
1	BONNET HINGE RH	\$	N 348.31	
1	BONNET LOCK	\$	N 305.48	

Trans-cab Auto Services Pte Ltd**AAD1810-148**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5910E - DOA 11.10.2018

1	BONNET CABLE	\$	Sh	119.19	X
1	BONNET CABLE COVER	\$	Sh	161.03	X
1	BONNET SEAL OUTER	\$	Sh	92.36	X
1	BONNET SEAL INNER	\$	Sh	157.28	X
1	LOWER ARM LH L70Y	\$		685.76	?
1	KUNCKLE ARM LH L70Y	\$	Sh	846.98	✓
1	ABSORBER FRT LH L70Y	\$		360.54	?
1	SUBFRAME OUTER FRT L70Y	\$		2,652.45	?
1	SUBFRAME INNER FRT L70Y	\$	Sh	2,284.80	X
1	STABILIZER BAR FRT L70Y	\$	Sh	604.65	X
2	STABILIZER LINK FRT L70Y	\$		117.22	?
		\$		68,611.95	
		10% \$		6,861.20	
		\$		61,750.76	

Specical Nett

1SET	BUMPER CLIP FRT	\$	Sh	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	Sh	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	Sh	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	Sh	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Sh	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	Sh	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	Sh	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	Sh	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	Sh	80.00	60.00
1	FRONT DOOR STICKER 'Chassis'	\$	Sh	50.00	30.00
1	REAR DOOR STICKER '6555 3333'	\$	Sh	80.00	X
1	DOOR CHECK BOLT	\$	Sh	22.69	X
1	DOOR GUIDE SCREW	\$	Sh	10.85	X
1	DOOR HINGE BOLT	\$	Sh	10.85	X
1	DOOR HINGE NUT RH	\$	Sh	14.60	X
1	DOOR CHECK BOLT	\$	Sh	22.69	X
1	DOOR CHECK NUT	\$	Sh	3.75	X
1	DOOR LOCK SCREW L70Y	\$	Sh	6.12	X
1	DOOR CATCH SCREW L70Y	\$	Sh	10.06	X
1	FRONT LEFT TYRE	\$	Sh	330.00	200.00
1	FRONT LEFT TYRE RIM	\$	Sh	380.00	✓

Trans-cab Auto Services Pte Ltd

AAD1810-148

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5910E - DOA 11.10.2018

TOTAL	\$	1,329.63
-------	----	----------

TOTAL PARTS	\$	63,080.39
-------------	----	-----------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	9,000.00 <i>500</i>
Towing Fees.	\$	120.00 <i>50</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	9,000.00 <i>600</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>60</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>20</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1810-148

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5910E - DOA 11.10.2018

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
To remove and refit air bag system and reset.	\$	~ 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00 X
To replace, refix and top up coolant for radiator	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X

TOTAL	\$	23,170.00
--------------	-----------	------------------

Over All Total	\$	86,250.39
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~30 DAYS~~

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: