

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9735M**AAD1810-157***Not Authorised
L/Sing @ 1800/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9735M

VF1ABL15AUC276138

RENAULT

LATITUDE

14.10.2018

AIG

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 X
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70
19	1 BOOT REAR	\$	<i>R</i> 2,872.68
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
25	1 BOOT BADGE	\$	<i>na</i> 225.36
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84

Trans-cab Auto Services Pte Ltd**AAD1810-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9735M

30	1 BOOT INNER TRIM	\$	586.45	X
31	1 BOOT SWITCH	\$	168.13	X
32	1 BOOT LOCK	\$	202.67	X
33	1 BOOT LOCK CATCH	\$	74.40	X
		\$	16,046.87	
		10% \$	7.44	
		\$	16,039.43	

Special Nett

1	1SET PARKING AID	\$	700.00	X
2	1SET REAR BUMPER CLIP	\$	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	} X
5	1SET BUMPR RETAINER RH CLIP RR	\$	20.00	
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	10.00	
7	1SET BUMPR RETAINER CLIP LH RR	\$	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	66.00	
10	1 EXHAUST MOUNTING REAR	\$	17.82	
11	2 REAR WINDSCREEN SELANT	\$	80.00	
12	1 WINDSCREEN MOULDING	\$	100.00	
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	

TOTAL \$ 1,244.82**TOTAL PARTS \$ 17,284.25****LABOUR**Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *2200*

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ 2,200.00 *2000*

Trans-cab Auto Services Pte Ltd**AAD1810-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9735M

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>bol</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>

TOTAL \$ 6,610.00**Over All Total \$ 39,933.69****(LUMP SUM)****Repair Days****~~10~~ DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: