CRUISE AUTOCARE PTE LTD

ESTIMATE

MS: AIG ASIA PACIFIC INSURANCE PTE. LTD.

TO: CLAIM DEPARTMENT

Fax: 6835 7416

Xiao Tony

Quotation No:

QCA160190

Quote Date:

16-Oct-18

Contact No:

68416760

Fax No:

68413527

			1 ax 110.		0413327
	SBT2679A		Make / Model:		IDA VEZEL
<u>S/N.</u>	<u>Description</u>		LIST PRICE -	Qty	<u>Amount</u>
1	PARTS REAR TAILGATE PISCH		¢050.00		0050.00.
2	REAR TAILGATE TRIM BOARD REL		\$953,30 \$153,40	1	\$953.30
3	REAR WINDSCREEN MOULDING		\$48.00	1 4	\$153.40
4	REAR TAILGATE WEATHERSTRIP		\$108.00	1	\$192.00 \$108.00
5		. 24 10	\$48.60	1	
6	REAR TAILGATE HINGE IN J	4724.10	\$48.60	1	\$48.60 × \$48.60 ×
7	REAR TAILGATE ABSORBER, RH 7ML A		\$180.00	1	\$180.00 £
8	REAR TAILGATE ABSORBER, LH	7/10 10	\$180.00	1	\$180.00 \$
9	REAR TAILGATE EMBLEM, VEZEL	3619.28	\$64.00	1	\$64.00
10	REAR TAIL GATE REFLECTOR DH CUT		\$264.60	1	\$264.60
11	REAR TAILGATE UPPER LOCK		\$157.10	1	\$157.10
12	REAR TAIL LAMP, RH		\$428.70	1	\$428.70
13	REAR END PANEL DISCLE		\$365.70	1	\$365.70
14	REAR END PANEL TOP GARNISH		\$92.30	1	\$92.30
15	SPARE TYRE COMPARTMENT SASSALL		\$662.30	1	\$662.30
16	SPARE TYRE LOWER COVER 90	e i	\$190.00	1	\$190.00
17	ANTENNA RECEIVER (KEYLESS ENTRY AT REAR EN	D PANEL) Guld	\$58.10	1	\$58.10
18	REAR BUMPER & Store		\$508.50	1	\$508.50
19	REAR BUMPER REFLECTOR, RH &		\$141.10	1	\$141.10 -
20	REAR BUMPER REFLECTOR, LH ~~		\$141.10	1	\$141.10 K
21	REAR BUMPER RETAINER, RH 2		\$17.50	1	\$17.50
22	REAR BUMPER RETAINER, LH		\$17.50	1	\$17.50
23	REAR BUMPER SIDE, RH		\$150.00	1	\$150.00
24	REAR FENDER INNER SHIELD, RH		\$90.40	1	\$90.40 f
25	REAR FENDER PROTECTOR, RH		\$150.00	1	\$150.00
26	REAR EXHAUST MUFFLER	20	\$528.00	1	\$528.00
	DIS	COUNT GIVEN # %			(\$589.08)
	OBFOLAL NEW COLUMN				***************************************
1	REVERSE SENSOR Dand	AN - 1909	0400.00	20	سر. ۵۵ ۵۵ م
2	REAR WINDSCREEN SEALANT	230	\$180.00	1	\$180.00
_	NEAR WINDSONELIN SEALANT		\$50.00	1	\$50.00
	LABOUR				
1	LABOUR TO REMOVE REAR TRIM AND REAR CUSHIC	ON SEATS TO			\$180.00 150
	FACILATE THE REPAIR				· .
2	LABOUR TO REMOVE DAMAGED PARTS, ALIGN AND				\$1,200.00
	CUT/WELD REAR END PANEL AND REAR SPARE TYPE	RE COMPARTMENT			
3	LABOUR TO REMOVE AND RE INSTALL REAR WINDS	COPEEN OF AGO TO	2380		\$150.00' 24
~	FACILIATE REPAIR	ONEEN GEAGG TO	0 30 0)	\$130.00 12
4	LABOUR TO REMOVE AND REPLACE REAR EXHAUS	T MITEELER			\$1 50.00 × 2 0
5	SPRAY PAINTING ON REAR SPARE TYRE COMPARTI				\$800.00
	PANEL, REAR TAILGATE AND REAR BUMPER SIDE	WENT, INEAN END			φουσ.σο
6	CHECK ELECTRICAL	5 2 v 27 t 5			\$50:00 30
Г	A CONTROL OF THE CONT	Section Assessment Section - Business			(00.00 G -
		SUM DISCOUNT 20%	-8		(\$1,612.34)
1	the Repairer of the following:	£ .	-		La resona
	To resurvey before/after spray painting			Total	\$6,449.38
+	To display damaged part(s) during resurvey			@ 7%	\$451.46
1	• Paris prices are s collo confirme a Signature of	Customer		Total:	\$6,900.83
ᅪ	Third party survey on a "Without Prejudice" basis	156	L: 6275.28		11. 1:
	No flegal modification(s) is allowed	. 1	- " 01-	//	Lauren mus
_	Supplementary item(s) must be resurveyed and	U	s: 4.9K	. /	1 1/1
1	is subject to final aggress! (Avenuence Paryard bi industria	1 Dark #02 52 514	noso 400034	1	15 16/10/12
	TE1 - E0 # 416 760	II Mark #03-53 Singi FAX: 6841 3527	apore 406934		1 1/18
	Acknowledged by Repairer Email: cruiseac@				090
	Signature:	angnercom.sg *			UIVM
		_F			1
<u> </u>		1.29	,		
		· Lick of Ston St. 16			
	· V.				