

23/07/2017

ASS. REC. BY:

REF: CS3 / LPC18012027 / Brb-11

Special Instruction:

SUBV/OT

## ASSIGNMENT (Office)

From (Person): Gerald Poh of LPC Date/Time: 16-10-2018

Estimated Cost: Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SM 1234A Insured: GTV 8349m

at Workshop m/s: Sin Motor Tel: 6453 3908

of: Blk 176 Sin Ming Drive #05-07

Policy No: Claim No: 18/18/18/VP05/020701

Sum Insured: Excess:

Make of Veh: D.O.A 25062018  
(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) (Signature)
	SM 1234A - X
	GTV 8349m - X
	Submit PRS report

X Check with Lim

91811947

Submit L/s \$2,900.00 @ 4 days  
Red: \$4600, 61%.

RECEIVED 22 OCT 2018

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLM 1234 A Yr Regn: Mar, 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru BRZ c.c. 1998Colour: White A/C: Insured / Std / NI / NASp. Reading: 5595 T/Radio: Insured / Std / NI / NAEng/No: FA20B844486C/No: JF1ZC6K72HG012009Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45 R17R: 215/45 R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/6/2018 D.O.I. 27/18 @ 1209pmSurvey held at Auto CareDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

1) trip in☒ : Final ReportResurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Date/Time, File Return to?

Transportation

2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

) \$ + RS. \$ \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_)

) Photos

☐ : Tech. Invs (\$ \_\_\_\_\_)

) Others

☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

450
450

Surveyor:

REF: CSI/LPC18018715/rb

Special Instruction:

US: \$7500.00

Third Parties:

Claimant:

Surveyor: PRO Plus Automobile

Workshop: Sin Motor

From (Person): Gerald Poh of LPC Date/Time: 16.10.2018  
Estimated Cost: Bill to:

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SLM 1234 A Insured: SJV 83149H  
at Workshop m/s Sin Motor Tel: 6459 6302  
of 176 Sin Ming Drive #05-07  
Policy No: Claim No: 18/18/18/VPUB/020701  
Sum Insured: Excess:  
Make of Veh: D.O.A. 25.06.2018  
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT  
Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 7 days)  
Date/Time: Submit Final Fig days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	SLM 1234A - X
	SJV 83149H - X
	Submit report by 24 October 2018
	Repair days 4
	TCRim 16/10/18

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :  
Salvage Value :  
Nett Value :


Inspected/  
Evaluated by:

Fee Charged:

Basic & Add  
Transport  
Photos  
Others  
Total

Date:

1) Date/Time File Pass to 2) Date/Time File Return to  
3) Date/Time File Pass to 4) Date/Time File Return to  
5) Date/Time File Pass to 6) Date/Time File Return to



# **LONPAC INSURANCE BHD**

(S98FC5635C)

Our Ref : 18/18/18/VP05/020701

Your Ref : Not Advised

12 October 2018

M/s LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1  
#01-25 Paya Ubi Industrial Pk  
Singapore 408933

Dear Sirs/Madam

## **PAPER SURVEY OF SLM123A**

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SLM1234A
- b) GIA report of SLM1234A
- c) GIA report & photos of SJV8349H

Kindly study the documents and let us have your report by 24 October 2018.

Yours faithfully

**GERALD POH**  
**SENIOR EXECUTIVE**  
**(CLAIMS)**  
Email : [mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 26/06/2018 14:23  
Date Of Accident 25/06/2018 11:05  
Exact Location Of Accident CTE TWDS CITY (NEAR NOVENA)  
Country/State of Loss SINGAPORE


### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLM1234A  
Insured/Policyholder  
Name Of Registered Owner CHEW LI BENG  
NRIC No S7537478Z  
Email Address VICKICHEW@HOTMAIL.COM  
Mobile Phone No (LOCAL) +65-91551696  
Alternative Phone No OFFICE-NOPHONE  
Vehicle Particulars  
Manufacturer SUBARU  
Model BR2  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR  
Insurance Company  
Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD  
Type Of Coverage COMPREHENSIVE  
Is it a Fleet Policy NO  
Policy Number MT/00465522  
Cover Note Number  
Driver  
Name of Driver CHEW LI BENG  
NRIC No S7537478Z  
Date Of Birth 12/12/1975  
Occupation INDOOR  
Date Of Driving Pass 04/07/1997  
Driving Experience 20 YEARS AND 11 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-91551696  
Fax Number  
Contact Number OFFICE-NOPHONE  
Mail Address VICKICHEW@HOTMAIL.COM

Sketch Plan Pg. 2

Date of accident: 25/6/18 Time: 11:05 Location: CTE (Towards City)  
 My Vehicle A: SLM 1234A Vehicle B: SJV 8349H Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along CTE towards city on 25th June 2018 around 11:05am on lane 1. Suddenly I heard and felt a long bang on back of my vehicle (A). I put on hazard light and stopped the car immediately. The car (BM black) B behind had hit my left rear of A while trying to change to lane 2. B then moved his car in front of my car and we took photos and exchange details and contact numbers.

2 men stopped their car on road shoulder and came up to offer assistance. They then called LTA and EMAS towing as both cars' wheel were damaged in accident.

EMAS towed our vehicles to nearest public carpark behind Moulmain road and subsequently owner & driver of B called towing service to tow to his preferred workshop Sin Ming Ambcare # 05-07 and B said informed me to ~~submit~~ insurance. He will pay damages through his insurance.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my official accident report to:  
 My workshop: Sin Motor  
 Email address:  
 & myself:  
 Email address: vickidew@hotmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Vehicle: - SLM 1234A

Policyholder's Signature  
 Date & Time: 26/6/18 1:02pm  
 GIANMC Sketch Plan Form V2

Driver's Signature -  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:  
 26/06/18



勝摩多修理  
SIN MOTOR REPAIRS

27 September 2018

Madam Chew Li Beng  
c/o 176 Sin Ming Drive  
#05-07 Sin Ming Auto Care  
Singapore 575721

**FINAL REPAIR COSTS**

SLM 1234 A  
Subaru BR2

To cost of repair lump sum as recommend by surveyor.....\$7,500.00 NETT

*SINGAPORE DOLLARS : SEVEN THOUSAND AND FIVE HUNDRED ONLY*

勝摩多修理  
SIN MOTOR REPAIRS  
BLK 176 SIN MING DRIVE #05-07  
SINGAPORE 575721  
TEL: 4533908, 4596902  
FAX: 4536602

*Li Hong Ly*

BLOCK 176, SIN MING DRIVE, SIN MING AUTO CARE #05-07, SINGAPORE 575721.

TEL: 4533908, 4596902, 4536602 • FAX: 4536602



**PRO  
PLUS  
AUTOMOBILE  
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928  
Tel: +65 6707 8932 Fax: +65 6352 6802  
Mobile: +65 9673 0585 / +65 9788 9809  
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com  
Company Registration No : 40156500M

*Consultants to Motor Industry, Automobile  
Engineers, Claims Investigators, Accident  
Reconstruction Specialists, Insurance Loss  
Assessors / Adjusters, Valuers And  
Licensed Appraisers.*

Our Ref : PP/ET/CT.1234.TP.9-18

27 September 2018

Madam Chew Li Beng  
c/o 176 Sin Ming Drive  
#05-07 Sin Ming Auto Care  
Singapore 575721

**WITHOUT PREJUDICE**

Dear Sirs,

**Re : Third Party Claim  
Vehicle Registration No. SLM 1234 A**

We refer to your instruction to appraise the above-mentioned vehicle on 28 June 2018.

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by Messrs **Sin Motor Repairs** for **\$16,579.63** as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is **\$8,801.10**. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for **\$7,500.00 NETT** which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of **7 (seven)** days, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Very truly yours,  
**PRO PLUS AUTOMOBILE ENGINEERS**

  
**Errol Tan**  
*Licensed Appraiser & Automobile Engineer*  
Encls:

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please contact us immediately by telephone so that we can arrange for its return.





**PRO  
PLUS  
AUTOMOBILE  
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928  
Tel: +65 6707 8932 Fax: +65 6352 6802  
Mobile: +65 9673 0595 / +65 9788 9809  
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com  
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile  
Engineers, Claims Investigators, Accident  
Reconstruction Specialists, Insurance Loss  
Assessors / Adjusters, Valuers And  
Licensed Appraisers.*

## VEHICLE INSPECTION REPORT

To : Madam Chew Li Beng  
c/o 176 Sin Ming Drive  
#05-07 Sin Ming Auto care  
Singapore 575721

Insured :  
Policy Number :  
Claim Number :  
Our Reference : PP/ET/CT.1234.TP.9-18  
Own Damage/Sum Insured :  
Excess :  
Third Party/Insce Company :  
Date : 27 September 2018

Instructed By : Madam Chew Li Beng  
Date of Assignment : 28 June 2018  
Date of Accident : 25 June 2018  
Date of Inspection : 28 June 2018  
Name of Workshop : Sin Motor Repairs  
Place of Inspection : 176 Sin Ming Drive  
#05-07 Sin Ming Auto care  
Singapore 575721

### PARTICULARS OF DAMAGED VEHICLE

Registration Number	: SLM 1234 A	Odometer Reading	: 005 595 Km
Make/Model	: Subaru BR2	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2018	Air Conditioner	: Fitted
Engine Number	: Hidden from view	View Mirrors	: Fitted -O/s & n/s
Chassis Frame Number	: JFLZC6K72HG012009	Seat Belts	: Fitted -Front & rear
Class/Type	: Passenger ( Coupe )	Other Assessories	
Colour	: White	(Specify)	:

### PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine	
Paintwork	: Good	Modification/s	:
Footbrakes	: Serviceable	Market Value	: -
Steering	: Serviceable	Scrap Value (PARF/OMV)	: -
Undercarriage (Front)	: Serviceable		
Undercarriage (Rear)	: N/s affected by accident		

### TYRE CONDITIONS ON VEHICLE

		NEAR SIDE	OFF SIDE
Front (Size)	: 215/45R17	90%	90%
MAKE	: Michelin		
Rear (Size)	: 215/45R17	90%*	90%
MAKE	: Michelin		
SPARE (Size)	: -	-	-
MAKE	: -		
Type of Road Wheels	: Alloy		

NOTE: The above percentages represent the estimated remaining life of the tyre threads


\* Denotes damaged component/s

## PRO PLUS AUTOMOBILE ENGINEERS


### IMPACT OF VEHICLE


Direction of Impact (→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the n/s rear portion of the vehicle. Apparently, the n/s rear wheel was struck-upon, thus, damaging its suspension members & misaligning its wheel camber/geometry.



### SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



 Damage Area/s

Damages sustained were the rear end panel- thrust inwards/buckled, rear bumper assembly, rear fender n/s- buckled, rear suspension members n/s- bent/buckled/clangorous & rear chassis members- bent/misaligned etc-----

*Note : Follow-up reinspection of damaged components & works-in-progress on 3 July 2018.*

*Follow-up reinspection of vehicle on 9 July 2018 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.*

### ESTIMATE

The estimate submitted by **M/s Sin Motor Repairs** as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have/have not agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts :	12559.63	6551.10	Estimated number of
Labour Charges :	1500.00	800.00	days for repairs: 7
Paint Work :	1000.00	600.00	
Towing Charges :	120.00	80.00	Number of photographs
Others :	1400.00	770.00	taken at time of
TOTAL	16579.63	8801.10	static inspection: 47

**Remarks:** The repairer has agreed to undertake the repairs on a contract lump sum of \$7,500.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

*NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.*

## APPRAISEMENT SCHEDULE

Registration No: SLM 1234 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢	
		<u>PARTS REPLACEMENT- LIST ITEMS</u>				
1	1 pc	Taillamp assembly n/s	Base cracked/displaced	366.10	366.10	CRAV
2	1 pc	Rear fender n/s	Dented/buckled/ warped	1509.70	Repair	
3	1 pc	Rear fender quarter window c/w moulding n/s	Unnecessary	630.80	Rejected	
4	1 pc	Rear bumper	Torn/distorted	626.80	626.80	CUTV
5	1 pc	Rear bumper side retainer n/s	Cracked	54.60	54.60	NECV
6	1 pc	Differential assembly	Bent/distorted	3281.30	Refer special nett items	
7	1 pc	Differential [ front mount bush kit ]	Essential	21.01	21.01	} NNX
8	1 pc	Rear axle shaft n/s	Bent/clangorous	591.50	591.50	
9	1 pc	Rear trailing arm n/s	Bent	155.42	155.42	BTv
10	1 pc	Rear trailing arm front bushing n/s	Essential	10.41	10.41	} NECV
11	1 pc	Rear trailing arm rear bushing n/s	Essential	10.41	10.41	
12	1 pc	Rear trailing arm rear bar link lower bushing n/s	Essential	12.32	12.32	
13	1 pc	Panhard rod	Bent	320.96	320.96	} BTv
14	1 pc	Sway bar mount to axle	Bent	31.42	31.42	
15	1 pc	Rear shock absorber n/s	Bent	168.95	168.95	} NNX
16	1 pc	Rear shock absorber upper bush n/s	Essential	18.42	18.42	
17	1 pc	Rear shock absorber lower bush n/s	Essential	18.42	18.42	
18	1 pc	Rear control arm upper n/s	Bent	145.20	145.20	BTv
19	1 pc	Rear control arm inner bush & outer bush kit n/s	Essential	31.42	31.42	NECV
20	1 pc	Rear axle shaft oil seal	Essential	21.56	21.56	} NNX
21	1 pc	Rear axle shaft bearing cone	Distorted	171.59	171.59	
22	1 pc	Rear lower arm n/s	Bent/buckled	159.60	159.60	BTv
23	1 pc	Rear knuckle arm n/s	Buckled	414.20	414.20	BTv
24	1 pc	Rear knuckle arm bearing n/s	Essential	110.00	110.00	NECV
			Sub - Total	8882.11	3460.31	

## APPRAISEMENT SCHEDULE

Registration No: SLM 1234 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$    ¢	Revised Amount \$    ¢
			B/F	8882.11	3460.31
		<u>PARTS REPLACEMENT- LIST ITEMS</u> <u>( CONT'D )</u>			
25	1 pc	Rear propellar shaft	Bent/warped	1733.63	<del>1733.63</del>
26	1 pc	Rear propellar shaft mounting	Essential	156.02	<del>156.02</del>
27	1 pc	Rear propellar shaft centre bearing	Clangorous/essential	41.42	<del>41.42</del>
28	1 pc	Exhaust muffler/tailpipe	Bent	786.45	Refer labour charges
				11599.63	5391.38
		<u>Less : 20% by Pro Plus Automobile Engineers</u>			1078.28
				11599.63	4313.10
		<u>PARTS REPLACEMENT- SPECIAL</u> <u>NETT ITEMS</u>			
1	1 pc	Rear differential assembly	Reconditioned/ secondhand component	0.00	<del>1600.00</del>
2	1 pc	Rear alloy rim n/s	Dented/distorted	450.00	350.00
3	1 pc	Rear tyre [ Michelin : 215/45R17] n/s	Torn/10% depreciation	320.00	<del>150.00</del> <del>288.00</del>
4	1 pc	Rear fender quarter window sealant/repair kit n/s	Unnecessary	60.00	Rejected
5	1 pc	Rear fender quarter window inner seal/dam kit n/s	Unnecessary	30.00	Rejected
6	1 pc	Rear windscreen sealant/repair kit	Unnecessary	60.00	Rejected
7	1 pc	Rear windscreen inner seal/dam kit	Unnecessary	40.00	Rejected
			Sub - Total	12559.63	6551.10

NNX

NEED  
XNN

NNX X

cut ✓

## APPRAISEMENT SCHEDULE

Registration No: SLM 1234 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
			B/F	12559.63	6551.10
		<u>LABOUR &amp; MISC. CHARGES</u>			
1		To towing charges		120.00	80.00
2		To disconnect rear wire harness of rear bumper reverse sensors to facilitate repairs, reconnect & check functions including to reinstall/recalibrate rear bumper reverse sensors to specifications.		80.00	50.00
3		To dismantle/install n/s rear fender quarter window to facilitate repairs including to conduct water leakages etc.		120.00	Rejected
4		To dismantle/install rear windscreen to facilitate repairs including to conduct water leakages etc.		150.00	Rejected
5		To dismantle/check/renew n/s rear suspension members, rear differential assembly, rear propellar shaft, bushes etc to facilitate repairs.		600.00	<del>200.00</del> <del>450.00</del>
6		To correct rear wheel geometry including to oscillate/equipoise n/s rear alloy rim/tyre to specifications.		150.00	<del>60.00</del> 90.00
7		To dismantle/renew exhaust muffler/tailpipe including heat cut/weld & align system & to check for carbon monoxide leakages	( To repair & align )	150.00	<del>60.00</del>
8		To check diagnostics of vehicle management/control units , reset memories to specification etc.		150.00	<del>120.00</del>
			Sub - Total	14079.63	7401.10

} NNX

## APPRAISEMENT SCHEDULE

Registration No: SLM 1234 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$    ¢	Revised Amount \$    ¢
			B/F	14079.63	7401.10
		<u>LABOUR &amp; MISC. CHARGES</u> <u>(CONT'D)</u>			
9		To dismantle/renew the rear accident damaged portion. To heat, knock-out, reshape, straighten, orientate, restore & align repairable constituents; to mount vehicle onto alignment bench. set-up necessary tools & equipment and to calibrate rear chassis members to symmetrical dimensions. [ Note: 'BLACKHAWK' chassis alignment bench/equipment available in motor workshop ]		1500.00	<del>500.00</del> <del>800.00</del>
10		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.	) ) ) ) )	1000.00	<del>300.00</del> <del>600.00</del>
11		To rustproofing & cavities preservation to the replaced and repaired panels.	) )		
			Grand - Total	16579.63	8801.10

Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$7,500.00 NETT, corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

  
 ERROL TAN

B.A.Econ (Hons).UK

Dip. Auto Engr. & Motor Trade Management .UK  
Automobile Engineer & Licensed Appraiser

Repair days 4

Tg Lim

16/10/18

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/06/2018 01:19
Date Of Accident	25/06/2018 10:45
Exact Location Of Accident	CTE BALESTIER EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV8349H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YANG YAN
NRIC No	S7964193F
Email Address	GEROGEYANG.REALITY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84882185
Alternative Phone No	OFFICE-84882185

### Vehicle Particulars

Manufacturer	BMW
Model	525I-2.5 XL (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05017424
Cover Note Number	

### Driver

Name of Driver	YANG YAN
NRIC No	S7964193F
Date Of Birth	03/06/1979
Occupation	OUTDOOR
Date Of Driving Pass	06/06/2013
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84882185
Fax Number	
Contact Number	
Email Address	GEROGEYANG.REALTY@GMAIL.COM

Address	BLK 306 YISHUN CENTRAL #03-191
Postcode	760306
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ATTACHED REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Boletier

CTE

A: 57V8344H

B: 5LM1234A

## Common Statement

## SINGAPORE ACCIDENT STATEMENT

Accident Date: 25/06/2018 Time: 10.45 AM (hh:mm) 24 hr format	
Location CTE turn left to Bulevar (400m before)	
Vehicle Number S7V8349 H	
Insured Name Yang Yan	
NRIC / FIN S7914193 F	Contact Number 84682185
Make BMW	Model 525
Are you claiming under your own insurance policy for repair to your vehicle?	
(✓) Yes If No, Pls select: ( ) Third Party ( ) Reporting	
Insurance Company Lompac	
Type of Policy (✓) Comprehensive ( ) Third Party Fire & Theft ( ) TP Only	
Policy Number 2186505012424	
Name of Driver Yang Yan	(✓) Same as Insured
NRIC / FIN	Contact Number
Date of Birth 03/06/1979	
Driving Pass Date 06/06/2013	
Occupation ( ) Indoor (✓) Outdoor	
Gender (✓) Male ( ) Female	
Email Address george.yang.realtor@gmail.com	( ) NO EMAIL
Address of Driver	
Was driver an employee of the Insured's Company? ( ) Yes (✓) No	
If No, Relationship of the Driver with the Insured	
(✓) Owner ( ) Spouse ( ) Friend ( ) Relative ( ) Children ( ) Sibling	
Does the Driver Own Any Other Vehicle? ( ) Yes (✓) No	
If Yes, Vehicle Registration Number of Driver's Own Vehicle	
Insurance Company of Driver's Own Vehicle	
Weather Conditions (✓) Clear ( ) Raining ( ) Others	
Road Surface (✓) Dry ( ) Wet ( ) Others	
Was any foreign vehicle involved in this accident? ( ) Yes (✓) No	
Was anybody injured in the accident? ( ) Yes (✓) No	
If yes, injured detail	
Was there any video captured by Car Camera? ( ) Yes (✓) No	
Was the Accident reported to the Police? ( ) Yes (✓) No If yes attach police report	
DETAILS OF 3 <sup>rd</sup> party	Name / Nric Contact
Veh B SLM 1234 A	
Veh C	
Veh D	
Veh E	
Veh F	


## Individual Statement

### Describe Circumstances of the Accident

I, Jany Yau 57464143F, drive to Balesley on CTI from before when turned left and find behind got car crash in, so I kept back, then crashed right side car SUM1234A.

### Declaration

We declare the foregoing particulars are true in every respect.

 25/06/2018

Policyholder's Signature / Date & Time

 25/06/2018

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

## CERTIFICATE



**LONPAC INSURANCE BHD** (598FC5635C)

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555.

Tel: (65) 6250 7366 Fax: (65) 6296 3767 Website: www.lonpac.com.sg

GST Reg No.: P9-0005635-C

MX1

### CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE.  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE).  
ROAD TRANSPORT ACT 1987 (MALAYSIA).  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No. : Z18VP05017424

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

BMW 525i XL 2.5  
- SJV8349H

2. Name of Policy Holder

YANG YAN

3. Effective Date of the Commencement of Insurance  
for the purpose of the Act

11/02/2018

4. Date of Expiry of the Insurance

10/02/2019

5. Persons or Classes of Persons entitled to drive

(A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

Excess : S\$ 0.00 (SECTION 1) INSURED / NAMED DRIVERS

S\$ 2,000.00 (SECTION 1) UNNAMED DRIVERS

S\$ 3,000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS

S\$ 100.00 WINDSCREEN EXCESS

Condition : ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

\* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner : UNITED OVERSEAS BANK LIMITED

CHIEF EXECUTIVE  
(Singapore Branch)

User ID: GE2136

Date Issued: 07/02/2018

LEFT SIDE REAR VIEW



RIGHT SIDE REAR VIEW



RIGHT SIDE FRONT VIEW



REAR VIEW





FRONT VIEW



LEFT SIDE FRONT VIEW



Driving License-FRONT & BACK

**REPUBLIC OF SINGAPORE** **DRIVING LICENCE**

Portrait photo of a man.

License number: **S7964193F**

Name: **YANG YAN**

Birth Date: **03 Jun 1979**

Issue Date: **06 Jun 2013**

Barcode: 002100621F

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)**

**EFFECTIVE DATE** 06 Jun 2013



**Class 3** Motor Cars  $\leq$  9000kg with  $\leq$  7 passengers, exclusive of the driver; and other motor vehicles  $\leq$  2500kg

NP-4204

Barcode: Licence No: S7964193F

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7964193F



Name

YANG YAN

杨 燕

Race

CHINESE

Date of birth



03-06-1979

Sex


M

Country of birth

CHINA



8981849



NRIC No. **S7964193F**



Nationality

**CHINESE**

Date of issue

**13-11-2008**

**APT BLK 306 YISHUN CENTRAL #03-191  
SINGAPORE 760306**

NRIC No: **S7964193F**

Date: **16/06/2012**

No: **7112933**

CHASSIS NO





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18012027/Brbe2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 24-10-2018	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJV 8349M	Veh. Inspected	SLM 1234A	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020701	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	16/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU BRZ	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1ZC6K72HG012009	Colour	WHITE	
Odometer	5595	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/06/2018	Inspection Date	02/07/2018	
Survey held at	SIN MOTOR REPAIRS BLK 176 SIN MING DRIVE #05-07 SINGAPORE 575721			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 1234A**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILLAMP ASSEMBLY N/S	CRACKED	366.10	366.10
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,509.70	-
1	REAR FENDER QUARTER WINDOW C/W MOULDING N/S	UNNECESSARY	630.80	-
1	REAR BUMPER	CUT	626.80	626.80
1	REAR BUMPER SIDE RETAINER N/S	NECESSARY	54.60	54.60
1	DIFFERENTIAL ASSEMBLY	NOT NECESSARY	3,281.30	-
1	DIFFERENTIAL [FRONT MOUNT BUSH KIT]	NOT NECESSARY	21.01	-
1	REAR AXLE SHAFT N/S	NOT NECESSARY	591.50	-
1	REAR TRAILING ARM N/S	BENT	155.42	155.42
1	REAR TRAILING ARM FRONT BUSHING N/S	NECESSARY	10.41	10.41
1	REAR TRAILING ARM REAR BUSHING N/S	NECESSARY	10.41	10.41
1	REAR TRAILING ARM REAR BAR LINK LOWER BUSHING N/S	NECESSARY	12.32	12.32
1	PANHARD ROD	BENT	320.96	320.96
1	SWAY BAR MOUNT TO AXLE	BENT	31.42	31.42
1	REAR SHOCK ABSORBER N/S	NOT NECESSARY	168.95	-
1	REAR SHOCK ABSORBER UPPER BUSH N/S	NOT NECESSARY	18.42	-
1	REAR SHOCK ABSORBER LOWER BUSH N/S	NOT NECESSARY	18.42	-
1	REAR CONTROL ARM UPPER N/S	BENT	145.20	145.20
1	REAR CONTROL ARM INNER BUSH & OUTER BUSH KIT N/S	NECESSARY	31.42	31.42
1	REAR AXLE SHAFT OIL SEAL	NOT NECESSARY	21.56	-
1	REAR AXLE SHAFT BEARING CONE	NOT NECESSARY	171.59	-
1	REAR LOWER ARM N/S	BENT	159.60	159.60
1	REAR KNUCKLE ARM N/S	BENT	414.20	414.20
1	REAR KNUCKLE ARM BEARING N/S	NECESSARY	110.00	110.00
1	REAR PROPELLER SHAFT	NOT NECESSARY	1,733.63	-
1	REAR PROPELLER SHAFT MOUNTING	NOT NECESSARY	156.02	-
1	REAR PROPELLER SHAFT CENTRE BEARING	NOT NECESSARY	41.42	-
1	EXHAUST MUFFLER / TAILPIPE	NOT NECESSARY	786.45	-





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-489.77
			11,599.63	1,959.09
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR DIFFERENTIAL ASSEMBLY (SN) (NPA)	NOT NECESSARY	-	-
1	REAR ALLOY RIM N/S (SN)	CUT	450.00	350.00
1	REAR TYRE (MICHELIN : 215/45R17) N/S (SN)	TORN	320.00	150.00
1	REAR FENDER QUARTER WINDOW SEALANT / REPAIR KIT N/S (SN)	UNNECESSARY	60.00	-
1	REAR FENDER QUARTER WINDOW INNER SEAL / DAM KIT N/S (SN)	UNNECESSARY	30.00	-
1	REAR WINDSCREEN SEALANT / REPAIR KIT (SN)	UNNECESSARY	60.00	-
1	REAR WINDSCREEN INNER SEAL / DAM KIT (SN)	UNNECESSARY	40.00	-
			960.00	500.00
	<b><u>LABOUR</u></b>			
	TO TOWING CHARGES.		120.00	80.00
	TO DISCONNECT REAR WIRE HARNESS OF REAR BUMPER REVERSE SENSORS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO REINSTALL / RECALIBRATE REAR BUMPER REVERSE SENSORS TO SPECIFICATIONS.		80.00	50.00
	TO DISMANTLE / INSTALL N/S REAR FENDER QUARTER WINDOW TO FACILITATE REPAIRS INCLUDING TO CONDUCT WATER LEAKAGES ETC.	NOT NECESSARY	120.00	-
	TO DISMANTLE / INSTALL REAR WINDSCREEN TO FACILITATE REPAIRS INCLUDING TO CONDUCT WATER LEAKAGES ETC.	NOT NECESSARY	150.00	-
	TO DISMANTLE / CHECK / RENEW N/S REAR SUSPENSION, MEMBERS, REAR DIFFERENTIAL ASSEMBLY, REAR PROPELLER SHAFT, BUSHES ETC TO FACILITATE REPAIRS.		600.00	200.00
	TO CORRECT REAR WHEEL GEOMETRY INCLUDING TO OSCILLATE / EQUIPOISE N/S REAR ALLOY RIM / TYRE TO SPECIFICATIONS.		150.00	60.00
	TO DISMANTLE / RENEW EXHAUST MUFFLER / TAILPIPE INCLUDING HEAT CUT / WELD & ALIGN SYSTEM & TO CHECK FOR CARBON MONOXIDE LEAKAGES.	NOT NECESSARY	150.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	150.00	-

Report Ref No. CS3/LPC18012027/Brbe2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTION. TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE, RESTORE & ALIGN REPAIRABLE CONSTITUENTS; TO MOUNT VEHICLE ONTO ALIGNMENT BENCH, SET-UP NECESSARY TOOLS & EQUIPMENT AND TO CALIBRATE REAR CHASSIS MEMBERS TO SYMMETRICAL DIMENSIONS. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S.		1,500.00	500.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		1,000.00	300.00
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			4,020.00	1,190.00
GRAND TOTAL			16,579.63	3,649.09
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS3/LPC18012027/Brbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.