

Surveyor:

DOI:

ASSIGNMENT

Date/Time:

Registered in Merimon:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia: 0

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

Loss of Use (LOU):

S\$

Loss of Income (LOI):

S\$

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Payee 2: (Strike if N.A.)

S\$

Payee 3: (Strike if N.A.)

S\$

Name 1:

Name 2:

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

31/4/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

Global Sum S\$: 22500.00

Trans-cab Auto Services Pte Ltd.

ASS. REC. BY:

REF:

A/G/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Trans Cob

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/H/F 3884

Yr Regn:

06/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perault Longitude C.C. 1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

611097

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

V/F1 ABL15/MC 278427

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

12/10/18

D.O.I.

16/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/B

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/10 File pass to Catherine

L1 Prop @ 19,500 Cntm Jamim (8+324 x 99.38 + 600)

8# 2 sum + 1RS = 11

(Reel @ 10154.83/844.7)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fixt

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U**AAD1810-175***Not Authorized*
L/Sing &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 588U

VF1ABL15AUC278427

RENAULT

LATITUDE

12.10.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	Bu 1,108.46	—
2	1 BUMPER LOWER REAR	\$	Na 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	Dis 113.47	—
4	1 BUMPER BRACKET SIDE RH REAR	\$	SL 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	SL 44.99	X
6	1 BUMPER REFLECTOR RH	\$	SL 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	SL 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	SL 44.99	X
9	1 BUMPER REFLECTOR LH	\$	CM 43.61	✓
10	1 BUMPER BEAM REAR	\$	Bz 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	Dis 225.95	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	Bz 225.95	—
13	1 BOOT REAR	\$	Bz 2,872.68	—
14	1 BOOT FINISHER	\$	SL 470.06	X
15	1 BOOT WHEATERSTRIP	\$	CM 323.05	50652
16	1 BOOT REFLECTOR LAMP LH	\$	SL 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	CM 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	Na 225.36	—
19	1 BOOT BADGE	\$	Na 225.36	—
20	1 BOOT STRUT LH	\$	SL 276.08	} X
21	1 BOOT STRUT RH	\$	SL 276.08	
22	1 BOOT HINGE LH	\$	R 367.84	
23	1 BOOT HINGE RH	\$	R 367.84	
24	1 BOOT INNER TRIM	\$	SL 586.45	
25	1 BOOT SWITCH	\$	SL 168.13	
26	1 BOOT LOCK	\$	R 202.67	
27	1 BOOT LOCK CATCH	\$	R 74.40	
28	2 LICENCE PLATE LAMP	\$	SL 50.52	
29	2 BOOT RUBBER PLUG	\$	SL 221.81	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD1810-175**SHF 588U**

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	
31	1 FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45	
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	
33	1 WHEELARCH REAR LH	\$	SL	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	
36	1 WHEELARCH REAR RH	\$	SL	543.47	
37	1 TAILLAMP RH	\$	SL	552.55	
38	1 TAILLAMP PANEL RH	\$	R	986.70	
39	1 TAILLAMP LH	\$	mgm	552.55	✓
40	1 TAILLAMP PANEL LH	\$	R	986.70	X
41	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	RA	404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21	
45	1 EXHAUST REAR	\$	R	7,489.05	
46	1 EXHAUST CAP REAR	\$	R	230.49	
47	1 FUEL FLAP L70Y	\$	SL	343.57	
48	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	
49	1 CHASSIS PANEL REAR LH L70Y	\$	R	3,766.43	
50	1 KUCKLE ARM REAR LH	\$	SL	736.67	
51	1 BRAKE DISC REAR L70Y	\$	SL	525.91	
52	1 WHEEL HUB NUT L70Y	\$	SL	51.11	
53	1 WHEEL HUB CAP L70Y	\$	SL	57.82	
54	1 ABS SENSOR REAR LH	\$	SL	255.75	
55	1 REAR AXLE L70Y	\$	SL	4,167.03	
56	1 AXLE ARM LH	\$	SL	117.22	
57	1 LOWER ARM REAR LH	\$	SL	905.99	
58	1 ABSORBER REAR	\$	SL	389.75	
59	1 STABILIZER BAR REAR LH	\$	SL	604.65	
60	1 BRAKE CALIPER REAR LH	\$	SL	1,300.67	
61	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	
62	1 BUMPER COVER FRT	\$	B	1,259.42	✓
63	1 BUMPER SPOILER FRT	\$	D.I	181.75	✓
64	1 BUMPER ABSORBER FRT	\$	CM	394.68	✓
65	1 BUMPER RETAINER FRT LH	\$	D.I	151.41	✓
66	1 BUMPER SUPPORT FRT	\$	SL	123.88	X
67	1 BUMPER RETAINER FRT RH	\$	D.I	150.77	✓

Trans-cab Auto Services Pte Ltd

AAD1810-175

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

68	1 BUMPER SUPPORT FRT	\$	SL	123.88	X
69	1 BUMPER UNDERTRAY FRT	\$	SL	472.83	X
70	1 BUMPER GRILLE LOWER FRT	\$	Di	266.80	✓
71	1 BUMPER FOG LAMP GRILLE LH	\$	SL	207.21	X
72	1 BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	X
73	1 BUMPER BEAM FRT	\$	B	914.08	✓
74	1 TOW COVER FRT	\$	SL	28.61	X
75	1 RADIATOR GRILLE	\$	mi	1,707.78	✓
76	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	mi	225.36	✓
77	1 RADIATOR GRILLE FRAME	\$	CM	1,353.75	✓
78	1 FRAME FULL SUPPORT PANEL	\$	CM	615.90	✓
79	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79	X
80	1 FRONT BRACE PANEL	\$	R	177.22	X
81	1 HORN	\$	SL	314.17	X
82	1 HORN BRACKET	\$	R	40.45	X
83	1 HEADLAMP LH	\$	puller	1,184.43	✓
84	1 HEADLAMP RH	\$	CM	1,184.43	✓
85	1 HEADLAMP PANEL FRT LH	\$	R	152.15	X
86	1 HEADLAMP PANEL FRT RH	\$	R	152.15	X
87	1 BONNET	\$	B	1,941.63	✓
88	1 BONNET INSULATOR	\$	SL	405.73	X
89	1 BONNET STRUT LH	\$	SL	88.61	X
90	1 BONNET STRUT RH	\$	SL	88.61	X
91	1 BONNET HINGE LH	\$	R	348.31	X
92	1 BONNET HINGE RH	\$	R	348.31	X
93	1 BONNET LOCK	\$	Di	305.48	✓
94	1 BONNET CABLE	\$	SL	119.19	} X
95	1 BONNET CABLE COVER	\$	SL	161.03	
96	1 BONNET SEAL OUTER	\$	SL	92.36	
97	1 BONNET SEAL INNER	\$	SL	157.28	
98	1 FENDER PANEL FRT LH	\$	R	783.83	
99	1 WHEELARCH FRT LH	\$	SL	278.84	
100	1 FENDER BRACKET LOWER LH	\$	SL	15.79	
101	1 FENDER INSULATOR LH	\$	SL	130.84	
102	1 FENDER INSULATOR RH	\$	SL	130.84	}
103	1 AIR CLEANER LOWER	\$	SL	271.26	
104	1 AIR CLEANER HOSE	\$	SL	76.14	
105	1 BASE BATTERY TRAY	\$	SL	363.40	}

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

106	1 AIR CLEANER BOX	\$	Sh 464.20 X
107	1 TURBO DUCT	\$	Sh 1,027.80 X
108	1 A/C HEATER VALVE	\$	Sh 484.50 X
109	1 SUBFRAME OUTER FRT	\$	Sh 2,652.45 X
110	1 SUBFRAME BRACKET OUTER LH	\$	Sh 92.36 X
111	1 ENGINE UNDERTRAY	\$	Sh 564.98 X
112	1 A/C CONDENSER	\$	Sh 2,020.37 ✓
113	1 A/C CONDENSER GARNISH LH UPPER	\$	Sh 39.67
114	1 A/C CONDENSER GARNISH RH UPPER	\$	Sh 39.67
115	1 A/C CONDENSER GARNISH LH	\$	Sh 58.81
116	1 A/C CONDENSER GARNISH RH	\$	Sh 59.60
117	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	Sh 208.39
118	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sh 658.72
119	1 A/C PIPE COMPRESSOR	\$	Sh 334.29
120	1 A/C PIPE	\$	Sh 658.72
121	1 A/C COMRPRESSOR	\$	Sh 2,684.61
122	1 AIR COOLER	\$	Sh 792.60
123	1 AIR INTERCOOLER HOSE (LONG)	\$	Sh 1,014.13
124	1 AIR INTERCOOLER HOSE (Short)	\$	Sh 375.14
125	1 TRANSMISSION COOLER	\$	Sh 1,219.30
126	1 TRANSMISSION COOLER PAD	\$	Sh 17.96
127	1 RADIATOR	\$	Sh 1,202.20
128	2 RADIATOR STUD UPPER	\$	Sh 14.41
129	2 RADIATOR BUSH UPPER	\$	Sh 50.12
130	2 RADIATOR MTG LOWER	\$	Sh 55.85
131	1 RADAITOR FAN COWLING	\$	Sh 820.54
132	1 RADIATOR FAN MOTOR LH	\$	Sh 967.36
133	1 RADIATOR FAN MOTOR RH	\$	Sh 1,479.46
134	1 RADIATOR TANK	\$	Sh 324.62
135	1 RADIATOR HOSE UPPER	\$	Sh 240.56
136	1 RADIATOR HOSE LOWER	\$	Sh 491.18
137	1 RADIATOR TANK HOSE	\$	Sh 61.18

TOTAL	\$	100,263.67
10%	\$	10,026.37
	\$	90,237.31

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

AAD1810-175

Special Nett

1 1SET PARKING AID	\$	Sm	700.00	X
2 1SET REAR BUMPER CLIP	\$	nn	66.00	—
3 1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	—
10 1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11 1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	nn	30.00	—
13 1 BOOT STICKER "6555-3333"	\$	nn	30.00	—
14 1 BOOT INNER TRIM CLIP	\$	nn	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19 1 TAILLAMP CLIP RH	\$	nn	5.00	X
20 1 TAILLAMP CLIP LH	\$	nn	5.00	—
21 2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
22 1 WINDSCREEN MOULDING	\$	nn	100.00	X
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	X
25 1 SPARE TYRE	\$	Sm	330.00	X
26 1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	X
27 1SET BUMPER CLIP FRT	\$	nn	66.00	—
28 1 BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	} X
29 1 BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
30 1 BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
31 1 BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
32 1 TOW COVER FRT	\$	Sm	14.50	
33 1SET RADIATOR GRILLE SCREW	\$	nn	16.00	
34 1SET BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
35 1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
36 2 FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

37	1 LEFT REAR TYRE	\$	SH 330.00 X
38	1 LEFT REAR TYRE RIM	\$	SH 380.00 X
39	2 FRAME FULL SUPPORT PANEL STUD	\$	SH 30.00 X
40	1 Windscreen moulding	\$	nn 100.00 X
41	1SET Front licence plate with holder	\$	BH 80.00 45nn
42	1 FRONT RIGHT FENDER ADVERTISEMENT STICKER	\$	nn 300.00 X
43	1 REAR RIGHT FENDER ADVERTISEMENT STICKER	\$	nn 300.00 X
44	1 REAR BOOT ADVERTISEMENT STICKER	\$	nn 300.00 150nn
45	1 REAR LEFT FENDER ADVERTISEMENT STICKER	\$	nn 300.00 X
46	1 REAR RIGHT FENDER ADVERTISEMENT STICKER	\$	nn 300.00 X
46	1 REAR BUMPER ADVERTISEMENT STICKER	\$	nn 200.00 100nn

TOTAL \$ 5,197.52**TOTAL PARTS \$ 95,434.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00 1100l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00 1100l
To Rust-Proofing Of The Affected Areas.	\$	170.00 90l
To reinstall rear bumper parking sensor.	\$	170.00 60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60l
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 60h

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00 X
Towing Fees.	\$	120.00 Sol
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To rust-proofing of the affected areas.	\$	Repectly 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 Sol

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To lift-up engine with gear box and refit.

\$ *nn* 440.00 X

To remove and renew power steering pump, oil cooler pipe and final checking and testing.

\$ *nn* 440.00 X

To remove and refit air bag system and reset.

\$ *nn* 480.00 X

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.

\$ *nn* 380.00 X

To vacuum, replace, refix and recharge air condenser

\$ 380.00 *100%*

To replace, refix and top up coolant for radiator

\$ 170.00 *50%*

To vacuum, replace, refix and recharge Air Intercooler

\$ 170.00 *50%*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X**TOTAL \$ 24,220.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Over All Total \$ 119,654.83**(LUMP SUM)****Repair Days****30 DAYS***80%*

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Sunday, 10 March 2019 11:42 AM
To: 'Tan, Wilson-KL'
Subject: <Seek Mandate> AIG Ref: 8043588180SG *LKK Ref: CC3/LCR18018883/Kpa3
[ACCIDENT INVOLVING SLG 5720T(OI)/ SHF 588U(TP) / OTHERS ON 12/10/2018]

AIG Ref: **8043588180SG**
LKK Ref: CC3/LCR18018883/Kpa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLG 5720T(OI)/ SHF 588U(TP) / OTHERS ON 12/10/2018

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We seek your approval to offer to Third Party repairer, **"Trans-cab Auto Services Pte Ltd"** is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 128,030.67	\$ 20,865.00
2. Loss of Rental (12days x \$99.32)	\$ 1,191.84	\$ 1,092.52 (11days x \$99.32)
3. Loss of Income (12days x \$50.00)	\$ 600.00	\$ 550.00 (11days x \$50.00)
4. LTA/ GIA Search Fee	\$ 7.49	\$ 7.45
Total	\$ 129,830.00	<u>\$ 22,514.97</u>

**08days recommendation for repair + 2Sunday + 1 PRS = 11days

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SHF588U (8043588180SG)**

[SLG5720T]

TP

TRANS-CAB SERVICES PTE LTD

Oct 12 2018 8:00PM

[LCRF PTE LTD]

Trans-cab Auto Services Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **21/03/2019 08:55 AM**.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$22514.97) - SHF588U - Claim Handler: Tan, Wilson-KL**

Approved:22514.97.

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Wednesday, 3 April 2019 8:41 AM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'
Cc: claims@transcab.com.sg
Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHF 588U(DOA: 12/10/2018) - AAD1810-175 //LKK REF: CC3/LCR18018883/Kpa3

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Monday, 25 March 2019 2:48 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>
Cc: claims@transcab.com.sg
Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHF 588U(DOA: 12/10/2018) - AAD1810-175 //LKK REF: CC3/LCR18018883/Kpa3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$22,500.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Monday, 11 March 2019 6:43 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHF 588U(DOA: 12/10/2018) - AAD1810-175

Dear Hsiao Tong

Enclosed is the after paint photos for your action.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Sunday, 10 March, 2019 11:34 AM

To: claims@transcab.com.sg; 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>

Subject: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHF 588U(DOA: 12/10/2018) - AAD1810-175

Your ref: **AAD1810-175 (SHF 588U)**

Without Prejudice

Our ref: CC3/LCR18018883/Kpa3

Dear Sirs/Mdm,

We refer to the above matter.

We are seeking mandate approval from AIG.

Kindly advise if there is any after repair/ after paint photos for SHF 588U(DOA: 12/10/2018). If so, kindly let us have a copy of the photos.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

TP Veh	SHF 588U
Date of Reg	20.06.2014
DOA	12.10.2018
COE Expiry Date	19.06.2022

\$

(I) Estimated Book Value

Unit Cost	38,000.00
Import Duty	3,999.60
Registration Fee	140.00
PQP Paid	57,338.00
ARF Paid	12,498.00
Estimated Per Taxi Purchase Price	111,975.60
Estimated Per Taxi Purchase Price	111,975.60
Less 60% of ARF Paid	7,498.80
Estimated Full Lifespan Depreciation	104,476.80
Estimated Full Lifespan Depreciation	104,476.80
Times Balance Life (44/96 months)	47,885.20
Add 60% of ARF Paid	7,498.80
Estimated Book Value	55,384.00

(II) Adjusted LTA Rebate

PARF Rebate	
PQP Paid	
Times Balance Life (69/96 months)	
Adjusted COE Rebate	
PARF Rebate	
Add Adjusted COE Rebate	
Adjusted LTA Rebate	35,732.00

(Summary) Estimated Nett Value

Estimated Book Value	55,384.00
Less Adjusted LTA Rebate	35,732.00
Estimated Net Value	19,652.00

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1810-175

Your Ref : SLG5720T, SLV5069L

Date : 31.January 2019

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

**ACCIDENT INVOLVING SHF0588U AND SLG5720T, SLV5069L ON 12/10/18 08:20 PM
ALONG ANG MO KIO AVENUE 5 SLIP ROAD TOWARDS CTE**

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	20,865.00
2.	Loss of Rental for <u>12</u> days @ \$ <u>99.32</u> per day	\$	1,191.84
3.	Loss of Income for <u>12</u> days @ \$ <u>50</u> per day	\$	600.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	22,664.33

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2018 Edit Reg		16 Oct 2018 00:00 Edit Adj Rpt	\$19,500.00 Edit Estimates	\$19,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LION CITY RENTALS PTE LTD, Co. Reg. No.: 201504621K		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHF588U	Date of Loss:	12/10/2018 20:00 - :59 [51 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8043588180SG	Policy/Cover Note No.:	0999994811 (Comprehensive)
Vehicle Reg. No. (Insured):	SLG5720T	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/10/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (21/03/2019): Alert - Adj Mandate Approved (\$22514.97) - SHF588U - Claim Handler: Tan, Wilson...
- AIG_SG (18/10/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SHF588U (8043588180SG)**
[SLG5720T]
TP
TRANS-CAB SERVICES PTE LTD
Oct 12 2018 8:00PM
[LION CITY RENTALS PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/10/18 15:45	Video - Accident 01 VIDEO FOOTAGE	Load MP4	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 16:35	General View	Load JPG	☒
2	24/10/18 16:35	General View	Load JPG	☒
3	24/10/18 16:35	General View	Load JPG	☒
4	24/10/18 16:35	General View	Load JPG	☒
5	24/10/18 16:35	General View	Load JPG	☒
6	24/10/18 16:35	General View	Load JPG	☒
7	24/10/18 16:35	General View	Load JPG	☒
8	24/10/18 16:35	General View	Load JPG	☒
9	24/10/18 16:35	General View	Load JPG	☒
10	24/10/18 16:35	General View	Load JPG	☒
11	24/10/18 16:35	General View	Load JPG	☒
12	24/10/18 16:35	General View	Load JPG	☒
13	24/10/18 16:35	General View	Load JPG	☒
14	24/10/18 16:35	General View	Load JPG	☒
15	24/10/18 16:35	General View	Load JPG	☒
16	24/10/18 16:35	General View	Load JPG	☒
17	24/10/18 16:35	General View	Load JPG	☒
18	24/10/18 16:35	General View	Load JPG	☒
19	24/10/18 16:35	General View	Load JPG	☒
20	24/10/18 16:35	General View	Load JPG	☒
21	24/10/18 16:35	Odometer Reading	Load JPG	☒
22	24/10/18 16:35	General View	Load JPG	☒
23	24/10/18 16:35	General View	Load JPG	☒
24	24/10/18 16:35	General View	Load JPG	☒
25	24/10/18 16:35	General View	Load JPG	☒
26	24/10/18 16:35	General View	Load JPG	☒
27	24/10/18 16:35	General View	Load JPG	☒
28	24/10/18 16:35	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
29	24/10/18 16:35	General View	 Load JPG	☒
30	24/10/18 16:35	General View	 Load JPG	☒
31	24/10/18 16:35	General View	 Load JPG	☒
32	24/10/18 16:35	General View	 Load JPG	☒
33	24/10/18 16:35	General View	 Load JPG	☒
34	24/10/18 16:35	General View	 Load JPG	☒
35	24/10/18 16:35	General View	 Load JPG	☒
36	24/10/18 16:35	General View	 Load JPG	☒
37	24/10/18 16:35	General View	 Load JPG	☒
38	24/10/18 16:35	General View	 Load JPG	☒
39	24/10/18 16:35	General View	 Load JPG	☒
40	12/03/19 21:52	Reinspection Photo	 Load JPG	☒
41	12/03/19 21:52	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 17:23	TP ESTIMATE - MARKED	 Load PDF	
2	23/10/18 17:23	TP GIA REPORT	 Load PDF	
3	12/02/19 14:26	LETTER TO OI	 Load PDF	
4	12/02/19 14:26	LTA SEARCH	 Load PDF	
5	12/02/19 14:26	RENTAL RECEIPT	 Load PDF	
6	14/05/19 09:48	AUTHORISATION TO ACT	 Load PDF	
7	14/05/19 09:48	RELEASE VOUCHER	 Load PDF	
8	14/05/19 09:48	WORKSHOP INVOICE	 Load PDF	
9	14/05/19 09:48	RENTAL MILEAGE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/10/18 10:02	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLG5720T (Insd veh)	Model:	RENAULT LATITUDE 2.0 L DCI
	SHF588U (TP veh)		AUTO D/AB 4DR (A)
Date of Accident:	12/10/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	128,030.67
Final Repair Cost	:	\$	22,500.00
Loss of Use	:	\$	11.00 days at \$50.00 per day
Rental (if any)	:	\$	11 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	22,500.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:	\$ 22,500.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

14 May
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18018883/KPA3S2
Date: 14/05/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994811
Claimant Vehicle No :	SHF588U	Insured Vehicle No :	SLG5720T
Date of Loss:	12/10/2018	Nature of Claim:	TP
		Claim No:	8043588180SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF588U	Engine No:	M9R8839C001440
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC278427
Reg. Date:	20/06/2014 (Man. Year: 2014)	Odometer:	611097 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	95,434.83	21,788.25	73,646.58	77.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,220.00	2,760.00	21,460.00	88.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	119,654.83	24,548.25	95,106.58	79.48
Approved Total (Overridden) (S\$)		19,500.00		
(S\$)	119,654.83	19,500.00	100,154.83	83.70
+ GST 7.00/7.00% (S\$)	8,375.84	1,365.00	7,010.84	83.70
Nett Amount (S\$)	128,030.67	20,865.00	107,165.67	83.70
+ Loss of Use (11.0 x S\$50.00/day) (S\$)		550.00		
+ Car Rental (11.0 x S\$99.32/day) (S\$)		1,092.52		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		22,514.97		
Global Sum Settlement (S\$)		22,500.00		

INSPECTION

Date of Assignment:	16/10/2018	
Date Inspected:	16/10/2018	Inspected At: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111

5/14/2019

Adjuster Report

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Distorted	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
16	1		*BOT REFLECTOR LAMP RH	Cracked	493.35 FL	*493.35 FL
17	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
18	1		*BOT BADGE	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
20	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
21	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
22	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
23	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
24	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
25	1		*BOOT LOCK	Repair	202.67 FL	*- FL
26	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
27	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
28	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
29	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
30	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
31	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
32	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
33	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
34	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
35	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
36	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1		*TAILLAMP LH	Mtg Cracked	552.55 FL	*552.55 FL
39	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
40	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
41	1		*OUTER PANEL REAR (END PANEL) TRIM	Dented	404.56 FL	*404.56 FL
42	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
43	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
44	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
45	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
46	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
47	1		*WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	*- FL
48	1		*CHASSIS PANEL REAR LH L70Y	Repair	3,766.43 FL	*- FL
49	1		*KNUCKLE ARM REAR LH	Serviceable	736.67 FL	*- FL
50	1		*BRAKE DISC REAR L70Y	Serviceable	525.91 FL	*- FL
51	1		*WHEEL HUB NUT L70Y	Serviceable	51.11 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*WHEEL HUB CAP L70Y	Serviceable	57.82 FL	*- FL
53	1		*ABS SENSOR REAR LH	Serviceable	255.75 FL	*- FL
54	1		*REAR AXLE L70Y	Serviceable	4,167.03 FL	*- FL
55	1		*AXLE ARM LH	Serviceable	117.22 FL	*- FL
56	1		*LOWER ARM REAR LH	Serviceable	905.99 FL	*- FL
57	1		*ABSORBER REAR	Serviceable	389.75 FL	*- FL
58	1		*STABILIZER BAR REAR LH	Serviceable	604.65 FL	*- FL
59	1		*BRAKE CALIPER REAR LH	Serviceable	1,300.67 FL	*- FL
60	1		*WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	*- FL
61	1		*BUMPER COVER FRT	Bent	1,259.42 FL	*1,259.42 FL
62	1		*BUMPER SPOILER FRT	Distorted	181.75 FL	*181.75 FL
63	1		*BUMPER ABSORBER FRT	Cracked	394.68 FL	*394.68 FL
64	1		*BUMPER RETAINER FRT LH	Distorted	151.41 FL	*151.41 FL
65	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
66	1		*BUMPER RETAINER FRT RH	Distorted	150.77 FL	*150.77 FL
67	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
68	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
69	1		*BUMPER GRILLE LOWER FRT	Distorted	266.80 FL	*266.80 FL
70	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
71	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
72	1		*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
73	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
74	1		*RADIATOR GRILLE	Missing	1,707.78 FL	*1,707.78 FL
75	1		*RADIATOR GRILLE BADGE RENAULT	Missing	225.36 FL	*225.36 FL
76	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
77	1		*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
78	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
79	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
80	1		*HORN	Serviceable	314.17 FL	*- FL
81	1		*HORN BRACKET	Repair	40.45 FL	*- FL
82	1		*HEADLAMP LH	Dented / Cut	1,184.43 FL	*1,184.43 FL
83	1		*HEADLAMP RH	Cracked	1,184.43 FL	*1,184.43 FL
84	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
85	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
86	1		*BONNET	Bent	1,941.63 FL	*1,941.63 FL
87	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
88	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
89	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
90	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
91	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
92	1		*BONNET LOCK	Distorted	305.48 FL	*305.48 FL
93	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
94	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
95	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
96	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
97	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
98	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
99	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
100	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
101	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
102	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
103	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*- FL
104	1		*BASE BATTERY TRAY	Serviceable	363.40 FL	*- FL
105	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
106	1		*TURBO DUCT	Serviceable	1,027.80 FL	*- FL
107	1		*A/C HEATER VALVE	Serviceable	484.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*- FL
109	1		*SUBFRAME BRACKET OUTER LH	Serviceable	92.36 FL	*- FL
110	1		*ENGINE UNDERTRAY	Serviceable	564.98 FL	*- FL
111	1		*A/C CONDENSER	Punctured	2,020.37 FL	*2,020.37 FL
112	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*- FL
113	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*- FL
114	1		*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*- FL
115	1		*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*- FL
116	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
117	1		*A/C PIPE CONDENSER TO EXPANSION VALVE	Serviceable	658.72 FL	*- FL
118	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
119	1		*A/C PIPE	Serviceable	658.72 FL	*- FL
120	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
121	1		*AIR COOLER	Serviceable	792.60 FL	*- FL
122	1		*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
123	1		*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
124	1		*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
125	1		*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*- FL
126	1		*RADIATOR	Serviceable	1,202.20 FL	*- FL
127	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
128	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
129	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
130	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
131	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
132	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
133	1		*RADIATOR TANK	Serviceable	324.62 FL	*- FL
134	1		*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*- FL
135	1		*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*- FL
136	1		*RADIATOR TANK HOSE	Serviceable	61.18 FL	*- FL
137	1		*BOOT WEATHERSTRIP (50%)	Cut	290.75 FS	*161.53 FS
138	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
139	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
140	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
141	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
142	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
143	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
144	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
145	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
146	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
147	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
148	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
149	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
150	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
151	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
152	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
153	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
154	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
155	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
156	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
157	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
158	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
159	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
160	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
161	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Not Necessary	385.00 FS	*- FS
162	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
163	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
164	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
165	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
166	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
167	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
168	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
169	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
170	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
171	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
172	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
173	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
174	1		*LEFT REAR TYRE	Serviceable	330.00 FS	*- FS
175	1		*LEFT REAR TYRE RIM	Serviceable	380.00 FS	*- FS
176	2		*FRAME FULL SUPPORT PANEL STUD	Serviceable	30.00 FS	*- FS
177	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
178	1		*SET FRONT LICENCE PLATE WITH HOLDER	Bent	80.00 FS	*45.00 FS
179	1		*FRONT RIGHT FENDER ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*- FS
180	1		*REAR RIGHT FENDER ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*- FS
181	1		*REAR BOOT ADVERTISEMENT STICKER	Necessary	300.00 FS	*150.00 FS
182	1		*REAR LEFT FENDER ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*- FS
183	1		*REAR RIGHT FENDER ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*- FS
184	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	200.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	105,428.89	24,125.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	9,994.06	2,336.75
Total Parts (\$\$)	95,434.83	21,788.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	9,000.00	1,100.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	7,500.00	1,100.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	90.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
15	TOWING FEES.	New	120.00	50.00
16	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
17	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
18	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
19	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
20	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
21	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	40.00
22	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	New	380.00	0.00
23	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
24	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	New	440.00	0.00
25	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	New	440.00	0.00
26	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	New	480.00	0.00
27	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	380.00	0.00
28	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	100.00
29	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	50.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
30	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	50.00
31	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (S\$)			24,220.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >