

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U**AAD1810-175***Not Authorised*
L/Lng &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 588U

VF1ABL15AUC278427

RENAULT

LATITUDE

12.10.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>Na</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>Na</i> 113.47	—
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>CMT</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Na</i> 225.95	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bu</i> 225.95	—
13	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	—
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>CMT</i> 323.05	<i>508SL</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CMT</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>Na</i> 225.36	—
19	1 BOOT BADGE	\$	<i>Na</i> 225.36	—
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

- 30 1 DOOR PANEL REAR LH
- 31 1 FENDER PANEL INNER TRIM REAR LH
- 32 1 FENDER PANEL REAR LH
- 33 1 WHEELARCH REAR LH
- 34 1 FENDER PANEL INNER TRIM REAR RH
- 35 1 FENDER PANEL REAR RH
- 36 1 WHEELARCH REAR RH
- 37 1 TAILLAMP RH
- 38 1 TAILLAMP PANEL RH
- 39 1 TAILLAMP LH
- 40 1 TAILLAMP PANEL LH
- 41 1 OUTER PANEL REAR (End Panel)
- 42 1 OUTER PANEL REAR (End Panel)TRIM
- 43 1 SPARE WHEEL PANEL (Luggage Floor Panel)
- 44 1 SPARE WHEEL PANEL TRIM
- 45 1 EXHAUST REAR
- 46 1 EXHAUST CAP REAR
- 47 1 FUEL FLAP L70Y
- 48 1 WHEEL HOUSING PANEL REAR LH
- 49 1 CHASSIS PANEL REAR LH L70Y
- 50 1 KUCKLE ARM REAR LH
- 51 1 BRAKE DISC REAR L70Y
- 52 1 WHEEL HUB NUT L70Y
- 53 1 WHEEL HUB CAP L70Y
- 54 1 ABS SENSOR REAR LH
- 55 1 REAR AXLE L70Y
- 56 1 AXLE ARM LH
- 57 1 LOWER ARM REAR LH
- 58 1 ABSORBER REAR
- 59 1 STABILIZER BAR REAR LH
- 60 1 BRAKE CALIPER REAR LH
- 61 1 WHEEL HOUSING PANEL REAR LH
- 62 1 BUMPER COVER FRT
- 63 1 BUMPER SPOILER FRT
- 64 1 BUMPER ABSORBER FRT
- 65 1 BUMPER RETAINER FRT LH
- 66 1 BUMPER SUPPORT FRT
- 67 1 BUMPER RETAINER FRT RH

\$	<i>R</i>	2,844.66	
\$	<i>Su</i>	671.45	
\$	<i>R</i>	3,299.13	
\$	<i>Su</i>	543.47	
\$	<i>Su</i>	671.45	
\$	<i>R</i>	3,299.13	
\$	<i>Su</i>	543.47	
\$	<i>Su</i>	552.55	
\$	<i>R</i>	986.70	
\$	<i>mgm</i>	552.55	✓
\$	<i>R</i>	986.70	X
\$	<i>B</i>	1,471.77	✓
\$	<i>nd</i>	404.56	✓
\$	<i>R</i>	2,189.88	
\$	<i>Su</i>	612.21	
\$	<i>R</i>	7,489.05	
\$	<i>R</i>	230.49	
\$	<i>Su</i>	343.57	
\$	<i>R</i>	4,682.09	
\$	<i>R</i>	3,766.43	
\$	<i>Su</i>	736.67	
\$	<i>Su</i>	525.91	
\$	<i>Su</i>	51.11	
\$	<i>Su</i>	57.82	
\$	<i>Su</i>	255.75	
\$	<i>Su</i>	4,167.03	
\$	<i>Su</i>	117.22	
\$	<i>Su</i>	905.99	
\$	<i>Su</i>	389.75	
\$	<i>Su</i>	604.65	
\$	<i>Su</i>	1,300.67	
\$	<i>R</i>	4,682.09	
\$	<i>B</i>	1,259.42	✓
\$	<i>D.Y</i>	181.75	✓
\$	<i>CM</i>	394.68	✓
\$	<i>D.Y</i>	151.41	✓
\$	<i>Su</i>	123.88	X
\$	<i>D.Y</i>	150.77	✓

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

68	1 BUMPER SUPPORT FRT	\$	SL	123.88	X
69	1 BUMPER UNDERTRAY FRT	\$	SL	472.83	X
70	1 BUMPER GRILLE LOWER FRT	\$	Di	266.80	✓
71	1 BUMPER FOG LAMP GRILLE LH	\$	SL	207.21	X
72	1 BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	X
73	1 BUMPER BEAM FRT	\$	B	914.08	✓
74	1 TOW COVER FRT	\$	SL	28.61	X
75	1 RADIATOR GRILLE	\$	Miy	1,707.78	✓
76	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	Miy	225.36	✓
77	1 RADIATOR GRILLE FRAME	\$	CM	1,353.75	✓
78	1 FRAME FULL SUPPORT PANEL	\$	CM	615.90	✓
79	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79	X
80	1 FRONT BRACE PANEL	\$	R	177.22	X
81	1 HORN	\$	SL	314.17	X
82	1 HORN BRACKET	\$	R	40.45	X
83	1 HEADLAMP LH	\$	nd/gw	1,184.43	✓
84	1 HEADLAMP RH	\$	CM	1,184.43	✓
85	1 HEADLAMP PANEL FRT LH	\$	R	152.15	X
86	1 HEADLAMP PANEL FRT RH	\$	R	152.15	X
87	1 BONNET	\$	B	1,941.63	✓
88	1 BONNET INSULATOR	\$	SL	405.73	X
89	1 BONNET STRUT LH	\$	SL	88.61	X
90	1 BONNET STRUT RH	\$	SL	88.61	X
91	1 BONNET HINGE LH	\$	R	348.31	X
92	1 BONNET HINGE RH	\$	R	348.31	X
93	1 BONNET LOCK	\$	Di	305.48	✓
94	1 BONNET CABLE	\$	SL	119.19	} X
95	1 BONNET CABLE COVER	\$	SL	161.03	
96	1 BONNET SEAL OUTER	\$	SL	92.36	
97	1 BONNET SEAL INNER	\$	SL	157.28	
98	1 FENDER PANEL FRT LH	\$	R	783.83	
99	1 WHEELARCH FRT LH	\$	SL	278.84	
100	1 FENDER BRACKET LOWER LH	\$	SL	15.79	
101	1 FENDER INSULATOR LH	\$	SL	130.84	
102	1 FENDER INSULATOR RH	\$	SL	130.84	}
103	1 AIR CLEANER LOWER	\$	SL	271.26	
104	1 AIR CLEANER HOSE	\$	SL	76.14	}
105	1 BASE BATTERY TRAY	\$	SL	363.40	

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

106	1 AIR CLEANER BOX	\$	S _h	464.20	X
107	1 TURBO DUCT	\$	S _h	1,027.80	X
108	1 A/C HEATER VALVE	\$	S _h	484.50	X
109	1 SUBFRAME OUTER FRT	\$	S _h	2,652.45	X
110	1 SUBFRAME BRACKET OUTER LH	\$	S _h	92.36	X
111	1 ENGINE UNDERTRAY	\$	S _h	564.98	X
112	1 A/C CONDENSER	\$	P _h	2,020.37	✓
113	1 A/C CONDENSER GARNISH LH UPPER	\$	P _h	39.67	X
114	1 A/C CONDENSER GARNISH RH UPPER	\$	S _h	39.67	
115	1 A/C CONDENSER GARNISH LH	\$	S _h	58.81	
116	1 A/C CONDENSER GARNISH RH	\$	S _h	59.60	
117	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	S _h	208.39	
118	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S _h	658.72	
119	1 A/C PIPE COMPRESSOR	\$	S _h	334.29	
120	1 A/C PIPE	\$	S _h	658.72	
121	1 A/C COMRPRESSOR	\$	S _h	2,684.61	
122	1 AIR COOLER	\$	S _h	792.60	
123	1 AIR INTERCOOLER HOSE (LONG)	\$	S _h	1,014.13	
124	1 AIR INTERCOOLER HOSE (Short)	\$	S _h	375.14	
125	1 TRANSMISSION COOLER	\$	S _h	1,219.30	
126	1 TRANSMISSION COOLER PAD	\$	S _h	17.96	
127	1 RADIATOR	\$	S _h	1,202.20	
128	2 RADIATOR STUD UPPER	\$	S _h	14.41	X
129	2 RADIATOR BUSH UPPER	\$	S _h	50.12	
130	2 RADIATOR MTG LOWER	\$	S _h	55.85	
131	1 RADAITOR FAN COWLING	\$	S _h	820.54	
132	1 RADIATOR FAN MOTOR LH	\$	S _h	967.36	
133	1 RADIATOR FAN MOTOR RH	\$	S _h	1,479.46	
134	1 RADIATOR TANK	\$	S _h	324.62	
135	1 RADIATOR HOSE UPPER	\$	S _h	240.56	
136	1 RADIATOR HOSE LOWER	\$	S _h	491.18	
137	1 RADIATOR TANK HOSE	\$	S _h	61.18	

TOTAL	\$	100,263.67
10%	\$	10,026.37
	\$	90,237.31

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U**Special Nett**

1 1SET PARKING AID	\$	Sm	700.00	X
2 1SET REAR BUMPER CLIP	\$	nn	66.00	—
3 1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	—
10 1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11 1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	nn	30.00	—
13 1 BOOT STICKER "6555-3333"	\$	nn	30.00	—
14 1 BOOT INNER TRIM CLIP	\$	nn	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19 1 TAILLAMP CLIP RH	\$	nn	5.00	X
20 1 TAILLAMP CLIP LH	\$	nn	5.00	—
21 2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
22 1 WINDSCREEN MOULDING	\$	nn	100.00	X
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	X
25 1 SPARE TYRE	\$	Sm	330.00	X
26 1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	X
27 1SET BUMPER CLIP FRT	\$	nn	66.00	—
28 1 BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	} X
29 1 BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
30 1 BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
31 1 BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
32 1 TOW COVER FRT	\$	Sm	14.50	
33 1SET RADIATOR GRILLE SCREW	\$	nn	16.00	
34 1SET BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
35 1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
36 2 FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

37	1 LEFT REAR TYRE	\$	Sn	330.00	X
38	1 LEFT REAR TYRE RIM	\$	Sn	380.00	X
39	2 FRAME FULL SUPPORT PANEL STUD	\$	Sn	30.00	X
40	1 Windscreen moulding	\$	nn	100.00	X
41	1SET Front licence plate with holder	\$	B	80.00	45sn
42	1 FRONT RIGHT FENDER ADVERTISEMENT STICKER	\$	nn	300.00	X
43	1 REAR RIGHT FENDER ADVERTISEMENT STICKER	\$	nn	300.00	X
44	1 REAR BOOT ADVERTISEMENT STICKER	\$	nn	300.00	150sn
45	1 REAR LEFT FENDER ADVERTISEMENT STICKER	\$	nn	300.00	X
46	1 REAR RIGHT FENDER ADVERTISEMENT STICKER	\$	nn	300.00	X
46	1 REAR BUMPER ADVERTISEMENT STICKER	\$	nn	200.00	100sn

TOTAL \$ 5,197.52**TOTAL PARTS \$ 95,434.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00	1100d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	1100d
To Rust-Proofing Of The Affected Areas.	\$	170.00	9d
To reinstall rear bumper parking sensor.	\$	170.00	6d
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	6d
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	6d

Trans-cab Auto Services Pte Ltd**AAD1810-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
Towing Fees.	\$	120.00	<i>501</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	X
To rust-proofing of the affected areas.	\$	<i>Repco</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>501</i>

Trans-cab Auto Services Pte Ltd

AAD1810-175

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 588U

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To lift-up engine with gear box and refit.

\$ *nn* 440.00 X

To remove and renew power steering pump, oil cooler pipe and final checking and testing.

\$ *nn* 440.00 X

To remove and refit air bag system and reset.

\$ *nn* 480.00 X

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.

\$ *nn* 380.00 X

To vacuum, replace, refix and recharge air condenser

\$ 380.00 *100%*

To replace, refix and top up coolant for radiator

\$ 170.00 *50%*

To vacuum, replace, refix and recharge Air Intercooler

\$ 170.00 *50%*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X**TOTAL \$ 24,220.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Over All Total \$ 119,654.83**(LUMP SUM)****Repair Days****30 DAYS***8 days*