

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized
L1 Sm & ?
Pursing After Paint
Fday

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **15.10.2018**

Accident Date : 13.10.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Altis" Reg. No. SJL5567S Claiming Against Your Insured Reg. No. SMA1225C			
1pc	Boot	71.80	B 792.00 ✓
2pcs	Boot Hinges		R 143.60 X
1pc	Boot Center Emblem		M 57.40 ✓
1pc	Boot Badge "1.6"		M 42.20 X
1pc	Boot Badge "Corolla"		M 46.50 X
1pc	Boot Badge "Altis"		M 48.20 X
1pc	Boot Outer Moulding		svc 239.00 ?
1pc	Boot Lamp LH		dt 185.00 ✓
1pc	Boot Lock		dt 106.00 ✓
1pc	Boot Lock Catch		dt 32.00 ✓
2pcs	Boot Stoppers	10.30	Sm 20.60 X
1pc	Boot Trim Board	3.80	CM 282.00 ✓
10pcs	Boot Trim Board Clips		M 38.00 ✓
1pc	Boot Weatherstrip	3.80	G 191.00 50% ✓
1pc	Rear Bumper		B 495.00 ✓
10pcs	Rear Bumper Clips	3.80	M 38.00 ✓
2pcs	Rear Bumper Brackets	87.50	CM 175.00 ✓
1pc	Rear Bumper Sponge	79.00	CM 129.00 ✓
1pc	Rear Bumper Reinforcement		R 315.00 ?
2pcs	Rear Bumper Top Retainers	79.00	M 158.00 ✓
1pc	Rear Bumper Reflector LH	73.50	Sm 37.00 X
2pcs	Rear Bumper Corner Holders		M 147.00 ✓
2pcs	Taillamps Assy	386.00	CM 772.00 ✓
1pc	End Panel	345.00	B 607.00 ✓
1pc	End Panel Garnish		M 203.00 ✓
1pc	Spare Tyre Panel	345.00	R 763.00 X
1pc	Spare Tyre Top Board		dt 362.00 ✓
2pcs	Rear Fender Trim Boards	345.00	Sm 690.00 X
Less 25%			7,114.50
			1,778.63
			5,335.88
1pc	Rear Bumper Reverse Sensor	NN	R 280.00 SN 200% ✓
1pc	Rear Number Plate		R 45.00 SN ✓
1pc	Roadside Triangle		CM 75.00 SN ✓
1pc	Portable Vaccum Cleaner		CM 105.00 SN X
To Dismantle / Refit Boot Fittings / Ancillary Accessories			80.00 50%
C/F			5,920.88

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **15.10.2018**

Accident Date : 13.10.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Altis" Reg. No. SJL5567S Claiming Against Your Insured Reg. No. SMA1225C		
		B/F	5,920.88
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		120.00 <i>701</i>
	To Supply End Panel Joint Sealant		60.00 <i>301</i>
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		80.00 <i>601</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>601</i>
	To Provide Transportation (Towing)		(<i>Bill</i>) 70.00 <i>7 50</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel, Rear LH Fender, Floor Panel, Cnt, Weld End Panel and Parts Replacement		1,400.00 <i>9001</i>
	To Respray Affected Areas Boot, Bumper, End Panel, Spare Tyre Panel, Taillamp Panel *2, Fenders		1,400.00 <i>10001</i>
	Total :		9,150.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: