

Kp

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-12, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1426 (24Hrs) Fax: 6484 0465
Business Reg. No. 221830/00C GST Reg. No. MX-0486007-A0

Not Authorized
L1 Sm @ 1500/-
Running After Paint
Today

Y0. AIG Asia Pacific Insurance Pte Ltd

Policy No. Third Party

Date 15.10.2018

Accident Date : 13.10.2018

Specialises in: Bodywork, Welding,
Painting, Glass, Tyre, Spare Parts

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	名称 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Altis" Reg. No. SJL5567S Claiming Against Your Insured Reg. No. SMA1225C			
1pc	Boot	71.80	B1 792.00 ✓
1pc	Door Handle		R 143.60 X
1pc	Door Corner Emblem		M 57.40 ✓
1pc	Body Panel "1.5"		R 42.20 X
1pc	Body Panel "Corolla"		M 46.50 X
1pc	Body Panel "Altis"		R 48.20 X
1pc	Front Bumper Moulding		M 239.00 X
1pc	Front Lamp LH		R 185.00 ✓
1pc	Door Lock		R 106.00 ✓
1pc	Door Lock Catch		R 32.00 ✓
3pcs	Door Straps	10.30	R 20.60 X
1pc	Door Trim Board		CM 282.00 ✓
12pcs	Door Trim Board Clips	3.80	R 38.00 ✓
1pc	Door Weatherstrip		R 191.00 50%
1pc	Front Bumper	3.80	B1 495.00 ✓
10pcs	Front Bumper Clips		R 38.00 ✓
2pcs	Front Bumper Brackets	87.50	CM 175.00 ✓
1pc	Front Bumper Sponge		R 129.00 ✓
1pc	Front Bumper Reinforcement	79.00	R 315.00 X
2pcs	Front Bumper Top Retainers		MSD 158.00 ✓
1pc	Front Bumper Reflector LH	73.50	R 37.00 X
2pcs	Front Bumper Corner Holders		MSD 147.00 ✓
2pcs	Side Mirror Assy	386.00	CM 772.00 ✓
1pc	Side Panel		B1 607.00 ✓
1pc	Side Panel Garnish	203.00	MSD 763.00 X
1pc	Side Tyre Panel		R 362.00 ✓
1pc	Spare Tyre Top Board	345.00	R 690.00 X
2pcs	Rear Bumper Trim Boards		7,114.50
Less 25%			1,778.63
			5,335.88
1pc	Front Bumper Reverse Sensor	280.00	R 280.00 SN
1pc	Rear Bumper Plate		R 45.00 SN ✓
1pc	Rockers Triangle	75.00	CM 75.00 SN ✓
1pc	Front Bumper Vacuum Cleaner		R 105.00 SN X
For Bolts/Washers / Refit Bolt Fittings / Ancillary Accessories			80.00 50%
		C/F	5,920.88

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 2826 (24Hrs) Fax: 6484 0465
Business Lic No: Z21880/00C GST Reg No: MX-0486007-A0

To: AMK Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 15.10.2018

Accident Date: 13.10.2018

Subsidiary: LK Auto Consulting
Particulars: Motor Vehicle Claim

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	项 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Altis" Reg. No. SJL5567S Claiming Against Your Insured Reg. No. SMA1225C		
		B/F	5,920.88
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rearview Etc.		120.00 <i>701</i>
	To Supply End Panel Joint Sealant		60.00 <i>301</i>
	To Dismantle & Transfer Rear Spare Tyre Panel Inner Trims Boards, Garnish and Rear Fenders Inner Trims Boards / Garnish to Accurate Repair		80.00 <i>601</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray Affected & Repair Panel		100.00 <i>601</i>
	To Provide Transportation (Towing)		(B.II) 70.00 <i>301</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Left Panel, Spare Tyre Panel, Rear LH Fender, Floor Panel, Cnt, Weld End Panel and Parts Replacement		1,400.00 <i>9001</i>
	To Respray Affected Areas Rear Bumper, End Panel, Spare Tyre Panel, Taillamp Panel *2, Fenders		1,400.00 <i>10001</i>
	Total :		9,150.88

LK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: