

CASE OWNER:

4. UPC 180 18886, P1ha3n2

TEK:

LAC:

Surveyor:

PAM

DOB:

ASSIGNMENT

10/10/18

Date / Time:

16-10-18

Registered in Meriton:

Pre-assign / CCU / FTE

GBE 208K



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

13/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final? Yes / No

SPW 44445



INSRS:

WSP:

Tel:

Liability:

RMKS:

N157



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

14-1-18

FOR MANDATE

10-4-19

TP VIDEO SENT TO LONPAC MEM.

- MANDATE APPROVED
- TP ACCEPTED OFFER.
- ALL TO DO IN ORDER.
- TO CLOSE.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

L6

\$2,650.00

4

days

Reduction:

55

%

Confirm by:

Email

Call

FINAL SETTLEMENT

Date/Time:

10/04/19

Confirm with

GMBRINA

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

33

If NO or B 28, Ass. Lia:

Repair Cost: (w/gst)

\$2,835.50

Loss of Rental (LOR) (w/gst)

\$642.00

6

days

\$100.00

Loss of Use (LOU):

\$

-

(\$

x

days)

Loss of Income (LOI):

\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$

7.45

Medical:

\$

-

Disbursement:

\$

-

Legal Cost

\$

-

(e.g. Tow/Independent)

Total:

\$

3,484.95

Global Sum \$:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$480.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

3,484.95

Name 1:

N-BI AUTOMOTIVE PTB LTD

Payee 2: (Strike if N.A.)

\$

-

Name 2:

Payee 3: (Strike if N.A.)

\$

-

Name 3:

18/7/19

Surveyor

REF:

IPC

846c

ASSIGNMENT

From:

Date:

16/10/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKW 9444S

at Workshop m/s

N-51 Automotive

of

2 kaki Blk Ave 2 # 01-17 118

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1 up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKW 9444S

Yr Regn:

2015 / NOV

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA MRS 1.6 c.c. 1598

Colour:

BLACK

A/C:

Insured / Std / NI / NA

Sp. Reading

184880

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRS 3REH104537084

Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

COMFORT MAX

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/10/18

D.O.I.

16/10/18

Survey held at

N-51

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S PR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LIS \$2,650.00

CRD: \$3,357.65 (55%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ATTN: YONG
67410510.

kindly confirm amount and
email to me at rasul@1kkauto.com

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 91426464

ESTIMATE

Repair Code : CLM14848

Date in : 15/10/2018

Vehicle Num. : SKW9444S

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104537084/1ZRX525656

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>scr</i>	1	485.00	485.00
FRONT BUMPER RH FOGLAMP <i>CRA</i>	1	325.00	325.00
FRONT BUMPER RH FOGLAMP COVER <i>scr</i>	1	91.90	91.90
FRONT BUMPER SIDE RETAINER L/R <i>ne / RH / LH X 1</i>	<i>2</i>	55.20	110.40
FRONT RH FENDER 'DUAL VVT-I' EMBLEM <i>ne</i>	1	54.00	54.00
FRONT RH FENDER INNER SHIELD <i>ent</i>	1	200.90	200.90
FRONT RH HEADLAMP <i>CRA</i>	1	850.00	850.00
FRONT RH KNUCKLE ARM <i>BT</i>	1	521.20	521.20
FRONT RH KNUCKLE ARM BEARING <i>BT</i>	1	95.70	95.70
FRONT RH LINKAGE <i>X</i>	1	196.80	196.80
FRONT RH LOWER ARM <i>X</i>	1	608.10	608.10
FRONT RH LOWER BALL JOINT <i>X</i>	1	223.10	223.10
FRONT RH SHOCK ABSORBER <i>X</i>	1	398.10	398.10
FRONT RH STEERING TIE ROD END <i>X</i>	1	170.00	170.00
Subtotal before discount			4,330.20
Percentage discount 25%			1,082.55
Sub-total 1			3,247.65
FRONT BUMPER CLIPS - SET <i>ne</i>	1	50.00	50.00



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 91426464

Car
Hp 90010068

4 days

4/3

16/10/18 @ 1540

Resurvey after repair

2009.17

450.00

850.00

3349.17

208

2679.33

42-2,650

4 days

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

ESTIMATE

Repair Code : CLM14848

Date in : 15/10/2018

Vehicle Num. : SKW9444S

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104537084/1ZRX525656

FRONT RH FENDER INNER SHIELD CLIPS - SET	<i>X 111</i>	1	50.00	50.00
FRONT RH SPORT RIM	<i>sun</i>	1	800.00	<i>400</i> 800.00
FRONT RH TYRE	<i>X 111</i>	1	280.00	280.00
Subtotal before discount			<i>450</i>	1,180.00
Percentage discount 0%				0.00
Sub-total 2				1,180.00
Parts-total				4,427.65

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

1,580.00

Parts & Labour Total

6,007.65

Take note: ALL parts that was not given are not consistent to accident

890

111 X 50.00

100 200.00

60 100.00

400 200.00

300 480.00

30 50.00

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 16 October 2018 10:22 AM
To: Chin Hui Xin
Cc: MT_Claim_SG; assignments; Catherine Chong (LKK Auto)
Subject: RE: Our Ref: 18/18/18/VP05/021029 RE: SKW9444S & GBE2108K - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
Attachments: image002.jpg; 16102018095918.pdf

Without Prejudice

Dear Melody

Thank you for confirming the appointment of SJE.

Dear Catherine/Nivitha

fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Chin Hui Xin [mailto:huixin@n51.com.sg]
Sent: Tuesday, 16 October, 2018 10:00 AM
To: ONG LI LI
Cc: MT_Claim_SG; assignments; Catherine Chong (LKK Auto)
Subject: Re: Our Ref: TBA RE: SKW9444S & GBE2108K - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,


We appoint your surveyor Mr Mohammed Rasul.

Please see attached.

Thank you

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg

11:06am @ 16/10/18
vehicle in
person @ Melody
sup @ Rasul.
Repairer said estimate
provided.



On Tue, Oct 16, 2018 at 9:06 AM ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Monday, 15 October, 2018 5:34 PM

To: MT_Claim_SG

Subject: SKW9444S & GBE2108K - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **SKW 9444 S**
Your ref: **GBE 2108 K**

16 October 2018

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702
Attn: Motor Claims Department

BY EMAIL llong@lonpac.com ONLY

Dear Sir/Madam,

NAME OF CLAIMANT : TWINCAR LEASING PTE LTD
VEHICLE NUMBER : SKW 9444 S
YOUR INSURED VEHICLE NUMBER : GBE 2108 K
ACCIDENT ON 13 Oct 2018 ALONG BLK 115 BEDOK RESERVOIR RD OPEN CARPARK
AT ABOUT 18:10 HOURS

We refer to your email dated 16 Oct 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **Mohammed Rasul** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18

Contact Person:

Singapore 417921
6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



N-51 AUTOMOTIVE PTE LTD

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18018886/Rha3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 19-07-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 2108K	Veh. Inspected	SKW 9444S
Policy No.	Z/18/VC05/00768-001	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021029	Excess (\$)	0.00
Assign From	GERALD	Assign Date	16/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104537084	Colour	BLACK
Odometer	184880	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	COMFORT MAX	6 mm
L/H Front Tyre	205/55 R16	COMFORT MAX	6 mm
R/H Rear Tyre	205/55 R16	COMFORT MAX	6 mm
L/H Rear Tyre	205/55 R16	COMFORT MAX	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/10/2018	Inspection Date	16/10/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 9444S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	SCRATCHED	485.00	485.00
1	FRONT BUMPER RH FOGLAMP	CRACKED	325.00	325.00
1	FRONT BUMPER RH FOGLAMP COVER	SCRATCHED	91.90	91.90
2	FRONT BUMPER SIDE RETAINER L/R @\$55.20	O/S NECESSARY / N/S NOT NECESSARY	110.40	55.20
1	FRONT RH FENDER "DUAL VVT-I" EMBLEM	NECESSARY	54.00	54.00
1	FRONT RH FENDER INNER SHIELD	CUT	200.90	200.90
1	FRONT RH HEADLAMP	CRACKED	850.00	850.00
1	FRONT RH KNUCKLE ARM	BENT	521.20	521.20
1	FRONT RH KNUCKLE ARM BEARING	BENT	95.70	95.70
1	FRONT RH LINKAGE	SERVICEABLE	196.80	-
1	FRONT RH LOWER ARM	SERVICEABLE	608.10	-
1	FRONT RH LOWER BALL JOINT	SERVICEABLE	223.10	-
1	FRONT RH SHOCK ABSORBER	SERVICEABLE	398.10	-
1	FRONT RH STEERING TIE ROD END	SERVICEABLE	170.00	-
	LESS 25% DISCOUNT		-1,082.55	-669.73
			3,247.65	2,009.17
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT RH SPORT RIM (SN)	SCRATCHED	800.00	400.00
1	FRONT RH TYRE (SN)	NOT NECESSARY	280.00	-
			1,180.00	450.00
LABOUR				
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING (TO FR).	NOT NECESSARY	50.00	-
	TO REMOVE,CHANGE FRONT SUSPENSION PARTS,ABSORBER,LOWER ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB,DRIVE SHAFT,ANTI-ROLL BAR,TOP-ARM AND STEERING RACK AND PINION.		200.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		700.00	400.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		480.00	300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		50.00	30.00
			1,580.00	890.00
GRAND TOTAL			6,007.65	3,349.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CC4/LPC18018886/Rha3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.