

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719

Workshop: 24, Sungei Kadut Street 4 Singapore 729050

Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712

Business Reg. No: 36463500B

M/s: **AXA INSURANCE SINGAPORE PTE LTD**
8 SHENTON WAY #27-10
Singapore 068811

Motor Claim Dept

Vehicle number : EU 8848 Z
Make/Model : SUBARU FORESTER 2.0 X
Date of accident : 14.10.2018
Claim Type : TP Claim

Accident involving EU 8848 Z & SHD 5002 X along ORCHARD ROAD on 14.10.2018.

Re: Estimate

1.	1 pc	Front bonnet	\$	776.00	PD
2.	1 pc	Front headlamp LH	\$	1,007.00	CRK
3.	1 pc	Front headlamp lower bracket	\$	44.00	?
4.	1 pc	Front mudguard LH	\$	320.00	DD
5.	1 pc	Front bumper	\$	620.00	CRK
6.	1 pc	Front bumper reinforcement	\$	288.00	?
7.	1 pc	Front bumper fog lamp LH	\$	323.00	?
8.	14 pcs	Front bumper clips	\$	28.00	NEC
9.	1 pc	Front bumper corner bracket LH	\$	15.00	?
10.	1 pc	Front mudguard inner shield LH	\$	104.00	?
11.	1 pc	Front water tank LH	\$	93.00	DD
12.	1 pc	Front grille	\$	600.00	?
13.	1 pc	Front bonnet lock	\$	60.00	?
			\$	4,278.00	
To towing services			\$	80.00	XNN
To wiring services			\$	80.00	30
To alignment			\$	120.00	60
To Replace & Repair Labour Charge			\$	880.00	550
To Putty & Spray Painting			\$	1,000.00	800
Total			\$	6,438.00	

Yours Faithfully,

李光華 摩哆燒焊

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

Date: 17.10.2018
LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: