

HITACHI
Inspire the Next

TP INSURER: India International Insurance Pte Ltd (HQ)
LIANG ZHENGYAO

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/10/2018
Vehicle Reg. No.:	SLW8267G	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIANG ZHENGYAO	Driver (Insured):	LIANG ZHENGYAO

Make/Model:	HONDA SHUTTLE, 1.5 G (A)	Vehicle Reg. Date:	02/03/2018
Vehicle Colour:	BLUE		
Engine No:	L15B5461149	Chassis No:	GK8120097
Odometer:	10000 KM		Tanpin 9749

Paint Type:
List Item Discount: 20.00 %
Total Loss? **NO**
Est. Duration of Repair (day) 7

Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

Chassis No: GK81200976

GR01200976
Taylor 97495749
-wp
18/10/15 @ 445
Resurvey before paint
sure@1/11/antw-wm
days

COST OF CLAIMS

Parts	2,403.20
Miscellaneous Items	10.00
Labour	2,340.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$)	4,753.20
+ GST 7.00% (\$\$)	332.72
Nett Amount (\$\$)	5,085.92

This claim is handled by: NG JIONG HOW

- the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification allowed
 - Supplementary part(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 16 Oct 2018)	
Parts:	N/A	HONDA SHUTTLE 1.5 G (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Hitachi Capital Asia Pacific Pte. Ltd/SLW8267G/16/10/2018 11:13	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear Bumper	20.00	0.00	*1,209.00 FL <i>de</i>
2	10		*Rear Bumper Clips	20.00	0.00	*55.00 FL <i>de</i>
3	2		*Rear Bumper Outer Bracket LH/RH	20.00	0.00	*70.00 FL <i>de</i>
4	1		*Rear Reverse Sensor	0	0.00	*200.00 FS <i>nu</i>
5	1		*Rear Bumper Reflector Cover LH	20.00	0.00	*45.00 FL <i>ad</i>
6	1		*Rear Bumper Reflector LH	20.00	0.00	*60.00 FL ?
7	2		*Rear Bumper Reinforcement Sponge	20.00	0.00	*170.00 FL ?
8	1		*Tailgate	20.00	0.00	*945.00 FL <i>bt</i>
9	2		*Tailgate Hinge LH/RH	20.00	0.00	*110.00 FL <i>Ry</i>
10	1		*Honda Logo	20.00	0.00	*35.00 FL <i>nu</i>
11	1		*Shuttle Logo	20.00	0.00	*55.00 FL <i>nu</i>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,954.00
- List Item Discount on L Items (\$\$)	550.80
Total Parts (\$\$)	2,403.20

Hitachi Capital Asia Pacific Pte. Ltd/SLW8267G/16/10/2018 11:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	750.00 500
2	Putty, blend and paint affected area	New	750.00 500
3	Remove & reinstall 2 pieces bumper sensors	New	120.00 30
4	Remove & reinstall rear reverse camera	New	120.00 30
5	Remove & reinstall tailgate windscreen glass	New	180.00 120
6	Transfer Tailgate lock & mechanism to new tailgate	New	150.00 60
7	Conduct water seepage test	New	120.00 20
8	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	150.00 40
Gross Labour Cost (S\$)			2,340.00

Hitachi Capital Asia Pacific Pte. Ltd/SLW8267G/16/10/2018 11:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591