



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LAU KUM SENG	Document No.	: SQT18004385	Page	1
	115 BUKIT MERAH CENTRAL	Date	: 13. Oct 2018		
	#17-3767	Customer No.	: ****8936H		
	SINGAPORE 150115	Svc Advisor	: NG SIN HAI		
Registration No	: SFY7731A	Engine No	: K24W72040272		
Chassis No	: JHMRC1890HC200813	Date Time	: 13. Oct 2018 1:23:26 PM		
Model	: ODYSSEY 2.4 EXV-S 17YM	Surveyor Name	:		
Owner's Name	: LAU KUM SENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 12/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:LAU KUM SENG						
	OWNER INSURER:AVIVA						
	ACC DATE:12/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:SHA2611Z						
04711-T6A-900ZZ	FACE,FR.BUMPER <i>repair</i>	1	686.20	25	514.65	36.03	550.68
71117-T6A-921ZA	SPOILER ASSYL.FR.SIDE <i>repair</i>	1	92.50	25	69.37	4.86	74.23
71198-T6A-003	SPACERL.FR.BUMPER SIDE <i>new</i>	1	11.60	25	8.70	0.61	9.31
91505-TM8-003	CLIPBUMPER <i>new</i>	14	2.00	25	21.00	1.47	22.47
60260-T6A-300ZZ	FENDER COMPL.FR. <i>repair</i>	1	537.80	25	403.35	28.23	431.58
73370-T6A-315	GLASS ASSYL.FR.CORNER <i>X</i>	1	361.40	25	271.05	18.97	290.02
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>X</i>	1	60.00		60.00	4.20	64.20
76251-T6A-J01ZA	CAPL.SKULL <i>X</i>	1	64.70	25	48.52	3.40	51.92
76252-T6A-J01ZA	COVER RH-LBASE <i>X</i>	1	27.90	25	20.92	1.46	22.38
76258-T6A-Q03	SET,RH.L.MIRROR ASSY <i>new repair ?</i>	1	1275.90	25	956.92	66.98	1023.90
67050-T6A-000ZZ	PANEL COMPL.FR.DOOR <i>repair</i>	1	877.70	25	658.27	46.08	704.35
67550-T6A-J00ZZ	PANEL COMPL.SLIDE DOOR <i>repair</i>	1	980.90	25	735.67	51.50	787.17
04646-T6A-J21ZZ	PANEL SET,L.RR.OUTER <i>repair</i>	1	974.50	25	730.87	51.16	782.03
04715-T6A-900ZZ	FACERR.BUMPER <i>repair</i>	1	557.20	25	417.90	29.25	447.15
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>X</i>	1	18.70	25	14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER <i>X</i>	7	2.00	25	10.50	0.74	11.24
42700-T6A-T81	WHEEL,DISK ALUMINIUM 17X7J <i>new</i>	2	845.30	25	1267.95	88.76	1356.71
44300-T6A-J51	BEARING ASSYFR.HUB <i>?</i>	1	135.50	25	101.62	7.11	108.73
44600-T0B-A00	HUB ASSYFR. <i>?</i>	1	183.50	25	137.62	9.63	147.25
42200-T6A-J51	BEARING ASSYRR.HUB UNIT <i>?</i>	1	314.00	25	235.50	16.49	251.99
Sum Item					<u>6684.40</u>	<u>467.91</u>	<u>7,152.31</u>



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LAU KUM SENG	Document No.	: SQT18004385	Page	2
	115 BUKIT MERAH CENTRAL	Date	: 13. Oct 2018		
	#17-3767	Customer No.	: ****8936H		
	SINGAPORE 150115	Svc Advisor	: NG SIN HAI		
Registration No	: SFY7731A	Engine No	: K24W72040272		
Chassis No	: JHMRC1890HC200813	Date Time	: 13. Oct 2018 1:23:26 PM		
Model	: ODYSSEY 2.4 EXV-S 17YM	Surveyor Name	:		
Owner's Name	: LAU KUM SENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 12/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BOMISC1	RESET ALL SMART ENTRY FOR DOORS	1	380.00		380.00	26.60	406.60
BOMISC1	RESET, CALIBRATE AND ALIGN ALL CAMERA	1	560.00		560.00	39.20	599.20
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)1	1	1120.00	840?	1120.00	78.40	1198.40
BMU21R	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS.(N)1	1	1120.00	840?	1120.00	78.40	1198.40
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00	2700	4000.00	280.00	4280.00
BKB01R	REMOVE & RENEW FR BUMPER AND ALL DAMAGED PARTS	1	4000.00	2800	4000.00	280.00	4280.00
BG41D	REMOVE & INSTALL FR. L QTR GLASS.(N)	1	280.00	X	280.00	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	X	80.00	5.60	85.60
Sum Labor					11820.00	827.40	12,647.40
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By RASUL - Hp 90010068

Date & Time 23/10/18 @ 0900

Excess 8 days

Status Resurvey after repair

Signature [Signature]

Total Amount 18,684.40 1,307.91 19,992.31

Total (Inclusive of GST) 19,992.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/10/2018 1:42:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)