

ESTIMATE

INDIAN INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04-05 IOB Building
Singapore 049711

Attn: Claim Department

Date: 16.10.2018

OUR REF CP/041018/GBB9243Y/15
VEHICLE NO GBB9243Y
MODEL TOYOTA

PARTS

1 PC Rear Bumper
1 PC Rear End Panel
1 PC Rear Exhaust Pipe
1 PC Rear Boot
1 PC Rear Boot Lock
1 PC Rear Boot Emblem (Logo)
1 PC Rear Right Light Assy
1 PC Rear Right Light Lower Panel
1 PC Rear End Panel Top Garnish

B \$399.13 ✓
B \$330.82 ✓
B \$997.41 ✓
B \$1,789.26 ✓
B \$267.09 ✓
B \$75.16 ✓
CM \$274.88 ✓
B \$89.88 ✓
B \$148.40 X
\$4,372.03
Less 25% \$1,093.00
\$3,279.03

1 PC Rear Bumper Lower Spoiler
1 PC Body Lettering
1 SET Reverse Sensor
Tuff Kote

B \$600.00 SN X
B \$850.00 SN 4000N
Sh \$300.00 SN 2000N
\$80.00 601

LABOUR

Being labour to dismantle & renew the above mentioned parts
Respray Painting

\$1,500.00 9001
\$1,500.00 8001

Total \$8,109.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: